

(a)
(a) (b) (c–e) Symbol in panel
Flood inundation
Flood source
x-axis
Distance from source (km)
Town
Building in flood inundation
Road in flood inundation
Hydropower structure damaged
Bridge washed away (65)
Bridge damaged (13)
Bridge intact (28)
Bridge, no information (12)
Zoomed areas (c)–(e)
District boundary
160 km
Chumlingtar
GORKHA
140 km
Malekhu
120 km
DHADING
100 km
Galchi
NUWAKOT
80 km
Bidur
(e)
60 km
Betrawati
(d)
40 km
Syafrubesi
RASUWA
(c)
20 km
Rasuwagadhi
NEPAL
CHINA
Flood source
0 5 10 km
N
CHINA
NEPAL
INDIA
Hillshade: Copernicus DEM GLO-30.
(b)
(c)
(d)
(e)
source
Rasuwagadhi 08:44
Syafrubesi 08:54
Betrawati 09:27
Galchi 10:28
Chumlingtar 12:30
Flood arrival times in Nepal Time (UTC+05:45)
Elevation (m)
4000
2000
0
Flooded buildings
1,129
1000
500
0
6,012 buildings
Road length (km)
20
10
0
Highway & main road
Local road & track
Within 100 m of inundation
108 km flooded (31 km main) +185 km ≤ 100 m
Hydropower
13 structures
Bridges
78 washed away or damaged
0 20 40 60 80 100 120 140 160
Distance from source along the flow path (km) | bars: totals per 5 km
(c) Rasuwagadhi–Timure (18–26 km)
20 km
Rasuwagadhi
Rasuwagadhi
Timure
25 km
0 1 2 km
Vantor WorldView-3, 27 Aug 2026
(d) Upper Trishuli hydropower (51–64 km)
Upper Trishuli-1
Mailun Khola
Upper Trishuli-3A
55 km
Ghale Gaun
Upper Trishuli-3A
60 km
Trishuli 3B Hub Substation
0 1 2 km
Upper Trishuli-3B DAM
Sentinel-2, 21 Sep 2026
(e) Trishuli–Bidur (67–80 km)
Trishuli-DAM
70 km
Trishuli Bazaar
75 km
Trishuli-Powerhouse
Bidur
Devighat
0 1 2 km
Vantor WorldView-2, 8 Sep 2026