
Manda Hararo 2026 — dike-induced stress on the east-fault receivers

map stress at 1.0 km depth · trace-supported east-fault receivers, 65° main case · source: dike opening only · identical GSLC/GUNW receivers



\+ = unclamping / normal-slip CFS
map receivers: strike 152.6°, dip 65° toward the dike, normal rake, friction 0.4, depth 1.0 km
dike-plane strip (±0.4 km) masked
receiver-plane depth exaggerated ×4.2

All panels resolve stress on the trace-supported east-fault orientation with the parameters listed above.
The stress source is the saved distributed dike opening only; the fitted fault slip is excluded.