DI8SO-01

DTC	Jam Protection Limit Switch Circuit on Passenger Door
	i doseligei booi

## **CIRCUIT DESCRIPTION**

This DTC is output when failure of the jam protection limit switch circuit is detected.

The jam protection limit switch is built in the power window motor.


This switch is OFF when the window stays between the fully closed position and 4 mm under the full-closed position, and Passenger Door ECU receives this information as a signal.

DTC No.	DTC Detection Condition	Trouble Area
B1233	No change in limit switch more than 2.0 seconds even if operating glass down when limit switch is OFF (window glass is fully closed)	Jam protection limit switch Wireharness

### HINT:

When the door ECU detects the condition that the power window is lowered to turn the limit switch from OFF to ON, this DTC is cleared.

### **WIRING DIAGRAM**



# INSPECTION PROCEDURE

HINT:

Incase of one of other of the control of the contro

1 Whether or not this DTC is cleared when the power window is lowered from fully close condition to half opened condition.



It[is[suspected[that[the[DTC[was[detected[by ECU[with[any[failure[in[the[past.

No

2 | Check[jam[protection[]imit[switch[using[LEXUS[]hand-held[]]ester.

#### PREPARATION:

Connect@he@LEXUS@hand-held@tester@lo@DLC@3.

#### CHECK:

Check The Tam Protection Timit switch using DATA LIST.

ok□

Replace passenger door ECU (See page N-35).

NG

3 | Check[jam[protection[]imit[switch[(See[page[BE-85)).

NG□

Replace power window motor.

OK

4 Check wireharness and connector between jam protection imit witch and front passenger door ECU (See page N-35).

NG

Repair or replace wireharness or connector.

**OK** 

$$\label{lem:condition} \begin{split} & Replace[passenger[door]ECU] \\ & (See[page]N-35). \end{split}$$