CIRCUIT INSPECTION


DI8ML-01

Power Source Circuit

CIRCUIT DESCRIPTION

This circuit provides power to operate the front light ECU.

WIRING DIAGRAM



INSPECTION PROCEDURE

1[]

Check[MPX-B3]fuse.

CHECK:

Checkcontinuityof MPX-B3 fluse.

OK:

Continuity

NG

Replace the failure fuse.

ок

2[]

Check[voltage[between[terminals[FMB3[and[E[bf[front]]ight[ECU[connector.

PREPARATION:

(a) Turn the ignition switch OFF.

(b) ☐ Disconnect ☐ the ☐ ront ☐ ight ☐ ECU ← connector.

CHECK:

Measure[voltage[between]]erminals[FMB3[and[E.

OK:

Voltage: 10 - 14V

OK∏

Proceed_to_next_circuit_inspection_shown_on problem_symptoms_table_(See_page_DI-1156).

NG

3□

Check[wire[harness[and[connector[between[ECU[and[body[ground (See[page[N-35).

NG[]

Repair or replace wire harness or connector.

OK

Check[and[repair]wire[harness[and[connector[between[ECU]and[battery (See[page[DI-1113]).