
DI0X4-13

Tc Terminal Circuit

CIRCUIT DESCRIPTION

Connecting terminals Tc and CG of the DLC3 causes the ECU to display the DTC by flashing the ABS warning light.


WIRING DIAGRAM



INSPECTION PROCEDURE

1

Check voltage between terminals Tc and CG of DLC3.



PREPARATION:

Turn the ignition switch ON.

CHECK:

Measure voltage between terminals Tc and CG of DLC3.

OK:

Voltage: 10 - 14 V

ок∖

If ABS warning light does not blink even after Tc and CG are connected, the ECU may be defective.



Check[or open and short circuit in harness and connector between engine and ECT ECU and DLC3, DLC3 and body ground (See page IN – 35).

NG
Repair or replace harness or connector.

OK

Check for open and short circuit in multiplex communication circuit between engine and ECT ECU to skid control ECU (See page IN – 35).

NG
Repair or replace harness or connector.

OK

Check and replace skid control ECU.