
DI8B2-01

# Power window motor circuit

### **CIRCUIT DESCRIPTION**

The rear left door ECU receives the rear left door power window switch signal from the master switch to operate the power window motor.

### **WIRING DIAGRAM**



## INSPECTION PROCEDURE

HINT:

Incase of using the LEXUS chand-held tester, start the inspection from step of and incase of chand-held tester.

1[

Check power window motor using LEXUS hand-held tester.

### **PREPARATION:**

Connect@he@LEXUS@hand-held@ester@o@DLC3.

#### **CHECK:**

Check[]hat[]he[]power[]window[]motor[]can[]perate[]n[]ACTIVE[]TEST.



Proceed\_to\_next\_circuit\_inspection\_shown\_on problem\_symptoms\_table\_see\_page\_DI-1395).

NG

2 | Check[power[window[motor[See[page[BE-85]]].

NG

Replace power window motor.

OK

Check wireharness and connector between power window motor and rear door LH[ECU[[See]]page[]N-35]).

NG

Repair or replace wireharness or connector.

OK

Proceed to next circuit inspection shown on problem symptoms table (See page DI-1395).