DI8N2-01


| DTC | B2233 | Front Left Center Sensor Malfunction | |
|-----|-------|--------------------------------------|--|
|-----|-------|--------------------------------------|--|

CIRCUIT DESCRIPTION

This DTC is output when failure of the ultrasonic sensor (front left center) is detected.

| DTC No. | DTC Detecting Condition | Trouble Area |
|---------|--|--|
| B2233 | Malfunction of ultrasonic sensor (front left center) | Ultrasonic sensor (front left center) Wire Harness |

WIRING DIAGRAM



INSPECTION PROCEDURE

1 | Check[clearance[sonar[sensor[See[page[BE-183]].

NG

Replace clearance sonar sensor.

OK

2 Check wire harness and connector between clearance sonar sensor and clearance[sonar[ECU[See[page]N-35]).

NG

Repair or replace wire harness or connector.

OK

Replāce clēarance sonar ECU See page IN-35).