
DI8KM-01

Navigation ECU Communication Circuit

CIRCUIT DESCRIPTION

Passenger[\$ide]]/B[ECU[\$ends[A/T[]everse[]position[\$ignal[]o[]the[]Navigation[ECU.

WIRING DIAGRAM



INSPECTION PROCEDURE

1 Check[the[navigation[ECU.

NG

Replace[he_navigation[ECU[See_page IN-35).

OK

2 Check[wire[harness[and[connector[between[havigation[ECU[and[bassenger[side J/B[ECU[See[bage]N-35).

NG

Repair or replace wire harness or connector.

OK

Proceed to next circuit inspection shown on problem symptom table (See page DI-1071).