DTC	B1223	POWER WINDOW SWITCH CIRCUIT ON PASSENGER DOOR
-----	-------	---


CIRCUIT DESCRIPTION

This DTC is output when the passenger door power window regulator switch is operated. HINT:

- If this DTC is output when the switch is not operated, the switch may be stuck.
- If this DTC is not output when the switch is operated, the switch's contact is defective.


DTC No.	DTC Detection Condition	Trouble Area
I B1223 I	Power window regulator switch on passenger door is operating	Power window regulator switch assy
		Passenger door ECU
		Wire harness

WIRING DIAGRAM



INSPECTION PROCEDURE

1 INSPECT POWER WINDOW REGULATOR SWITCH ASSY



- (a) Remove the power window regulator switch.
- (b) Disconnect the P10 (LHD) or P9 (RHD) switch connectors.
- (c) Measure the resistance between the terminals of the connector when the switch is operated.


Standard:

Switch Condition	Tester Connection	Specified Condition
AUTO UP	3 – 8 1 – 8	Below 1 Ω
UP	1 – 8	Below 1 Ω
OFF	-	ı
DOWN	6 – 8	Below 1 Ω
AUTO DOWN	3 – 8 6 – 8	Below 1 Ω

NG REPAIR POWER SWITCH ASSY	WINDOW	REGULATOR
-----------------------------	--------	-----------



2 CHECK WIRE HARNESS (POWER WINDOW CONTROL SWITCH FRONT RH FRONT LH – PASSENGER DOOR ECU)



- (a) Disconnect the P10 (LHD) or P9 (RHD) switch connectors.
- (b) Disconnect the F16 and F17 ECU connectors.
- (c) Measure the resistance of the wire harness side connectors

Standard:

LHD models

Tester Connection	Specified Condition
P10-1 (U) - F16-23 (MUP)	Below 1 Ω
P10-3 (A) - F16-2 (AUTO)	Below 1 Ω
P10-4 (E) - F16-30 (PWE)	Below 1 Ω
P10-6 (D) - F16-25 (MDN)	Below 1 Ω
P10-8 (PCT) - F17-25 (WLS1)	Below 1 Ω

RHD models

Tester Connection	Specified Condition
P9-1 (U) - F16-23 (MUP)	Below 1 Ω
P9-3 (A) - F16-2 (AUTO)	Below 1 Ω
P9-4 (E) - F16-30 (PWE)	Below 1 Ω
P9-6 (D) - F16-25 (MDN)	Below 1 Ω
P9-8 (PCT) - F17-25 (WLS1)	Below 1 Ω

NG

REPAIR OR REPLACE HARNESS AND CONNECTOR

OK

REPLACE PASSENGER DOOR ECU