
DI1GO-12

DTC C1251 / 51 ABS Pump Motor Lock

### **CIRCUIT DESCRIPTION**

DTC No.	DTC Detecting Condition	Trouble Area
C1251 / 51	Detection of either condition 1. or 2.:  1. The ABS pump motor is not operating normally.  2. Open circuit of the ABS pump motor continues for 2 sec. or more.	ABS pump motor


## **WIRING DIAGRAM**



# **INSPECTION PROCEDURE**

1[]

Check operation of pump motor.



#### **PREPARATION:**

Disconnect the brake actuator connector.

#### **CHECK:**

Connect positive ⊕ lead oterminal BM and hegative ⊖ lead to[terminal]GND[offthe]brake[actuator.]Check[that[the]bump[inotor[is perated.

### <u>OK:</u>

The running sound of the pump motor should be heard.



Check[for[open]circuit[]n[harness[and[connector between ABS MTR relay, brake actuator and skid control ECU (See page N-35).



Replace brake actuator.