
DI8O9-01

Power window motor circuit

CIRCUIT DESCRIPTION

The rear right door ECU receives the rear right door power window switch signal from the master switch to operate the power window motor.

WIRING DIAGRAM



INSPECTION PROCEDURE

HINT:

Incase of using the LEXUS hand-held tester, start the inspection from step of and incase of the LEXUS hand-held tester, start from step 2.

1[]

Check[power[window[motor[using[LEXUS[hand-held[tester.

PREPARATION:

Connect@heplexUS@hand-held@ester@oplex3.

CHECK:

Check[]hat[]he[]power[]window[]motor[]can[]perate[]n[]ACTIVE[]TEST.



Proceed_to_next_circuit_inspection_shown_on problem_symptoms_table_see_page_DI-1339).

NG

2[]

Check[power[window[motor[See[page[BE-85]).

NG

Replace power window motor.

OK

3

Check wireharness and connector between power window motor and rear door RH[ECU[See[page]]N-35).

NG

Repair or replace wireharness or connector.

OK

Proceed to next circuit inspection shown on problem symptoms table (See page DI-1339).