
DI8LL-01

Headrest[Limit[Switch[Circuit

CIRCUIT DESCRIPTION

The rear LH seat ECU is detecting the condition of the headrest imit witch.

WIRING DIAGRAM



INSPECTION PROCEDURE

HINT:

Incase of using the LEXUS hand-held tester, start the inspection from step to and incase of hot using the LEXUS hand-held tester, start from step 2.

1 Check[headrest[limit[switch[using[LEXUS[hand-held[tester.

PREPARATION:

Connect[]he[]LEXUS[]hand-held[]ester[]o[]DLC3.

CHECK:

Check the theadrest timit witch using DATA LIST.



Proceed to next circuit inspection shown on problem symptom table (See page DI-742).



2 Check[headrest[limit[switch[See[page[BE-13]]).

NG Replace limit switch.

OK

Check harness and connector between rear LH seat ECU and limit switch, limit switch and body ground (See page N-35).

OK Repair or replace harness or connector.

NG

Proceed to next circuit inspection shown in problem[symptoms[table[See[page IN-35]).