





76°8'0"E 76°8'30"E 76°9'0"E 76°9'30"E 76°10'0"E

Charter Call 1029

AOI No.01




Chooralmala, Wayanad, Kerala, India

Landslide Impact Map

Observed on 03/07/2024 and 04/07/2024

Location Diagrams



Cartographic Information

0 375 750 1,500 m

Local Projection : WGS 1984 UTM Zone 43N Datum : WGS1984
Geographic projection : Lat / Lon (DMS), Datum:WGS 84
Scale : 1:12,500 for A1 prints

N

Legend

	Road		Debris Flow
	River		
	Landslide location (76°8'10.58"E 11°28'0.347"N)		

Interpretation

A major debris flow was triggered by heavy rainfall in and around the Chooralmala town of Wayanad District in Kerala state of India. As per latest reports, more than 200 people are dead and many are missing. Very high resolution KOMPSAT 5 COSI (HH polarisation) SAR image of 3 August, 2024 shows the entire extent of the debris flow from crown to end of run out zone. Further, Pleiades image of 4 August shows small landslides which occurred along the course of the main debris flow.

Data Sources

Pre Event Image : Cartosat 3 (Mx-Pan merged) 22 May, 2023
image © NRSC/ISRO
Post Event : KOMPSAT 5 COSI (HH polarisation) 3 August, 2024
image © KARI
Post Event : Pleiades 1A 4 August, 2024 (Partially cloud free)
image © CNES (2024), Distribution Airbus DS

Frame Work

The best effort rapid mapping product is elaborated within a very short time frame, optimising the available material, and has been quality checked as per NRSC/ISRO procedures.
All geographic informations has limitations due to scale, resolution, date and interpretation of the original source material. No liability concerning the content or the use thereof is assured by the producer.
Note: When publishing this map as part of any report, source may be indicated as "LANDSLIDE OCCURRED IN CHOORALMALA TOWN, WAYANAD DISTRICT, KERALA, INDIA (30 JULY 2024)" dated 05-08-2024, NRSC/ISRO, Hyderabad.
E-mail: gdgsg@nrsc.gov.in

