

Vehicle Inspection Report

JOB-000297



Critical

Summary: Serious issues found. High risk.

Vehicle Details

Customer Name	MR. CX
Inspection Date	Tue Apr 07 2026
Car Make	HONDA
Car Model	CITY
Year	2018
Car Registration Number	TNXXBHXXXX
VIN Number	XXXXXXXXXXXXXXXXXX
Current Odometer Reading	XXXX

Fuel Type

Petrol

Transmission

Manual

Location

MYCARBOY.IN

Background History Check

Blacklist Status

No

[View Document](#)

FIR Record

No

[View Document](#)

Challan Status

No

[View Document](#)

● Overall Summary

Vehicle shows major accident and structural repair history, with several functional issues and incomplete inspection due to vehicle condition.

Windshield: Front windshield replaced → Replacement noted.

Front Body Panels: Bonnet & front bumper replaced → Previous front-end impact repair indicated.

Fog Lamp: Right fog lamp not fitted properly → Refit or bracket repair recommended.

Power Window: Rear LH power window not working → Motor/switch diagnosis required.

Chassis Structure: Front apron and chassis legs repaired → Indicates major front accident repair.

Pillars: All LH side pillars repaired → Structural repair history observed.

Roof: Roof repaired → Major bodywork previously carried out.

Dashboard: Dashboard replaced → Replacement possibly related to accident repair.

Overall Assessment:

Our comprehensive inspection has revealed that this vehicle has been involved in major accidents, with significant repairs performed on its structural components to mask the damage and restore a normal outward appearance. While the mechanical components are currently functioning well, the compromised integrity of the chassis poses a severe risk to long-term safety and vehicle stability. Consequently, we ****strongly recommend against purchasing**** this vehicle, as these structural defects are likely to cause serious future issues and significantly diminish its safety and resale value.

● Attention Needed Areas

Body & Structural	Major Repaired
Accidental History	Yes but repaired
Engine / Gearbox Performance	Normal
OBD Scan Errors (DTC)	No (Normal)
Water Logged (Flooded)	No

OBD Pre-scan Report
[View Document](#)

OBD Post-scan Report
[View Document](#)

Service History
N/A

Inspection Expert Remarks

- 1. Windshield replaced front
- 2. Bonnet and bumper front replaced
- 3. Right fog lamp fitting not properly
- 4. Rear left power window not working
- 5. Front major accident history found and body chassis repaired found (apron and legs)
- 6. Left all pillar repaired
- 7. Roof repaired
- 8. Dashboard replaced

Detailed Checkpoints

Engine Cabin

Engine Physical Condition	Normal
Engine Oil Condition	Normal
Coolant	Normal
Battery Condition	Normal
Fuel Injector	Normal
Left Apron	Normal
Left Apron Leg	Repaired
Right Apron	Normal
Right Apron Leg	Normal
Upper Cross Member	Normal
Lower Cross Member	Normal

Radiator and Support

Normal

Radiator Fan

Normal

Firewall

Normal

Engine Oil Sump

Normal

Cowltop

Normal

Exterior and Body

Windshield

Replaced

Bonnet

Replaced

Front Bumper

Replaced

Front Bumper Grill

Normal

Headlight Left

Normal

Headlight Right

Normal

Fog Lamp Left

Damaged

Fog Lamp Right

Damaged

Fender Left

Repaired

Mirror Assembly Left

Normal

A Pillar Left

Repaired

B Pillar Left

Repaired

C Pillar Left

Repaired

Left Door Front

Repainted

Left Door Rear	Repainted
----------------	-----------

Running Board Left	Repainted
--------------------	-----------

Quarter Panel Left	Repainted
--------------------	-----------

Roof Outer	Repaired
------------	----------

Rear Windshield	Normal
-----------------	--------

Boot Door (Dicky)	Repainted
-------------------	-----------

Rear Bumper	Repainted
-------------	-----------

Boot Floor	Normal
------------	--------

Tool Kit	All available
----------	---------------

Tail Lamp Left	Normal
----------------	--------

Tail Lamp Right	Normal
-----------------	--------

Quarter Panel Right	Repainted
---------------------	-----------

Running Board Right	Major scratched
---------------------	-----------------

Right Door Rear	Repainted
-----------------	-----------

Right Door Front	Major scratched
------------------	-----------------

A Pillar Right	Normal
----------------	--------

B Pillar Right	Normal
----------------	--------

C Pillar Right	Normal
----------------	--------

Mirror Assembly Right	Normal
-----------------------	--------

Fender Right	Major scratched
--------------	-----------------

Interior

Power Window

Rear left not working/switch broken

Power Window Remarks

Rear left power window not working

ORVM Switch

Normal

Airbags

Visual check normal

Instrument Cluster

Visual check normal

Music System

Visual check normal

Music System Remarks

No issues

Horn

Working Normal

Wipers

Working Normal

All Exterior Lamps

Working Normal

Interior Seat Condition

All seats Normal

Sunroof

Working Normal

Steering Wheel Mount Buttons

Damaged

Rear Defogger

Normal

Reverse Camera and Sensor

Working Normal

Airconditioner System

5°C - 8°C (Excellent)

Test Drive

Clutch

Weak need replace

Brakes

Normal

Anti-lock Braking System (ABS)

Working Normal

Acceleration

Normal

Handbrake

Normal

Gear Shifting

Normal

Gear Box

Normal

Paddle Shifters

Working Normal

Suspension

Normal

Engine Sound and Vibration

Normal

Turbo

Not available

Pickup and Performance

Normal

General Noise

No noise

All Wheel Bearing

Normal

Back Compression

Normal

Exhaust Pipe and Smoke

Normal

Flood Effected / Water Logged


No

Compression Check Video

Back Compression Check Video

[View Video](#)

Inspection Gallery



1. Car front image



2. Engine Cabin Image



3. Engine Oil Level Image



4. Radiator Cap Opened




5. Battery Photo



6. Injector / Plug Image



7. Left Apron Image



8. Left Apron Leg Image



9. Right Apron Image




10. Right Apron Leg Image



11. Sump Image



12. Inspection Image



13. Roof Outer Image



14. Inspection Image



15. Inspection Image



16. Rear Left Tyre Thickness



17. Rear Right Tyre Thickness



18. Car Rear Image



19. Boot Door Open Image



20. Boot Floor Images



21. Spare Wheel & Tool Kit Images



22. Cluster Meter Image




25. Interior Images

23. AC Temp Check



26. ABS Image

24. Interior Images



27. Chassis/VIN Image



28. Under Chassis Images



29. Under Chassis Images



30. Under Chassis Images



31. Under Chassis Images



32. Other / Reference



33. Other / Reference



34. Other / Reference



35. Other / Reference



36. Other / Reference



37. Car Right Image

Disclaimer

- **Scope:** This is a visual, non-invasive inspection at the time of service. We do not dismantle parts, and this report reflects the car's condition only at the moment of our check.
- **Repairs:** Use this report as a guide. Please consult a professional mechanic for a full teardown before starting any repairs or part replacements.
- **Odometer:** We record the mileage shown on the dashboard; absolute accuracy can only be guaranteed when backed by a verified service history.
- **Vahan Status:** Challan and Blacklist checks are based on real-time VAHAN portal data. We are not responsible for delays in government portal updates.
- **Testing Limits:** Road tests and OBD scans depend on seller permission and vehicle compatibility. Any restrictions will be noted in the report.
- **Final Decision:** We provide an expert recommendation to help you buy with confidence, but the final purchase decision and future maintenance are the buyer's responsibility.
- **Usage:** This report is created exclusively for the client and may not be resold or reproduced without our permission.