



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice


Date of Incident	12 June 2024	Time of Incident	4.00pm
Directorate / Region	IDD / Metropolitan	Main Roads or Contractor	Contractor
EQSafe Event Type	Injury / Illness	EQSafe Incident Number	41159
Actual Consequence	Major	Potential Consequence	Major

Incident Short Description	Worker sustained a crush injury whilst leveling a storm water pit lid.
-----------------------------------	--

What Happened

A worker was leveling a storm water pit lid (weighing 768kg) using a lifting bar and packers. In the process of leveling the lid the packers have slipped causing the pit lid to move. The Injured Person's (IP) fingers have been pinned between the pit lid and liner. The IP has sustained a crush injury to 3 fingers. The pit lid was lifted by a nearby excavator and slings to free the IP's fingers.

An ambulance was called, and the IP was taken to Hospital for treatment including surgery.



Pit lid, liner and packers (Please note slings were used to free the fingers (incident not involving crane operations))

A formal investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-------------------------------	--