GREY BANNER ALERT

mainroads WESTERN AUSTRALIA

SHW Serious Incident (SI) – Final Notice

Date of Incident	23 March 2026	**Time of Incident**	11:40 AM
Directorate / Region	RMO – Goldfields-Esperance Region	**Main Roads or Contractor**	Main Roads
EQSafe Event Type	Lost Time Injury	**EQSafe Incident Number**	57539
Actual Consequence	Moderate	**Potential Consequence**	Moderate

Incident Short Description	Worker tripped over parking bay wheel stop bar

Executive Summary

A worker was preparing to depart the office to undertake an unexpected delivery of supplies. They placed the items into the vehicle, which was parked in the office back car park, and intended to return to the office before departure. After closing and locking the vehicle, the worker tripped over the parking bay wheel stop bar in the next parking bay. To prevent themselves falling over onto the pavement, the worker overstretched their left leg. They immediately felt as though they had pulled a muscle. The worker was wearing sandals at the time of the incident. The worker sought medical attention the following morning. The Medical Practitioner issued a medical certificate deeming the worker 'unfit for work' for 2 days, resulting in a Lost Time Injury (LTI).

Incident Photos

Reenactment of trip over parking bay wheel stop bar



Measurement of Vehicle Door to Wheel Stop (91 cm)

Contributing Factors
• While Main Roads has installed signage and markings within parking bays, there is currently no signage specifically identifying the presence of a tripping hazard. • The worker was unaware of the hazard when walking back to the office. • The worker believed their foot had cleared the parking bay wheel stop bar. Although the worker was wearing sandals, it is believed that different footwear would not have prevented the incident, as the foot was still required to fully clear the height of stop bar. • The worker was requested at short notice to collect and deliver supplies. • The colour marking on the parking bay wheel stop bar had faded over time reducing its effectiveness.

Corrective Actions
• At the next Office Toolbox, revisit the *Slips, Trips, & Falls* PowerPoint slides which were the corporate monthly focus for February 2026. • Review existing signage and markings and, where required, replace signage and refresh colour markings on all parking bay wheel stop bars. • Install clear and visible signage identifying the tripping hazard within the parking bays to improve hazard awareness and reduce the risk of trips and falls.

Additional Issues / Learnings
• When workers are allocated tasks outside their normal work activities and on short notice, it is important that they take the time to assess the hazards and risks, and ensure appropriate steps are taken to prepare for the task before proceeding. • Workers attending a worksite on the network must wear appropriate PPE, including compliant footwear and high-visibility clothing, unless they remain within the vehicle.

Distribution of Notice	Main Roads Personnel and Contracting Organisations