

**RED BANNER ALERT****mainroads**
WESTERN AUSTRALIA**SHW Serious Incident (SI) – Preliminary Notice**

Date of Incident	10/04/2024	Time of Incident	8.00am
Directorate / Region	RMO, Wheatbelt	Main Roads or Contractor	Contractor
EQSafe Event Type	Injury/ Illness	EQSafe Incident Number	39559
Actual Consequence	Moderate	Potential Consequence	Catastrophic

Incident Short Description	Leaf Spring Dislodges from trailer & injures Member of Public.
-----------------------------------	--

What Happened


A subcontractor was driving a truck and trailer combination from a pit toward the site on Great Southern Highway, with a member of public vehicle (MoP) containing two occupants (driver and passenger) travelling behind.

During the journey, a leaf spring from the prime mover trailer has broken and dislodged from the trailer.

The section of leaf spring (approx. 600mm) has become a projectile and has speared through the windscreen of the member of public's vehicle. The piece of leaf spring has struck the passenger of the vehicle on the head, resulting in a laceration. The section of leaf spring has then come to rest on the back seat of the vehicle.

The Member of Public Driver has alerted the Subcontractor of the occurrence, and both vehicles have pulled over to assess the severity of damage and injury.

Details were exchanged and the driver escorted the passenger to a local medical centre for examination. The truck driver has reported the incident to the Superintendent.

**Section of Leaf spring****Damage to Member of Public's windscreen**

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to
Mobile Plant

Distribution of Notice

Main Roads Personnel and Contracting Organisations