

Crane Splice

Inspection Report:

Product Name: Fabricated lifting plate: a flat plate with 4 nos. of 20 mm drilled hole and complete with a bend rod welded on top

No	Inspection Item		Samples
1	Visual Inspection		Accepted
2	Dimension Inspection	Crane splice	50x10x0.5 cm
		Length	50 cm
		Inner Plate	48x5x0.6 cm
3	Loading Test Results		The Fabricated lifting plate loaded till 6.51 tons
Conclusion			The Fabricated lifting plate safe working load is 1 ton Factor of safety = 6.51







Result / Conclusions:

FROM THE ABOVE OBSERVATION, THE FAILURE POINT OF THE FABRICATED LIFTING PLATE WAS FOUND TO BE 6.51 TONNE .

Next Visit/Exit Call :

NOT APPLICABLE

Enclosures:



Head Office

Factory: Wady Houf, Helwan
Tel: (+202) 23254532 / 23254519
(+20223254534
Fax: (+202) 23671 347
E-mail: sales@acrow.co

