La Palma No 한글??

Steve Purves¹, Rowan Cockett¹

¹Curvenote,

Corresponding author: Steve Purves, ${\tt steve@curvenote.com}$

Abstract

- In September 2021, a significant jump in seismic activity on the island of La
- Palma (Canary Islands, Spain) signaled the start of a volcanic crisis that still
- continues at the time of writing. Earthquake data is continually collected
- and published by the Instituto Geográphico Nacional (IGN). ...

Plain Language Summary

- Earthquake data for the island of La Palma from the September 2021 erup-10
- tion is found ... 11

12

1 Introduction

13 Source: Article Notebook




Figure 1: Timeline of recent earthquakes on La Palma

- 14 Source: Article Notebook
- 15 Source: Article Notebook
- Based on data up to and including 1971, eruptions on La Palma happen ev-16
- ery 79.8 years on average. 17
- Studies of the magma systems feeding the volcano, such as Marrero et al. 18
- (2019), have proposed that there are two main magma reservoirs feeding the 19
- Cumbre Vieja volcano; one in the mantle (30-40km depth) which charges 20
- and in turn feeds a shallower crustal reservoir (10-20km depth). 21
- Eight eruptions have been recorded since the late 1400s (Figure 1). 22
- Data and methods are discussed in Section 2. 23
- Let x denote the number of eruptions in a year. Then, x can be modeled by 24
- a Poisson distribution

$$p(x) = \frac{e^{-\lambda}\lambda^x}{x!} \tag{1}$$

where λ is the rate of eruptions per year. Using Equation 1, the probability

of an eruption in the next t years can be calculated. 27

Table 1: Recent historic eruptions on La Palma

Name	Year
Current	2021
Teneguía	1971
Nambroque	1949
El Charco	1712
Volcán San Antonio	1677
Volcán San Martin	1646
Tajuya near El Paso	1585
Montaña Quemada	1492

- Table 1 summarises the eruptions recorded since the colonization of the
- islands by Europeans in the late 1400s.



Figure 2: Map of La Palma

- La Palma is one of the west most islands in the Volcanic Archipelago of the
- ³¹ Canary Islands (Figure 2).




Figure 3: Locations of earthquakes on La Palma since 2017

- ³² Source: Explore Earthquakes
- Figure 3 shows the location of recent Earthquakes on La Palma.
 - 2 Data & Methods
- 35 Conclusion
- 36 References

37

38

39

Marrero, J., García, A., Berrocoso, M., Llinares, Á., Rodríguez-Losada, A., & Ortiz, R. (2019). Strategies for the development of volcanic hazard maps in monogenetic volcanic fields: The example of La Palma (Canary Islands). Journal of Applied Volcanology, 8. https://doi.org/10.1186/s13617-019-0085-5