

No.: GZMR220902856301

Date: Sep 14, 2022

Page: 1 of 4



CUSTOMER NAME: SHENZHEN YIOUMAI TECHNOLOGY CO.,LTD

ADDRESS: 2F,BIDG.9,FU'AN PHASE II INDUSTRIAL CITY FACTORY,XINTIAN

COMMUNITY, FUHAI STREET, BAO'AN, SHENZHEN

Sample Name : MOBILE PHONE CASE(NIMASO)

Product or Lot No. : EOM-008

Manufacturer : SHENZHEN YIOUMAI TECHNOLOGY CO.,LTD

Other Information : PRODUCTION DATE:20220902

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

SGS Ref. No. : GZF22-030498

Date of Receipt : Sep 07, 2022

Testing Start Date : Sep 07, 2022

Testing End Date : Sep 14, 2022

Test result(s) : For further details, please refer to the following page(s)

(Unless otherwise stated the results shown in this test report refer only

to the sample(s) tested)

Signed for SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Gary Bai

Authorized signatory





No.: GZMR220902856301

Date: Sep 14, 2022

Page: 2 of 4

Summary of Results:


No.	Test Item	Test Method	Result	Conclusion
		With reference to MIL-STD-810H:2019		
1	Drop Test	Method 516.8 Section 4.6.5(Procedure	See result	Pass
		IV) and client's requirement		

Note: Pass: Meet the requirements;

Fail: Does not meet the requirements;

/ : Not Apply to the judgment.

Original Sample Photo:







No.: GZMR220902856301

Date: Sep 14, 2022

Page: 3 of 4

Test Item: Drop Test

Sample Description: Phone case

Test Method: With reference to MIL-STD-810H:2019 Method 516.8 Section 4.6.5(Procedure IV) and

client's requirement

Test Condition:

Drop Height: 200cm
Drop Plane: steel plate


Drop Times: Drop on each face, edge and corner; a total of 26 drops

Lab Environment Condition: 15°C ~ 35°C, 25%RH ~ 75%RH

Test Result:

Sample	Result	Client's requirement	Conclusion
Α	No visual damage.	No visual damage.	Pass

Test Photo:





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overteaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions for Centrolle format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Ferms-en-Document-aspx.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawfull and offenders may be prosecuted to the fullest entent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

**Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443,


or email: CN_Doccheck@sgs.com
□ Ns.1% (Azhu Roat, Szianz CN, Extract Retrindgy Designment Assa, Garagdou, Garagdou, Giras □ Room (10, Babiding 3, Ns.1501, Kaidhang Alenue, Haangu Dishid, Garagdou, Cirias (186-20) 8215555 www.sgsgroup.com.cn
中国・广东・广州市黄埔区开创大道1501号3株101房 (186-20) 8215555 sgs.china@sgs.com



No.: GZMR220902856301

Date: Sep 14, 2022

Page: 4 of 4





During Test-Face

During Test-Corner



During Test-Edge

Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Measuring Tape	7.5m	GZMR-RL-E213-01	2022-08-05	2023-08-04

****** End of report******



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-en-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's Instructions, if any. The Company's sole responsibility is to its Client and this colument cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN. Doccheck@ss.com

mildes, Ganghou, Ganghou, Ginia ロ Roon 101, Bulding 1, Nic 151, Kinhung Menue, Hungu Dishid, Ganghou, China ((86-20) 8215555 www.sgsgroup.com.cn - 地域科珠路198号 中国・广东・广州市黄埔区开创大道1501号3株101房 ((86-20) 8215555 sgs.china@sgs.com 中国・广东・广州高新技术产业开发区科学城科珠路198号