
CEDARS PARK

(Covenanted former site of James I's Theobalds Palace, Cheshunt, Hertfordshire, EN8 8RU)



22/2/2022

© Tarant Hobbs & Google Earth

Examples of 16/17 C. extant high brick walls, with bricks or part-bricks missing

In Zone 'B' (Great Garden) – without photos, although held

- 1. Over 9-foot length at base, past poor remedial work.
- 2. 22-foot total collapse "some four years ago" fenced site doorway frame "affixed to historic building (now toilets)". Late 2/22 several Saplings from fallen tree seed at spot, some 4 feet high, were cut down! Standing wall by entranceway is at a slight west-facing angle and is likely to fall, causing further loss (the Bricks were apparently taken away by the contracted artisan bricklayers, Robyland Ltd their name is on the site doorway).

In Zone 'C' (The Cedars) – without photos, although held

- 3. 1½-foot squarish collapse fenced off for "last 9 months or more".
- 4. 20-foot length of very low wall, 'pushed over' "some 6 years ago or more" now broken in two solid halves. No temporary fencing has ever been installed. (+ long section of collapsed very low wall further west)
- 5. Some 4 feet of low wall, by archway, demolished Summer of 2021 by children climbing on and up tree alongside no temporary fencing installed (reaction 8/21 by Council's Director of Environmental Services (Peter Linkson) was "The remainder needs removing"!!!)
- 6. Several bricks in a squarish shape, missing from the wall, downward cracked wall length nearby, flanked by rotting timber post at Zone 'D' (Pond Quarter) entranceway.

Missing bricks and holes in the walls – with photos

- 7. Wall north of Venusberg
- 8. Wall east of Venusberg
- 9. East-facing wall by the sensory garden
- 10. North-facing wall on Theobalds Lane, at East side of the pedestrian entrance (*No photo*)
- 11. North-facing wall on Theobalds Lane, at East side of main car park entrance (*No photo*)
- 12. North-facing wall on Theobalds Lane, further East a new collapse at top of wall (*No photo*)
- 13. South-facing wall by Venusberg Since before Christmas 2021, new vandalism and continuing (May 2022) imminent collapse of this section of the wall.

*** All the extant historic walls have weeds growing on top, and often on the sides, plus creepers of many species – all weakening the mortar structure, which the Council refuse to remedy ***

Broxbourne Borough Council claim they have a 5-year restoration programme, but there is no continual work underway, and seemingly little urgency or understanding of their responsibility to care for this recognised historic monument area.