Department of Computer Science (UBIT), University of Karachi
CSSE 604 — Software Testing | Morning Program 2026

Quality Assurance Report

Software Bug Report

Application under test: **Hyundai Nishat Motors Website**

Submitted by	Syed Sarim Jawad Zaidi
Seat number	B22110106080
Email ID	zaidisarim9@gmail.com
Contact number	0333 3024614
Submitted to	Sir Hussain Saleem

Acknowledgement

I would like to express my sincere gratitude to my respected teacher, Sir Hussain Saleem, for the guidance, encouragement and practical knowledge shared throughout the CSSE 604 Software Testing course. The emphasis on testing real applications rigorously, rather than only studying the theory, shaped the way this assignment was approached.

The instructions on standard bug-report formats, testing techniques and report structure made it possible to carry out this assignment as a real-world quality assurance exercise. I am also thankful to my classmates and mentors for their support during the testing period.

Syed Sarim Jawad Zaidi
B22110106080

Table of Contents

Acknowledgement....2
Table of Contents....3
1. Introduction....4
1.1 Purpose....4
1.2 Application under test....4
1.3 Scope....4
2. Test Environment....4
3. Testing Approach and Workflow....5
3.1 Testing workflow....5
3.2 Bug life cycle....5
3.3 Severity definitions....5
4. Bug Summary....5
5. Bug Reports....8
BUG-001: Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form....8
BUG-002: Spelling error "Extented Warranty" in the After Sales menu....10
BUG-003: Developer's personal email address exposed in the home page source code 12
BUG-004: Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"....14
BUG-005: "Find a Dealer" is missing from the mobile menu....16
BUG-006: Extended Warranty breadcrumb skips the "After Sales" level....18
BUG-007: Stray backtick instead of an apostrophe in "HNMPL ` s warranty"....20
BUG-008: Missing space in "up to125,000 KM"....22
BUG-009: Vehicle line-up differs between the home page and the Owner's Manual page 24
BUG-010: "Trending around you" tiles cut their captions off mid-sentence....26
BUG-011: Home page banner still promotes the "TUCSON Hybrid 2025"....28
BUG-012: Owner's Manual download buttons misaligned in the first row....30
Appendix....32
A. Features List of the Application....32
B. Tools Used to Find the Bugs....32
C. Testing Techniques Used....33
D. Helpful Internet Links....37

1. Introduction

1.1 Purpose

This report documents the defects found while testing Hyundai Nishat Motors Website as part of the CSSE 604 Software Testing quality assurance assignment. Each defect is recorded on its own page using the standard defect report format from the Lewis textbook, with its severity, reproducible steps, screenshots, environment details and the oracle explaining why it is a bug.

1.2 Application under test

Application	Hyundai Nishat Motors Website
Type	Web application (public corporate and automotive sales/service website)
URL / version	https://hyundai-nishat.com

The Hyundai Nishat Motors website is the official online presence of Hyundai Nishat Motor (Private) Limited, the company that assembles and sells Hyundai vehicles in Pakistan. Customers use it to browse the vehicle line-up and prices, book a vehicle online, check booking status, request a test drive or brochure, book a service appointment, find a dealer and download owner's manuals. It was chosen because it is a live, feature-rich site with many forms and navigation paths, it was not built by the tester, and it serves a large customer base, so its defects have a real impact on users.

1.3 Scope

Testing covered the application's features listed in Appendix A. A total of 19 testing techniques were applied (Appendix C), spanning functional, test-design, UI and usability, cross-browser and responsiveness, performance and security testing.

2. Test Environment

All bugs were found and reproduced on the environments below. Each bug report refers to one of these by its ID.

ID	Device	OS	Browser	Screen	Network
ENV-1	HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM)	Windows 11 Home (build 26300, 64-bit)	Google Chrome 156.0.8078.81	1920×1080 at 125% scaling (1536×864 effective)	4G-class connection, ~10 Mbps
ENV-2	HP Laptop 15s-fq2xxx, Chrome DevTools device emulation	Windows 11 Home (build 26300, 64-bit)	Google Chrome 156 (mobile viewport)	Mobile viewport, ~375 px wide	4G-class connection, ~10 Mbps

3. Testing Approach and Workflow

3.1 Testing workflow

Testing followed the workflow below: features were analysed first, techniques were selected according to the diagnosis of likely malfunctions, and every defect found was logged, classified and retested.




Figure 1: Testing workflow followed in this assignment

3.2 Bug life cycle




Figure 2: Bug life cycle

3.3 Severity definitions

Severity	Meaning
Critical	Crash, data loss, security breach, or a core feature completely unusable with no workaround.
High	A major feature behaves incorrectly or blocks a key user task; a workaround is difficult.
Medium	Feature works partly or incorrectly in some cases; a reasonable workaround exists.
Low	Cosmetic, spelling, alignment or minor usability issue that does not affect functionality.

4. Bug Summary

A total of 12 bug(s) were identified: 0 Critical, 1 High, 4 Medium, 7 Low.

Bug ID	Title	Module	Severity
BUG-001	Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form	Navigation – mobile menu (After Sales)	**High**
BUG-002	Spelling error "Extented Warranty" in the After Sales menu	Navigation – After Sales menu	**Low**
BUG-003	Developer's personal email address exposed in the home page source code	Home page – page source (Instagram feed plugin)	**Medium**
BUG-004	Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"	Navigation – mobile menu	**Medium**
BUG-005	"Find a Dealer" is missing from the mobile menu	Navigation – mobile menu	**Medium**
BUG-006	Extended Warranty breadcrumb skips the "After Sales" level	Extended Warranty page – breadcrumb	**Low**
BUG-007	Stray backtick instead of an apostrophe in "HNMPL ` s warranty"	Extended Warranty page – content	**Low**
BUG-008	Missing space in "up to125,000 KM"	Extended Warranty page – content	**Low**
BUG-009	Vehicle line-up differs between the home page and the Owner's Manual page	Home page vehicles vs Owner's Manual	**Medium**
BUG-010	"Trending around you" tiles cut their captions off mid-sentence	Home page – Trending around you	**Low**
BUG-011	Home page banner still promotes the "TUCSON Hybrid 2025"	Home page – hero banner	**Low**
BUG-012	Owner's Manual download buttons misaligned in the first row	Owner's Manual page – layout	**Low**




Figure 3: Distribution of bugs by severity




Figure 4: Distribution of bugs by module

5. Bug Reports

Each bug below is reported on a separate page using the standard defect report template.

BUG-001: Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form

Bug ID	BUG-001
Title	Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form
Module / feature	Navigation – mobile menu (After Sales)
Severity	**High**
Priority	P1
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Navigation Testing, Mobile Device Testing, Responsive Design Testing
Reproducibility	Always (3 of 3 tries)

Description

On mobile, the only link under "Service Appointment Request" is "Appointment Form", but it leads to the Owner's Manual page. Mobile users cannot reach the service booking form from the menu.

Preconditions

Website opened at a mobile screen width

Steps to reproduce

1. Open https://hyundai-nishat.com on a phone, or in Chrome DevTools device mode (F12, then Ctrl+Shift+M)
2. Tap the menu icon (☰) and expand After Sales
3. Under "Service Appointment Request", tap "Appointment Form"

Test data

None

Expected result

The service appointment booking form opens (hyundai-nishat.com/book-a-service/), as the desktop menu's "Service Appointment" link does.


Actual result

The Owner's Manual page (hyundai-nishat.com/owners-manual/) opens. No path in the mobile menu leads to the booking form.

Oracle (why this is a bug)

The link label and its section heading promise an appointment form. The desktop menu's equivalent link opens the booking form, so the same menu item behaves differently by device: an inconsistency oracle. It blocks a core user task (booking a service) for mobile users.

Screenshots



BUG-001 — Screenshot 1

BUG-002: Spelling error "Extented Warranty" in the After Sales menu

Bug ID	BUG-002
Title	Spelling error "Extented Warranty" in the After Sales menu
Module / feature	Navigation – After Sales menu
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, GUI Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The After Sales menu lists the warranty page as "Extented Warranty". The page it opens is titled "Extended Warranty".

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Hover over or click After Sales in the main menu
3. Read the items under Warranty

Test data

None

Expected result

The menu item reads "Extended Warranty".


Actual result

The menu item reads "Extented Warranty", on both desktop and mobile menus.

Oracle (why this is a bug)

Standard English spelling, and consistency with the destination page, whose heading and breadcrumb both say "Extended Warranty".

Screenshots



BUG-002 — Screenshot 1

BUG-003: Developer's personal email address exposed in the home page source code

Bug ID	BUG-003
Title	Developer's personal email address exposed in the home page source code
Module / feature	Home page – page source (Instagram feed plugin)
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Sensitive Data Exposure Testing, Security Testing, Grey-Box Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The home page HTML includes the Instagram-feed plugin's settings, which contain "mail_to_alert":"umair.munir@crewlogix.com": a named individual's address at a third-party development company.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Press Ctrl+U to view the page source
3. Press Ctrl+F and search for mail_to_alert

Test data

Search term: mail_to_alert

Expected result

No personal or developer email addresses appear in public page source; plugin alert settings stay server-side or use a company address.

Actual result

The source shows "mail_to_alert":"umair.munir@crewlogix.com" (line 1857 in the page source).

Oracle (why this is a bug)

OWASP guidance on sensitive data exposure: internal contact details in public code can be harvested for spam and phishing, and reveal the site's vendor. A production site for Hyundai Nishat should not publish a contractor employee's email address.

Screenshots



BUG-003 — Screenshot 1

BUG-004: Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"

Bug ID	BUG-004
Title	Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"
Module / feature	Navigation – mobile menu
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Responsive Design Testing, Mobile Device Testing, Layout and Alignment Testing, GUI Testing
Reproducibility	Always

Description

When the mobile menu is expanded, its panel ends before the page content. A car image from the page underneath overlaps the last menu item, "Hyundai Promise".

Preconditions

Website opened at a mobile screen width

Steps to reproduce

1. Open any page (for example Owner's Manual) at a mobile width
2. Tap the menu icon (☰)
3. Expand After Sales and scroll to the bottom of the menu

Test data

None

Expected result

The open menu sits on a solid background above all page content, and every menu item is fully readable and tappable.


Actual result

The "Hyundai Promise" item is partly covered by a car image from the page below, and page content continues directly under the menu.

Oracle (why this is a bug)

Usability heuristic: an open navigation menu must be fully visible and usable. The desktop menu has a solid panel, so the mobile behaviour is inconsistent.

Screenshots



BUG-004 — Screenshot 1

BUG-005: "Find a Dealer" is missing from the mobile menu

Bug ID	BUG-005
Title	"Find a Dealer" is missing from the mobile menu
Module / feature	Navigation – mobile menu
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Mobile Device Testing, Navigation Testing, Cross-Platform / OS Compatibility Testing, Checklist-Based Testing
Reproducibility	Always

Description

The desktop main menu has seven items, including Find a Dealer. The mobile menu shows only six: Find a Car, After Sales, Hyundai Pakistan, Press Release, Hyundai Easy Own and Hyundai Promise.

Preconditions

Website opened at a mobile screen width

Steps to reproduce

1. Open https://hyundai-nishat.com on desktop and note the main menu items
2. Switch to a mobile width and tap the menu icon (☰)
3. Compare the two lists

Test data

None

Expected result

The mobile menu offers the same main sections as desktop, including Find a Dealer.


Actual result

Find a Dealer does not appear in the mobile menu.

Oracle (why this is a bug)

Consistency oracle: the desktop menu is the specification of the site's main sections. Finding a dealer is a key task for car buyers, and many of them browse on phones.

Screenshots



BUG-005 — Screenshot 1

BUG-006: Extended Warranty breadcrumb skips the "After Sales" level

Bug ID	BUG-006
Title	Extended Warranty breadcrumb skips the "After Sales" level
Module / feature	Extended Warranty page – breadcrumb
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Navigation Testing, Checklist-Based Testing, GUI Testing
Reproducibility	Always

Description

The Extended Warranty page's breadcrumb reads "Home > Extended Warranty", although the page sits under After Sales in the menu.

Preconditions

None

Steps to reproduce

1. Open After Sales > Extended Warranty
2. Read the breadcrumb under the menu
3. Open After Sales > Owner's Manual and compare its breadcrumb

Test data

None

Expected result

Home > After Sales > Extended Warranty


Actual result

Home > Extended Warranty

Oracle (why this is a bug)

Consistency oracle: Owner's Manual, also under After Sales, shows "Home > After Sales > Owner's Manual". Breadcrumbs should reflect the site hierarchy.

Screenshots



BUG-006 — Screenshot 1

BUG-007: Stray backtick instead of an apostrophe in "HNMPL ` s warranty"

Bug ID	BUG-007
Title	Stray backtick instead of an apostrophe in "HNMPL ` s warranty"
Module / feature	Extended Warranty page – content
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The opening paragraph of the Extended Warranty page reads "backed by HNMPL ` s warranty coverage", with a backtick surrounded by spaces.

Preconditions

None

Steps to reproduce

1. Open After Sales > Extended Warranty
2. Read the first bold paragraph below the warranty badge

Test data

None

Expected result

"backed by HNMPL's warranty coverage"

Actual result

"backed by HNMPL ` s warranty coverage"

Oracle (why this is a bug)

Standard English punctuation for the possessive. The error is in the page's main promotional sentence, so it affects the brand's credibility.

Screenshots

With competitive pricing and extended warranty coverage, Hyundai customers can now drive confidently into the 5th year, knowing they are backed by HNMPL ` s warranty coverage every mile of the way.

Enjoy peace of mind with Hyundai Extended Warranty

- As low as PKR 55,000
- Protects your vehicle from unexpected repair costs
- Provides authorized service charges
- Offers up to125,000 KM / 5 Years Warranty

BUG-007 — Screenshot 1

BUG-008: Missing space in "up to125,000 KM"

Bug ID	BUG-008
Title	Missing space in "up to125,000 KM"
Module / feature	Extended Warranty page – content
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The last benefit bullet on the Extended Warranty page reads "Offers up to125,000 KM / 5 Years Warranty".

Preconditions

None

Steps to reproduce

1. Open After Sales > Extended Warranty
2. Read the bullet list under "Enjoy peace of mind with Hyundai Extended Warranty"

Test data

None

Expected result

"Offers up to 125,000 KM / 5 Years Warranty"


Actual result

"Offers up to125,000 KM / 5 Years Warranty"

Oracle (why this is a bug)

Standard typography: a space separates a word from the number that follows it.

Screenshots



BUG-008 — Screenshot 1

BUG-009: Vehicle line-up differs between the home page and the Owner's Manual page

Bug ID	BUG-009
Title	Vehicle line-up differs between the home page and the Owner's Manual page
Module / feature	Home page vehicles vs Owner's Manual
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Data Integrity Testing, Business Rule Testing, Exploratory Testing
Reproducibility	Always

Description

The home page lists "SANTA FE HYBRID" and no plain Tucson. The Owner's Manual page lists "SANTA FE" (not hybrid) and adds a separate "TUCSON". The two pages disagree on which models Hyundai Nishat offers.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com and scroll to the Vehicles section
2. Note the model names
3. Open After Sales > Owner's Manual and compare the model names

Test data

None

Expected result

Both pages list the same models with the same names, or the Owner's Manual clearly marks discontinued models.


Actual result

Home: Elantra 1.6 Special Edition, Elantra Hybrid, Sonata, Sonata N Line, Tucson Hybrid, Santa Fe Hybrid, Palisade Hybrid, IONIQ 5, IONIQ 6, Porter H-100 (10 models). Owner's Manual: adds "TUCSON" and names "SANTA FE" instead of "SANTA FE HYBRID" (11 models).


Oracle (why this is a bug)

Data integrity oracle: the same product data should match across pages. A Santa Fe Hybrid owner may download the wrong manual, and customers get conflicting information about which models are sold.

Screenshots



BUG-009 — Screenshot 1



BUG-009 — Screenshot 2

BUG-010: "Trending around you" tiles cut their captions off mid-sentence

Bug ID	BUG-010
Title	"Trending around you" tiles cut their captions off mid-sentence
Module / feature	Home page – Trending around you
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	GUI Testing, Layout and Alignment Testing, Content and Spelling Testing
Reproducibility	Always

Description

Captions at the bottom of the promotional tiles are truncated, for example "Bring home the SANTA FE Hybrid and" and "Choose the TUCSON Hybrid and", with no ellipsis or way to read the rest.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Scroll to "Trending around you"
3. Read the captions at the bottom of the second and third tiles

Test data

None

Expected result

Each caption is shown in full, or ends with an ellipsis and the tile links to the full offer.


Actual result

Captions stop mid-sentence and the rest of the text is hidden.

Oracle (why this is a bug)

Usability heuristic: text must not be clipped without an indication. The captions carry the offer details, so users miss the key information.

Screenshots



BUG-010 — Screenshot 1

BUG-011: Home page banner still promotes the "TUCSON Hybrid 2025"

Bug ID	BUG-011
Title	Home page banner still promotes the "TUCSON Hybrid 2025"
Module / feature	Home page – hero banner
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Business Rule Testing, Exploratory Testing
Reproducibility	Always

Description

The main home page carousel shows "The all-new Hyundai TUCSON Hybrid 2025" in November 2026.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Watch the hero carousel until the TUCSON Hybrid slide appears

Test data

None

Expected result

Banners promote current model-year vehicles, or omit the year.


Actual result

The slide calls a 2025 model "all-new" in late 2026.

Oracle (why this is a bug)

Currency of content: the site footer says "Copyright 2026", and an "all-new" claim for a previous model year is outdated marketing.

Screenshots



BUG-011 — Screenshot 1

BUG-012: Owner's Manual download buttons misaligned in the first row

Bug ID	BUG-012
Title	Owner's Manual download buttons misaligned in the first row
Module / feature	Owner's Manual page – layout
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Layout and Alignment Testing, GUI Testing, Visual Regression Testing
Reproducibility	Always

Description

"ELANTRA 1.6 SPECIAL EDITION" wraps onto two lines, which pushes its Download button lower than the Download buttons of the other three vehicles in the same row.

Preconditions

None

Steps to reproduce

1. Open After Sales > Owner's Manual on a 1920×1080 screen
2. Look at the first row of vehicles

Test data

None

Expected result

All Download buttons in a row line up horizontally, whatever the length of the model name.

Actual result

The first Download button sits about one line lower than the other three.

Oracle (why this is a bug)

Visual consistency in a grid layout. Every other row on the page is aligned, so this row is the exception.

Screenshots



BUG-012 — Screenshot 1

Appendix

A. Features List of the Application

- Home page: promotional banners, booking pop-up, quick-action links
- Find a Car: vehicle catalogue with category filter (All, Sedan, SUV, Electric, Commercial) and starting prices
- Vehicle model pages: Elantra, Elantra Hybrid, Sonata, Sonata N Line, Tucson Hybrid, Santa Fe, Palisade Hybrid, IONIQ 5, IONIQ 6, Porter H-100
- Online Booking
- Booking Status check
- Request a Test Drive form
- Request a Brochure form
- Service Appointment Request (Book a Service) form
- Find a Dealer (dealer locator)
- Hyundai Easy Own (financing information)
- Hyundai Promise
- After Sales: warranty conditions, extended warranty, genuine parts, lubricants, engine oil
- Hyundai Service: customer promise, dealership facility, free services, periodic maintenance charts, owner's manual
- About Us: overview, corporate message, philosophy
- Press Release & News
- Career page
- Contact Us page
- Email newsletter sign-up
- Footer: legal disclaimer, cookie policy, sitemap, social media links
- myHyundai customer portal (external: myhyundaipakistan.com)

B. Tools Used to Find the Bugs

#	Tool	Purpose
1	Google Chrome 156	Main browser for all functional, navigation, content and layout testing
2	Chrome DevTools – Device Mode (F12, Ctrl+Shift+M)	Mobile viewport emulation for responsive and mobile-menu testing (ENV-2)
3	Chrome DevTools – Elements and Console	Inspecting page structure, link targets and console errors
4	Chrome View Page Source (Ctrl+U)	Static review of the page's HTML; found the exposed developer email (BUG-003)
5	Google Lighthouse	Performance, accessibility, best-practice and SEO audits
6	GoFullPage (Chrome extension)	Full-page screenshots of long pages (home page, Owner's Manual, Extended Warranty)
7	Windows Snipping Tool (Win+Shift+S)	Screenshots of menus and specific screen areas used as bug evidence
8	Windows System Information (msinfo32)	Recording the test machine's hardware and OS details for the environment table

#	Tool	Purpose
9	Microsoft Word / LibreOffice Writer	Writing and exporting this report to .docx and .pdf
10	Python (Matplotlib) and Mermaid	Drawing the bug-summary graphs and the workflow diagrams

C. Testing Techniques Used

19 of the 100 techniques below were applied. Applied techniques are marked ✔ with the bugs they uncovered.

#	Technique	Category	Applied	Bug IDs
1	Functional Testing	Functional	—	
2	Smoke Testing	Functional	—	
3	Sanity Testing	Functional	—	
4	Regression Testing	Functional	✔	BUG-012
5	Retesting (Confirmation Testing)	Functional	—	
6	Exploratory Testing	Functional	✔	BUG-009, BUG-011
7	Ad-hoc Testing	Functional	—	
8	Monkey Testing	Functional	—	
9	Gorilla Testing	Functional	—	
10	End-to-End Testing	Functional	—	
11	Integration Testing	Functional	—	
12	System Testing	Functional	—	
13	User Acceptance Testing	Functional	—	
14	Alpha Testing	Functional	—	
15	Beta Testing	Functional	—	
16	API Testing	Functional	—	
17	Database Testing	Functional	—	
18	Data Integrity Testing	Functional	✔	BUG-009
19	Business Rule Testing	Functional	✔	BUG-009, BUG-011
20	Workflow Testing	Functional	—	
21	Navigation Testing	Functional	✔	BUG-001, BUG-005, BUG-006
22	Broken Link Testing	Functional	—	
23	Search Functionality Testing	Functional	—	
24	Error Handling Testing	Functional	—	

#	Technique	Category	Applied	Bug IDs
25	Error Message Testing	Functional	—	
26	Payment / Transaction Testing	Functional	—	
27	Session Management Testing	Functional	—	
28	Interrupt Testing	Functional	—	
29	Boundary Value Analysis	Test design (black-box)	—	
30	Equivalence Partitioning	Test design (black-box)	—	
31	Decision Table Testing	Test design (black-box)	—	
32	State Transition Testing	Test design (black-box)	—	
33	Use Case Testing	Test design (black-box)	—	
34	Cause-Effect Graphing	Test design (black-box)	—	
35	Pairwise (All-Pairs) Testing	Test design (black-box)	—	
36	Error Guessing	Test design (black-box)	—	
37	Positive Testing	Test design (black-box)	—	
38	Negative Testing	Test design (black-box)	—	
39	Input Validation Testing	Test design (black-box)	—	
40	Required Field Testing	Test design (black-box)	—	
41	Field Length Testing	Test design (black-box)	—	
42	Special Character Testing	Test design (black-box)	—	
43	Null / Empty Input Testing	Test design (black-box)	—	
44	Date and Time Testing	Test design (black-box)	—	
45	Checklist-Based Testing	Test design (black-box)	✔	BUG-005, BUG-006
46	Scenario-Based Testing	Test design (black-box)	—	
47	Black-Box Testing	Structural / approach	✔	
48	White-Box Testing	Structural / approach	—	

#	Technique	Category	Applied	Bug IDs
49	Grey-Box Testing	Structural / approach	✔	BUG-003
50	Static Testing (Reviews)	Structural / approach	✔	BUG-002, BUG-003, BUG-007, BUG-008
51	Unit Testing	Structural / approach	—	
52	Component Testing	Structural / approach	—	
53	GUI Testing	UI and usability	✔	BUG-002, BUG-004, BUG-006, BUG-010, BUG-012
54	Usability Testing	UI and usability	—	
55	Accessibility Testing	UI and usability	—	
56	Colour Contrast Testing	UI and usability	—	
57	Keyboard Navigation Testing	UI and usability	—	
58	Screen Reader Testing	UI and usability	—	
59	Responsive Design Testing	UI and usability	✔	BUG-001, BUG-004
60	Cross-Browser Testing	UI and usability	—	
61	Cross-Platform / OS Compatibility Testing	UI and usability	✔	BUG-005
62	Mobile Device Testing	UI and usability	✔	BUG-001, BUG-004, BUG-005
63	Orientation (Portrait/Landscape) Testing	UI and usability	—	
64	Layout and Alignment Testing	UI and usability	✔	BUG-004, BUG-010, BUG-012
65	Typography and Font Consistency Testing	UI and usability	—	
66	Content and Spelling Testing	UI and usability	✔	BUG-002, BUG-007, BUG-008, BUG-010, BUG-011
67	Zoom / Text Scaling Testing	UI and usability	—	
68	Localization Testing	UI and usability	—	
69	Internationalization Testing	UI and usability	—	
70	Visual Regression Testing	UI and usability	✔	BUG-012
71	Performance Testing	Performance	—	

#	Technique	Category	Applied	Bug IDs
72	Load Testing	Performance	—	
73	Stress Testing	Performance	—	
74	Spike Testing	Performance	—	
75	Endurance (Soak) Testing	Performance	—	
76	Volume Testing	Performance	—	
77	Scalability Testing	Performance	—	
78	Page Load Speed Testing	Performance	—	
79	Low Bandwidth / Network Throttling Testing	Performance	—	
80	Offline Behaviour Testing	Performance	—	
81	Security Testing	Security	✔	BUG-003
82	Authentication Testing	Security	—	
83	Authorization / Access Control Testing	Security	—	
84	Password Policy Testing	Security	—	
85	Session Timeout Testing	Security	—	
86	SQL Injection Testing	Security	—	
87	Cross-Site Scripting (XSS) Testing	Security	—	
88	CSRF Testing	Security	—	
89	HTTPS / SSL Testing	Security	—	
90	Security Headers Testing	Security	—	
91	Cookie Security Testing	Security	—	
92	Brute Force / Rate Limiting Testing	Security	—	
93	File Upload Testing	Security	—	
94	Sensitive Data Exposure Testing	Security	✔	BUG-003
95	Vulnerability Scanning	Security	—	
96	Compatibility Testing	Other	✔	BUG-005
97	Installation Testing	Other	—	
98	Update / Upgrade Testing	Other	—	
99	Recovery Testing	Other	—	
100	Configuration Testing	Other	—	

Techniques created or adapted for this assignment:

- Desktop–Mobile Parity Check: open the same page and menu on desktop and in mobile view side by side, and compare every item, link target and label. Any difference is a candidate bug (found BUG-001 and BUG-005).

D. Helpful Internet Links

- Hyundai Nishat Motors website (application under test) — https://hyundai-nishat.com
- OWASP Top 10 Web Application Security Risks — https://owasp.org/www-project-top-ten/
- W3C Web Content Accessibility Guidelines (WCAG) 2.1 — https://www.w3.org/TR/WCAG21/
- Chrome Lighthouse documentation — https://developer.chrome.com/docs/lighthouse/overview
- ISTQB Glossary — https://glossary.istqb.org/
- Chrome DevTools – Simulate mobile devices with Device Mode — https://developer.chrome.com/docs/devtools/device-mode