Department of Computer Science (UBIT), University of Karachi
CSSE 604 — Software Testing | Morning Program 2026

Quality Assurance Report

Software Bug Report

Application under test: **Hyundai Nishat Motors Website**

Submitted by	Syed Sarim Jawad Zaidi
Seat number	B22110106080
Email ID	zaidisarim9@gmail.com
Contact number	0333 3024614
Submitted to	Sir Hussain Saleem

Acknowledgement

I would like to express my sincere gratitude to my respected teacher, Sir Hussain Saleem, for the guidance, encouragement and practical knowledge shared throughout the CSSE 604 Software Testing course. The emphasis on testing real applications rigorously, rather than only studying the theory, shaped the way this assignment was approached.

The instructions on standard bug-report formats, testing techniques and report structure made it possible to carry out this assignment as a real-world quality assurance exercise. I am also thankful to my classmates and mentors for their support during the testing period.

Syed Sarim Jawad Zaidi
B22110106080

Table of Contents

Acknowledgement....2
Table of Contents....3
1. Introduction....5
1.1 Purpose....5
1.2 Application under test....5
1.3 Scope....5
2. Test Environment....5
3. Testing Approach and Workflow....6
3.1 Testing workflow....6
3.2 Bug life cycle....6
3.3 Severity definitions....6
4. Bug Summary....7
5. Bug Reports....11
BUG-001: Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form....11
BUG-002: Spelling error "Extented Warranty" in the After Sales menu....13
BUG-003: Developer's personal email address exposed in the home page source code 15
BUG-004: Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"....17
BUG-005: "Find a Dealer" is missing from the mobile menu....19
BUG-006: Extended Warranty breadcrumb skips the "After Sales" level....21
BUG-007: Stray backtick instead of an apostrophe in "HNMPL ` s warranty"....23
BUG-008: Missing space in "up to125,000 KM"....25
BUG-009: Vehicle line-up differs between the home page and the Owner's Manual page 27
BUG-010: "Trending around you" tiles cut their captions off mid-sentence....29
BUG-011: Home page banner still promotes the "TUCSON Hybrid 2025"....31
BUG-012: Owner's Manual download buttons misaligned in the first row....33
BUG-013: Name field accepts digits only ("12345") without any validation error....35
BUG-014: Required drop-down fields show no error when left empty....37
BUG-015: Form section is headed "Salutation" but contains no salutation field....39
BUG-016: Grammar error in the page subtitle: "Hyundai provide you with booking service" 41
BUG-017: Unit written as "Odometer (KM's)" with a wrong apostrophe....43
BUG-018: Comments field is mandatory for a service booking....45
BUG-019: VIN field placeholder shows a realistic VIN that looks pre-filled....47
BUG-020: Invalid email "abc@" gives a misleading message: "Please enter an email address"....48
BUG-021: "Model Name" does not depend on "Model": it lists model names and can be chosen while Model is empty....50
BUG-022: Model list does not match the current line-up: Palisade missing, Starex and Staria listed....52
BUG-023: Service appointment time allows any 15-minute slot from 00:00 to 23:45....54
BUG-024: Dealer list is not filtered by the selected City....56
BUG-025: Dealer names do not show their location ("Hyundai-South", "Hyundai-Premium", "Hyundai-Central")....58
BUG-026: Test Drive form also accepts digits only ("12345") as Full Name....60
BUG-027: Required "Vehicle" and "Salutation" show no error when empty, although City and Dealer Name do....62
BUG-028: Consent text contains an unfilled template blank ("Order**No:……") and refers to a Vehicle Sales Order....64
BUG-029: Salutation list offers only Mr., Mrs. and Other: no Ms. or Miss....66

BUG-030: Page promises a test drive "appointment" but the form has no date or time field 68
BUG-031: "Vehicle*" label has no space before the asterisk, unlike every other label..... 70
BUG-032: Reset button has a colour contrast of 1.6:1 and looks disabled..... 72
BUG-033: Footer links and copyright text fail contrast: grey #676767 on black (3.7:1)..... 74
BUG-034: The same page is called four different names: "Service Appointment", "Service Appointment Request", "Book a Service" and "Book a Hyundai Service"..... 76
BUG-035: "Request a Brochure" has no request form: the page is a plain download list. 78
BUG-036: Brochure grid misaligned in two rows (Elantra 1.6 Special Edition and Santa Fe Hybrid)..... 80
BUG-037: Owner's Manual downloads (17–76 MB) start immediately, with no file size shown and no preview..... 82
BUG-038: Elantra and Porter manuals are scanned images: text cannot be searched, selected or read by screen readers..... 84
BUG-039: Owner's manuals are generic, dated editions written for left-hand-drive cars (Elantra 2020, IONIQ 5 2022)..... 86
BUG-040: Tucson Hybrid manual's text layer is corrupted: searching or copying gives gibberish..... 88
BUG-041: Content-Security-Policy allows 'unsafe-inline' and 'unsafe-eval' scripts, weakening protection against XSS..... 90
BUG-042: Server header reveals the exact web server version: "Apache/2.4.58 (Ubuntu)" 92
BUG-043: Second SSL certificate (served to clients without SNI) does not match hyundai-nishat.com and is reported as not trusted..... 94
BUG-044: Home page is very slow on mobile: Lighthouse Performance 48, main content appears after 25.1 s..... 96
BUG-045: Page layout jumps while loading: Cumulative Layout Shift 0.367..... 98
BUG-046: Home page downloads 6 MB, with unoptimised images and no long-term caching..... 100
BUG-047: Accessibility audit failures: unnamed dialog, unnamed links, low contrast and skipped heading levels..... 102
BUG-048: Browser errors are logged to the console on the home page..... 104
BUG-049: "Booking your Hyundai?" pop-up covers the home page on every visit, even on mobile..... 106
BUG-050: SEO audit: links without descriptive text and links search engines cannot crawl 109
Appendix..... 111
A. Features List of the Application..... 111
B. Tools Used to Find the Bugs..... 111
C. Testing Techniques Used..... 112
D. Helpful Internet Links..... 117

1. Introduction

1.1 Purpose

This report documents the defects found while testing Hyundai Nishat Motors Website as part of the CSSE 604 Software Testing quality assurance assignment. Each defect is recorded on its own page using the standard defect report format from the Lewis textbook, with its severity, reproducible steps, screenshots, environment details and the oracle explaining why it is a bug.

1.2 Application under test

Application	Hyundai Nishat Motors Website
Type	Web application (public corporate and automotive sales/service website)
URL / version	https://hyundai-nishat.com

The Hyundai Nishat Motors website is the official online presence of Hyundai Nishat Motor (Private) Limited, the company that assembles and sells Hyundai vehicles in Pakistan. Customers use it to browse the vehicle line-up and prices, book a vehicle online, check booking status, request a test drive or brochure, book a service appointment, find a dealer and download owner's manuals. It was chosen because it is a live, feature-rich site with many forms and navigation paths, it was not built by the tester, and it serves a large customer base, so its defects have a real impact on users.

1.3 Scope

Testing covered the application's features listed in Appendix A. A total of 55 testing techniques were applied (Appendix C), spanning functional, test-design, UI and usability, cross-browser and responsiveness, performance and security testing.

2. Test Environment

All bugs were found and reproduced on the environments below. Each bug report refers to one of these by its ID.

ID	Device	OS	Browser	Screen	Network
ENV-1	HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM)	Windows 11 Home (build 26300, 64-bit)	Google Chrome 156.0.8078.81	1920×1080 at 125% scaling (1536×864 effective)	4G-class connection, ~10 Mbps
ENV-2	HP Laptop 15s-fq2xxx, Chrome DevTools device emulation	Windows 11 Home (build 26300, 64-bit)	Google Chrome 156 (mobile viewport)	Mobile viewport, ~375 px wide	4G-class connection, ~10 Mbps

ID	Device	OS	Browser	Screen	Network
ENV-3	HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM)	Windows 11 Home 26H2 (build 26300.9818, 64-bit)	Microsoft Edge 157.0.4341.42 (64-bit, Chromium 157.0.8103.39)	1920×1080 at 125% scaling	4G-class connection, ~10 Mbps

3. Testing Approach and Workflow

3.1 Testing workflow

Testing followed the workflow below: features were analysed first, techniques were selected according to the diagnosis of likely malfunctions, and every defect found was logged, classified and retested.




Figure 1: Testing workflow followed in this assignment

3.2 Bug life cycle




Figure 2: Bug life cycle

3.3 Severity definitions

Severity	Meaning
Critical	Crash, data loss, security breach, or a core feature completely unusable with no workaround.
High	A major feature behaves incorrectly or blocks a key user task; a workaround is difficult.

Severity	Meaning
Medium	Feature works partly or incorrectly in some cases; a reasonable workaround exists.
Low	Cosmetic, spelling, alignment or minor usability issue that does not affect functionality.

4. Bug Summary

A total of 50 bug(s) were identified: 0 Critical, 2 High, 23 Medium, 25 Low.

Bug ID	Title	Module	Severity
BUG-001	Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form	Navigation – mobile menu (After Sales)	**High**
BUG-002	Spelling error "Extented Warranty" in the After Sales menu	Navigation – After Sales menu	**Low**
BUG-003	Developer's personal email address exposed in the home page source code	Home page – page source (Instagram feed plugin)	**Medium**
BUG-004	Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"	Navigation – mobile menu	**Medium**
BUG-005	"Find a Dealer" is missing from the mobile menu	Navigation – mobile menu	**Medium**
BUG-006	Extended Warranty breadcrumb skips the "After Sales" level	Extended Warranty page – breadcrumb	**Low**
BUG-007	Stray backtick instead of an apostrophe in "HNMPL ` s warranty"	Extended Warranty page – content	**Low**
BUG-008	Missing space in "up to125,000 KM"	Extended Warranty page – content	**Low**
BUG-009	Vehicle line-up differs between the home page and the Owner's Manual page	Home page vehicles vs Owner's Manual	**Medium**
BUG-010	"Trending around you" tiles cut their captions off mid-sentence	Home page – Trending around you	**Low**
BUG-011	Home page banner still promotes the "TUCSON Hybrid 2025"	Home page – hero banner	**Low**
BUG-012	Owner's Manual download buttons misaligned in the first row	Owner's Manual page – layout	**Low**
BUG-013	Name field accepts digits only ("12345") without any validation error	Book a Service form	**Medium**
BUG-014	Required drop-down fields show no error when left empty	Book a Service form	**Medium**
BUG-015	Form section is headed "Salutation" but contains no salutation field	Book a Service form	**Low**

Bug ID	Title	Module	Severity
BUG-016	Grammar error in the page subtitle: "Hyundai provide you with booking service"	Book a Service form	**Low**
BUG-017	Unit written as "Odometer (KM's)" with a wrong apostrophe	Book a Service form	**Low**
BUG-018	Comments field is mandatory for a service booking	Book a Service form	**Low**
BUG-019	VIN field placeholder shows a realistic VIN that looks pre-filled	Book a Service form	**Low**
BUG-020	Invalid email "abc@" gives a misleading message: "Please enter an email address"	Book a Service form	**Low**
BUG-021	"Model Name" does not depend on "Model": it lists model names and can be chosen while Model is empty	Book a Service form	**Medium**
BUG-022	Model list does not match the current line-up: Palisade missing, Starex and Staria listed	Book a Service form	**Medium**
BUG-023	Service appointment time allows any 15-minute slot from 00:00 to 23:45	Book a Service form	**Medium**
BUG-024	Dealer list is not filtered by the selected City	Book a Service form	**Medium**
BUG-025	Dealer names do not show their location ("Hyundai-South", "Hyundai-Premium", "Hyundai-Central")	Book a Service form	**Low**
BUG-026	Test Drive form also accepts digits only ("12345") as Full Name	Request a Test Drive form	**Medium**
BUG-027	Required "Vehicle" and "Salutation" show no error when empty, although City and Dealer Name do	Request a Test Drive form	**Medium**
BUG-028	Consent text contains an unfilled template blank ("Order**No:……") and refers to a Vehicle Sales Order	Request a Test Drive form	**Medium**
BUG-029	Salutation list offers only Mr., Mrs. and Other: no Ms. or Miss	Request a Test Drive form	**Low**
BUG-030	Page promises a test drive "appointment" but the form has no date or time field	Request a Test Drive form	**Low**
BUG-031	"Vehicle*" label has no space before the asterisk, unlike every other label	Request a Test Drive form	**Low**
BUG-032	Reset button has a colour contrast of 1.6:1 and looks disabled	Book a Service form	**Medium**
BUG-033	Footer links and copyright text fail contrast: grey #676767 on black (3.7:1)	Site-wide footer	**Low**
BUG-034	The same page is called four different names: "Service Appointment", "Service Appointment Request", "Book a Service" and "Book a Hyundai Service"	Book a Service and Request a Test Drive pages	**Low**

Bug ID	Title	Module	Severity
BUG-035	"Request a Brochure" has no request form: the page is a plain download list	Request a Brochure page	**Low**
BUG-036	Brochure grid misaligned in two rows (Elantra 1.6 Special Edition and Santa Fe Hybrid)	Request a Brochure page	**Low**
BUG-037	Owner's Manual downloads (17–76 MB) start immediately, with no file size shown and no preview	Owner's Manual – downloads	**Medium**
BUG-038	Elantra and Porter manuals are scanned images: text cannot be searched, selected or read by screen readers	Owner's Manual – downloads	**Medium**
BUG-039	Owner's manuals are generic, dated editions written for left-hand-drive cars (Elantra 2020, IONIQ 5 2022)	Owner's Manual – downloads	**Medium**
BUG-040	Tucson Hybrid manual's text layer is corrupted: searching or copying gives gibberish	Owner's Manual – downloads	**Medium**
BUG-041	Content-Security-Policy allows 'unsafe-inline' and 'unsafe-eval' scripts, weakening protection against XSS	Site-wide – HTTP security headers	**Medium**
BUG-042	Server header reveals the exact web server version: "Apache/2.4.58 (Ubuntu)"	Site-wide – HTTP response headers	**Low**
BUG-043	Second SSL certificate (served to clients without SNI) does not match hyundai-nishat.com and is reported as not trusted	Site-wide – HTTPS / SSL	**Low**
BUG-044	Home page is very slow on mobile: Lighthouse Performance 48, main content appears after 25.1 s	Home page – performance	**High**
BUG-045	Page layout jumps while loading: Cumulative Layout Shift 0.367	Home page – performance	**Medium**
BUG-046	Home page downloads 6 MB, with unoptimised images and no long-term caching	Home page – performance	**Medium**
BUG-047	Accessibility audit failures: unnamed dialog, unnamed links, low contrast and skipped heading levels	Home page – accessibility	**Medium**
BUG-048	Browser errors are logged to the console on the home page	Home page – JavaScript	**Low**
BUG-049	"Booking your Hyundai?" pop-up covers the home page on every visit, even on mobile	Home page – pop-up	**Medium**
BUG-050	SEO audit: links without descriptive text and links search engines cannot crawl	Home page – SEO	**Low**




Figure 3: Distribution of bugs by severity




Figure 4: Distribution of bugs by module

5. Bug Reports

Each bug below is reported on a separate page using the standard defect report template.

BUG-001: Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form

Bug ID	BUG-001
Title	Mobile menu "Appointment Form" link opens the Owner's Manual page instead of the service booking form
Module / feature	Navigation – mobile menu (After Sales)
Severity	**High**
Priority	P1
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Navigation Testing, Mobile Device Testing, Responsive Design Testing
Reproducibility	Always (3 of 3 tries)

Description

On mobile, the only link under "Service Appointment Request" is "Appointment Form", but it leads to the Owner's Manual page. Mobile users cannot reach the service booking form from the menu.

Preconditions

Website opened at a mobile screen width

Steps to reproduce

1. Open https://hyundai-nishat.com on a phone, or in Chrome DevTools device mode (F12, then Ctrl+Shift+M)
2. Tap the menu icon (☰) and expand After Sales
3. Under "Service Appointment Request", tap "Appointment Form"

Test data

None

Expected result

The service appointment booking form opens (hyundai-nishat.com/book-a-service/), as the desktop menu's "Service Appointment" link does.


Actual result

The Owner's Manual page (hyundai-nishat.com/owners-manual/) opens. No path in the mobile menu leads to the booking form.

Oracle (why this is a bug)

The link label and its section heading promise an appointment form. The desktop menu's equivalent link opens the booking form, so the same menu item behaves differently by device: an inconsistency oracle. It blocks a core user task (booking a service) for mobile users.

Screenshots



BUG-001 — Screenshot 1

BUG-002: Spelling error "Extented Warranty" in the After Sales menu

Bug ID	BUG-002
Title	Spelling error "Extented Warranty" in the After Sales menu
Module / feature	Navigation – After Sales menu
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, GUI Testing, Static Testing (Reviews), Cross-Browser Testing
Reproducibility	Always

Description

The After Sales menu lists the warranty page as "Extented Warranty". The page it opens is titled "Extended Warranty". Reproduced in Microsoft Edge (ENV-3).

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Hover over or click After Sales in the main menu
3. Read the items under Warranty

Test data

None

Expected result

The menu item reads "Extended Warranty".


Actual result

The menu item reads "Extented Warranty", on both desktop and mobile menus.


Oracle (why this is a bug)

Standard English spelling, and consistency with the destination page, whose heading and breadcrumb both say "Extended Warranty".

Screenshots



BUG-002 — Screenshot 1



BUG-002 — Screenshot 2

BUG-003: Developer's personal email address exposed in the home page source code

Bug ID	BUG-003
Title	Developer's personal email address exposed in the home page source code
Module / feature	Home page – page source (Instagram feed plugin)
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Sensitive Data Exposure Testing, Security Testing, Grey-Box Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The home page HTML includes the Instagram-feed plugin's settings, which contain "mail_to_alert":"umair.munir@crewlogix.com": a named individual's address at a third-party development company.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Press Ctrl+U to view the page source
3. Press Ctrl+F and search for mail_to_alert

Test data

Search term: mail_to_alert

Expected result

No personal or developer email addresses appear in public page source; plugin alert settings stay server-side or use a company address.

Actual result

The source shows "mail_to_alert":"umair.munir@crewlogix.com" (line 1857 in the page source).

Oracle (why this is a bug)

OWASP guidance on sensitive data exposure: internal contact details in public code can be harvested for spam and phishing, and reveal the site's vendor. A production site for Hyundai Nishat should not publish a contractor employee's email address.

Screenshots



BUG-003 — Screenshot 1

BUG-004: Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"

Bug ID	BUG-004
Title	Open mobile menu does not cover the page: content shows through and overlaps "Hyundai Promise"
Module / feature	Navigation – mobile menu
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Responsive Design Testing, Mobile Device Testing, Layout and Alignment Testing, GUI Testing
Reproducibility	Always

Description

When the mobile menu is expanded, its panel ends before the page content. A car image from the page underneath overlaps the last menu item, "Hyundai Promise".

Preconditions

Website opened at a mobile screen width

Steps to reproduce

1. Open any page (for example Owner's Manual) at a mobile width
2. Tap the menu icon (☰)
3. Expand After Sales and scroll to the bottom of the menu

Test data

None

Expected result

The open menu sits on a solid background above all page content, and every menu item is fully readable and tappable.


Actual result

The "Hyundai Promise" item is partly covered by a car image from the page below, and page content continues directly under the menu.

Oracle (why this is a bug)

Usability heuristic: an open navigation menu must be fully visible and usable. The desktop menu has a solid panel, so the mobile behaviour is inconsistent.

Screenshots



BUG-004 — Screenshot 1

BUG-005: "Find a Dealer" is missing from the mobile menu

Bug ID	BUG-005
Title	"Find a Dealer" is missing from the mobile menu
Module / feature	Navigation – mobile menu
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Mobile Device Testing, Navigation Testing, Cross-Platform / OS Compatibility Testing, Checklist-Based Testing
Reproducibility	Always

Description

The desktop main menu has seven items, including Find a Dealer. The mobile menu shows only six: Find a Car, After Sales, Hyundai Pakistan, Press Release, Hyundai Easy Own and Hyundai Promise.

Preconditions

Website opened at a mobile screen width

Steps to reproduce

1. Open https://hyundai-nishat.com on desktop and note the main menu items
2. Switch to a mobile width and tap the menu icon (☰)
3. Compare the two lists

Test data

None

Expected result

The mobile menu offers the same main sections as desktop, including Find a Dealer.


Actual result

Find a Dealer does not appear in the mobile menu.

Oracle (why this is a bug)

Consistency oracle: the desktop menu is the specification of the site's main sections. Finding a dealer is a key task for car buyers, and many of them browse on phones.

Screenshots



BUG-005 — Screenshot 1

BUG-006: Extended Warranty breadcrumb skips the "After Sales" level

Bug ID	BUG-006
Title	Extended Warranty breadcrumb skips the "After Sales" level
Module / feature	Extended Warranty page – breadcrumb
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Navigation Testing, Checklist-Based Testing, GUI Testing
Reproducibility	Always

Description

The Extended Warranty page's breadcrumb reads "Home > Extended Warranty", although the page sits under After Sales in the menu.

Preconditions

None

Steps to reproduce

1. Open After Sales > Extended Warranty
2. Read the breadcrumb under the menu
3. Open After Sales > Owner's Manual and compare its breadcrumb

Test data

None

Expected result

Home > After Sales > Extended Warranty


Actual result

Home > Extended Warranty

Oracle (why this is a bug)

Consistency oracle: Owner's Manual, also under After Sales, shows "Home > After Sales > Owner's Manual". Breadcrumbs should reflect the site hierarchy.

Screenshots



BUG-006 — Screenshot 1

BUG-007: Stray backtick instead of an apostrophe in "HNMPL ` s warranty"

Bug ID	BUG-007
Title	Stray backtick instead of an apostrophe in "HNMPL ` s warranty"
Module / feature	Extended Warranty page – content
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The opening paragraph of the Extended Warranty page reads "backed by HNMPL ` s warranty coverage", with a backtick surrounded by spaces.

Preconditions

None

Steps to reproduce

1. Open After Sales > Extended Warranty
2. Read the first bold paragraph below the warranty badge

Test data

None

Expected result

"backed by HNMPL's warranty coverage"

Actual result

"backed by HNMPL ` s warranty coverage"

Oracle (why this is a bug)

Standard English punctuation for the possessive. The error is in the page's main promotional sentence, so it affects the brand's credibility.

Screenshots

With competitive pricing and extended warranty coverage, Hyundai customers can now drive confidently into the 5th year, knowing they are backed by HNMPL ` s warranty coverage every mile of the way.

Enjoy peace of mind with Hyundai Extended Warranty

- As low as PKR 55,000
- Protects your vehicle from unexpected repair costs
- Provides authorized service charges
- Offers up to125,000 KM / 5 Years Warranty

BUG-007 — Screenshot 1

BUG-008: Missing space in "up to125,000 KM"

Bug ID	BUG-008
Title	Missing space in "up to125,000 KM"
Module / feature	Extended Warranty page – content
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The last benefit bullet on the Extended Warranty page reads "Offers up to125,000 KM / 5 Years Warranty".

Preconditions

None

Steps to reproduce

1. Open After Sales > Extended Warranty
2. Read the bullet list under "Enjoy peace of mind with Hyundai Extended Warranty"

Test data

None

Expected result

"Offers up to 125,000 KM / 5 Years Warranty"


Actual result

"Offers up to125,000 KM / 5 Years Warranty"

Oracle (why this is a bug)

Standard typography: a space separates a word from the number that follows it.

Screenshots



BUG-008 — Screenshot 1

BUG-009: Vehicle line-up differs between the home page and the Owner's Manual page

Bug ID	BUG-009
Title	Vehicle line-up differs between the home page and the Owner's Manual page
Module / feature	Home page vehicles vs Owner's Manual
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Data Integrity Testing, Business Rule Testing, Exploratory Testing
Reproducibility	Always

Description

The home page lists "SANTA FE HYBRID" and no plain Tucson. The Owner's Manual page lists "SANTA FE" (not hybrid) and adds a separate "TUCSON". The two pages disagree on which models Hyundai Nishat offers.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com and scroll to the Vehicles section
2. Note the model names
3. Open After Sales > Owner's Manual and compare the model names

Test data

None

Expected result

Both pages list the same models with the same names, or the Owner's Manual clearly marks discontinued models.


Actual result

Home: Elantra 1.6 Special Edition, Elantra Hybrid, Sonata, Sonata N Line, Tucson Hybrid, Santa Fe Hybrid, Palisade Hybrid, IONIQ 5, IONIQ 6, Porter H-100 (10 models). Owner's Manual: adds "TUCSON" and names "SANTA FE" instead of "SANTA FE HYBRID" (11 models).


Oracle (why this is a bug)

Data integrity oracle: the same product data should match across pages. A Santa Fe Hybrid owner may download the wrong manual, and customers get conflicting information about which models are sold.

Screenshots



BUG-009 — Screenshot 1



BUG-009 — Screenshot 2

BUG-010: "Trending around you" tiles cut their captions off mid-sentence

Bug ID	BUG-010
Title	"Trending around you" tiles cut their captions off mid-sentence
Module / feature	Home page – Trending around you
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	GUI Testing, Layout and Alignment Testing, Content and Spelling Testing
Reproducibility	Always

Description

Captions at the bottom of the promotional tiles are truncated, for example "Bring home the SANTA FE Hybrid and" and "Choose the TUCSON Hybrid and", with no ellipsis or way to read the rest.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Scroll to "Trending around you"
3. Read the captions at the bottom of the second and third tiles

Test data

None

Expected result

Each caption is shown in full, or ends with an ellipsis and the tile links to the full offer.


Actual result

Captions stop mid-sentence and the rest of the text is hidden.

Oracle (why this is a bug)

Usability heuristic: text must not be clipped without an indication. The captions carry the offer details, so users miss the key information.

Screenshots



BUG-010 — Screenshot 1

BUG-011: Home page banner still promotes the "TUCSON Hybrid 2025"

Bug ID	BUG-011
Title	Home page banner still promotes the "TUCSON Hybrid 2025"
Module / feature	Home page – hero banner
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Business Rule Testing, Exploratory Testing
Reproducibility	Always

Description

The main home page carousel shows "The all-new Hyundai TUCSON Hybrid 2025" in November 2026.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Watch the hero carousel until the TUCSON Hybrid slide appears

Test data

None

Expected result

Banners promote current model-year vehicles, or omit the year.


Actual result

The slide calls a 2025 model "all-new" in late 2026.

Oracle (why this is a bug)

Currency of content: the site footer says "Copyright 2026", and an "all-new" claim for a previous model year is outdated marketing.

Screenshots



BUG-011 — Screenshot 1

BUG-012: Owner's Manual download buttons misaligned in the first row

Bug ID	BUG-012
Title	Owner's Manual download buttons misaligned in the first row
Module / feature	Owner's Manual page – layout
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Layout and Alignment Testing, GUI Testing, Visual Regression Testing
Reproducibility	Always

Description

"ELANTRA 1.6 SPECIAL EDITION" wraps onto two lines, which pushes its Download button lower than the Download buttons of the other three vehicles in the same row.

Preconditions

None

Steps to reproduce

1. Open After Sales > Owner's Manual on a 1920×1080 screen
2. Look at the first row of vehicles

Test data

None

Expected result

All Download buttons in a row line up horizontally, whatever the length of the model name.

Actual result

The first Download button sits about one line lower than the other three.

Oracle (why this is a bug)

Visual consistency in a grid layout. Every other row on the page is aligned, so this row is the exception.

Screenshots



BUG-012 — Screenshot 1

BUG-013: Name field accepts digits only ("12345") without any validation error

Bug ID	BUG-013
Title	Name field accepts digits only ("12345") without any validation error
Module / feature	Book a Service form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Input Validation Testing, Negative Testing, Equivalence Partitioning, Special Character Testing
Reproducibility	Always

Description

The required Name field accepts a value made only of numbers. On submit, every other empty field shows an error, but Name shows none, so a booking can carry an invalid customer name.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/ (After Sales > Service Appointment)
2. Type 12345 in the Name field
3. Leave the other fields empty and click Submit
4. Look at the message under Name

Test data

Name: 12345

Expected result

An error such as "Please enter a valid name (letters only)" under the Name field.


Actual result

No error under Name; the value 12345 is accepted as a name.

Oracle (why this is a bug)

A personal name belongs to the equivalence class of alphabetic text. Digits-only input is an invalid class and should be rejected, as the form already validates other fields.

Screenshots



BUG-013 — Screenshot 1

BUG-014: Required drop-down fields show no error when left empty

Bug ID	BUG-014
Title	Required drop-down fields show no error when left empty
Module / feature	Book a Service form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Required Field Testing, Error Message Testing, Error Handling Testing, Decision Table Testing
Reproducibility	Always

Description

Model, Model Name, Service type, City and Dealer name are all marked required (*). When the form is submitted with them empty, text fields show "Please fill out this field" but none of these five drop-downs shows any message.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/ (After Sales > Service Appointment)
2. Leave every field empty (or fill only Name)
3. Click Submit
4. Compare the messages under text fields with those under the drop-downs

Test data

All drop-downs left on "Select"

Expected result

Each empty required drop-down shows "Please fill out this field", like the text fields.


Actual result

Only a general banner, "One or more fields have an error", appears. The five drop-downs show no message, so the user cannot tell they still need filling.

Oracle (why this is a bug)

Consistency oracle: the form marks these fields with * and validates other required fields inline. Usability guidance (WCAG 3.3.1 Error Identification) says the field in error must be identified to the user.

Screenshots



BUG-014 — Screenshot 1

BUG-015: Form section is headed "Salutation" but contains no salutation field

Bug ID	BUG-015
Title	Form section is headed "Salutation" but contains no salutation field
Module / feature	Book a Service form
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Usability Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The heading above the booking fields reads "Salutation", which means a title such as Mr or Ms. The section holds contact, vehicle and appointment details and has no salutation field. The Request a Test Drive form uses the same "Salutation" heading above its Vehicle, City and Dealer fields.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/ (After Sales > Service Appointment)
2. Scroll to the start of the form
3. Read the section heading and the fields below it

Test data

None

Expected result

A heading that describes the section, such as "Your details" or "Appointment details", or a real Salutation (Mr/Ms) field.


Actual result

The heading "Salutation" sits above fields that have nothing to do with a salutation.

Oracle (why this is a bug)

Label accuracy: a heading must describe its content. The mismatch suggests a template heading left unchanged.

Screenshots



Salutation Required fields *

BUG-015 — Screenshot 1

BUG-016: Grammar error in the page subtitle: "Hyundai provide you with booking service"

Bug ID	BUG-016
Title	Grammar error in the page subtitle: "Hyundai provide you with booking service"
Module / feature	Book a Service form
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The subtitle under "Book a Service" reads "Hyundai provide you with booking service for your valuable time."

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/ (After Sales > Service Appointment)
2. Read the subtitle under the "Book a Service" heading

Test data

None

Expected result

"Hyundai provides you with a booking service to save your valuable time."


Actual result

"Hyundai provide you with booking service for your valuable time."

Oracle (why this is a bug)

English grammar: a singular subject (Hyundai) takes "provides", and "booking service" needs an article.

Screenshots



Salutation Required fields *

BUG-016 — Screenshot 1

BUG-017: Unit written as "Odometer (KM's)" with a wrong apostrophe

Bug ID	BUG-017
Title	Unit written as "Odometer (KM's)" with a wrong apostrophe
Module / feature	Book a Service form
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Content and Spelling Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The Odometer label and placeholder both read "Odometer (KM's)".

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/ (After Sales > Service Appointment)
2. Find the Odometer field in the form

Test data

None

Expected result

"Odometer (km)"


Actual result

"Odometer (KM's)" in both the label and the placeholder.

Oracle (why this is a bug)

SI unit style: the kilometre symbol is "km", and unit symbols take no plural or apostrophe.

Screenshots



BUG-017 — Screenshot 1

BUG-018: Comments field is mandatory for a service booking

Bug ID	BUG-018
Title	Comments field is mandatory for a service booking
Module / feature	Book a Service form
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Usability Testing, Business Rule Testing, Required Field Testing
Reproducibility	Always

Description

"Comments (max 2,000 characters)" is marked required, and the form cannot be submitted without typing something in it.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/ (After Sales > Service Appointment)
2. Fill every field except Comments
3. Click Submit

Test data

Comments: empty

Expected result

Comments are optional; a routine service can be booked without writing a note.


Actual result

"Please fill out this field" appears under Comments and the booking is blocked.

Oracle (why this is a bug)

Form usability practice: free-text notes should be optional. Forcing them adds effort and leads to filler text such as "none" in bookings.

Screenshots



BUG-018 — Screenshot 1

BUG-019: VIN field placeholder shows a realistic VIN that looks pre-filled

Bug ID	BUG-019
Title	VIN field placeholder shows a realistic VIN that looks pre-filled
Module / feature	Book a Service form
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Usability Testing, GUI Testing, Error Guessing
Reproducibility	Always

Description

The optional VIN number field shows "MALAA02HR4M123456" in grey. It looks like an already-entered value rather than an example.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/ (After Sales > Service Appointment)
2. Look at the empty VIN number field

Test data

None

Expected result

A clearly marked hint, such as "e.g. MALAA02HR4M123456" or "17-character VIN".


Actual result

A full, realistic VIN is shown as the placeholder with no "e.g.".

Oracle (why this is a bug)

Placeholder guidance (Nielsen Norman Group): placeholders that look like real data are mistaken for filled fields. Users may skip it or think the site already knows their car.

Screenshots



BUG-019 — Screenshot 1

BUG-020: Invalid email "abc@" gives a misleading message: "Please enter an email address"

Bug ID	BUG-020
Title	Invalid email "abc@" gives a misleading message: "Please enter an email address"
Module / feature	Book a Service form
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Error Message Testing, Input Validation Testing, Boundary Value Analysis, Negative Testing
Reproducibility	Always

Description

When the Email field contains an incomplete address such as "abc@", the form says "Please enter an email address", as if the field were empty. The message only appears after Submit is clicked, not when the user leaves the field. The same message appears on the Request a Test Drive form.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/
2. Type abc@ in the Email field and click into the next field
3. Click Submit and read the message under Email

Test data

Email: abc@

Expected result

A specific message such as "Please enter a valid email address (e.g. name@example.com)", shown as soon as the user leaves the field.


Actual result

No message when leaving the field. After Submit: "Please enter an email address.", although an address was entered.

Oracle (why this is a bug)

Error-message guidelines (WCAG 3.3.3 Error Suggestion): a message should say what is wrong and how to fix it. "Enter an email address" is wrong for a field that already holds text.

Screenshots



BUG-020 — Screenshot 1

BUG-021: "Model Name" does not depend on "Model": it lists model names and can be chosen while Model is empty

Bug ID	BUG-021
Title	"Model Name" does not depend on "Model": it lists model names and can be chosen while Model is empty
Module / feature	Book a Service form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	State Transition Testing, Cause-Effect Graphing, Integration Testing, Decision Table Testing
Reproducibility	Always

Description

Model and Model Name should work as a pair (choose a model, then its version). Instead, Model Name repeats a list of models (Elantra, Sonata, Tucson, Porter, Starex, Staria, Santa Fe, Ioniq, Other) and can be filled while Model is still "Select".

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/
2. Leave Model on "Select"
3. Open the Model Name drop-down and pick Staria

Test data

Model: empty; Model Name: Staria

Expected result

Model Name stays disabled until a Model is chosen, then lists only that model's versions (for example Elantra → 1.6 Special Edition, Hybrid).


Actual result

Model Name is enabled with Model empty, offers model names rather than versions, and accepts Staria while Model shows nothing.

Oracle (why this is a bug)

Dependent-field logic (cause-effect): a child field should only accept values valid for its parent. Two fields asking the same question, with no link, let users send contradictory data.

Screenshots



BUG-021 — Screenshot 1



BUG-021 — Screenshot 2

BUG-022: Model list does not match the current line-up: Palisade missing, Starex and Staria listed

Bug ID	BUG-022
Title	Model list does not match the current line-up: Palisade missing, Starex and Staria listed
Module / feature	Book a Service form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Data Integrity Testing, Business Rule Testing, Equivalence Partitioning
Reproducibility	Always

Description

The service form's model list offers Starex and Staria, which appear nowhere else on the site, and has no Palisade, which is sold on the site (Palisade Hybrid). IONIQ 5 and IONIQ 6 are merged into one "Ioniq" entry.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/
2. Open the Model Name drop-down
3. Compare it with the Vehicles section on the home page

Test data

None

Expected result

The list covers every model the dealer services, including all current models such as Palisade Hybrid, with the same names as the rest of the site.


Actual result

Palisade is missing; Starex and Staria are listed; IONIQ 5/6 appear only as "Ioniq".

Oracle (why this is a bug)

Data integrity oracle: the home page and Owner's Manual list Palisade Hybrid, IONIQ 5 and IONIQ 6 as current models. A Palisade owner cannot correctly book a service.

Screenshots



BUG-022 — Screenshot 1

BUG-023: Service appointment time allows any 15-minute slot from 00:00 to 23:45

Bug ID	BUG-023
Title	Service appointment time allows any 15-minute slot from 00:00 to 23:45
Module / feature	Book a Service form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Boundary Value Analysis, Business Rule Testing, Date and Time Testing
Reproducibility	Always

Description

The time picker offers all 96 slots of the day, including night times such as 03:00, with no link to dealership working hours.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/
2. Click the Service appointment time field
3. Scroll through the offered times

Test data

Time: 03:00 and 04:45

Expected result

Only slots within dealership working hours (for example 09:00 to 17:00) can be chosen.

Actual result

All 96 slots from 00:00 to 23:45 are offered in 15-minute steps, and night times such as 04:45 and 20:00 are accepted in the field (screenshots cover the whole list).


Oracle (why this is a bug)

Business rule oracle: service centres do not work at night. Accepting a 03:00 booking creates appointments the dealer cannot honour.

Screenshots



BUG-023 — Screenshot 1



BUG-023 — Screenshot 2

BUG-024: Dealer list is not filtered by the selected City

Bug ID	BUG-024
Title	Dealer list is not filtered by the selected City
Module / feature	Book a Service form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Integration Testing, Cause-Effect Graphing, Decision Table Testing
Reproducibility	Always

Description

Dealer name shows every dealer in Pakistan (Chakwal, DG Khan, Gujranwala, Islamabad, Karachi, Lahore, Quetta, Sargodha and more) regardless of the City field.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/
2. Leave City on "Select City" (or choose a city)
3. Open the Dealer name drop-down

Test data

City: not selected / any city

Expected result

Dealer name is disabled until a city is chosen, then lists only that city's dealers.


Actual result

All dealers nationwide are listed, so a user can pick a city and a dealer in a different city.

Oracle (why this is a bug)

Dependent-field logic: the form asks for City first, which only makes sense if it narrows the dealer list. Mismatched city and dealer leads to wrong bookings.

Screenshots



BUG-024 — Screenshot 1

BUG-025: Dealer names do not show their location ("Hyundai-South", "Hyundai-Premium", "Hyundai-Central")

Bug ID	BUG-025
Title	Dealer names do not show their location ("Hyundai-South", "Hyundai-Premium", "Hyundai-Central")
Module / feature	Book a Service form
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Usability Testing, Content and Spelling Testing
Reproducibility	Always

Description

Many dealers are listed by internal names that give no city or area, for example Hyundai-South, Hyundai-Highway, Hyundai-Central, Hyundai-Premium, Hyundai-Eastern and Hyundai-Metropolitan. Naming is also inconsistent: "Hyundai-City-Store-Karachi" and "Hyundai-City-Store" both appear.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/
2. Open the Dealer name drop-down
3. Read the dealer names

Test data

None

Expected result

Each dealer shows its city and area, for example "Hyundai Central – Lahore".


Actual result

Hyphenated internal names with no location, and two similar "City-Store" entries.

Oracle (why this is a bug)

Usability heuristic (match between system and real world): customers choose a dealer by location, which these labels do not give.

Screenshots



BUG-025 — Screenshot 1

BUG-026: Test Drive form also accepts digits only ("12345") as Full Name

Bug ID	BUG-026
Title	Test Drive form also accepts digits only ("12345") as Full Name
Module / feature	Request a Test Drive form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Input Validation Testing, Negative Testing, Equivalence Partitioning, Regression Testing
Reproducibility	Always

Description

The same name-validation gap as BUG-013 exists on a second form: Full Name accepts "12345" and shows no error, while other fields are flagged.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/request-a-test-drive/ (home page > Request a Test Drive)
2. Type 12345 in Full Name and abc@ in Email
3. Click Submit
4. Look under Full Name

Test data

Full Name: 12345

Expected result

"Please enter a valid name" under Full Name.


Actual result

No error under Full Name.

Oracle (why this is a bug)

Equivalence partitioning: digits-only is an invalid class for a person's name. Finding the defect on a second form shows it is a site-wide validation gap, not a one-off.

Screenshots



BUG-026 — Screenshot 1

BUG-027: Required "Vehicle" and "Salutation" show no error when empty, although City and Dealer Name do

Bug ID	BUG-027
Title	Required "Vehicle" and "Salutation" show no error when empty, although City and Dealer Name do
Module / feature	Request a Test Drive form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Required Field Testing, Error Message Testing, Decision Table Testing
Reproducibility	Always

Description

On submit with empty drop-downs, City and Dealer Name show "Please fill out this field", but Vehicle and Salutation, also marked required (*), show nothing.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/request-a-test-drive/ (home page > Request a Test Drive)
2. Leave all drop-downs on "Select"
3. Fill Full Name and Email with any text
4. Click Submit

Test data

All drop-downs empty

Expected result

Every empty required drop-down shows "Please fill out this field".


Actual result

Errors appear under City and Dealer Name only; Vehicle and Salutation stay unmarked. Only the general banner hints at a problem.

Oracle (why this is a bug)

Consistency within the same form: two required drop-downs are validated and two are not. WCAG 3.3.1 requires the field in error to be identified.

Screenshots



BUG-027 — Screenshot 1

BUG-028: Consent text contains an unfilled template blank ("Order**No: ……") and refers to a Vehicle Sales Order

Bug ID	BUG-028
Title	Consent text contains an unfilled template blank ("Order**No:…….. ……") and refers to a Vehicle Sales Order
Module / feature	Request a Test Drive form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Static Testing (Reviews), Content and Spelling Testing, Business Rule Testing
Reproducibility	Always

Description

The Terms & Agreement users must accept says data comes "through the Vehicle Sales Order / Retail Customer Order**No:……("the Order Form")". The order-number blank was never filled, and a test-drive request has no sales order. The company name is also written both "(private)" and "(Private)".

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/request-a-test-drive/ (home page > Request a Test Drive)
2. Scroll to "Disclose Personal Data/Information"
3. Read paragraph 1.2 of Terms & Agreement

Test data

None

Expected result

Consent text written for an online test-drive request, with no unfilled blanks and the company name spelled consistently.


Actual result

Paragraph 1.2 contains "Order**No:……" copied from a paper sales-order form; the company appears as both "(private)" and "(Private)".

Oracle (why this is a bug)

Legal text that users consent to must be accurate and complete. Pakistan's data protection practice and general privacy principles require consent to be informed; a template with blanks for another document does not describe this form's processing.

Screenshots



BUG-028 — Screenshot 1

BUG-029: Salutation list offers only Mr., Mrs. and Other: no Ms. or Miss

Bug ID	BUG-029
Title	Salutation list offers only Mr., Mrs. and Other: no Ms. or Miss
Module / feature	Request a Test Drive form
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Usability Testing, Equivalence Partitioning, Checklist-Based Testing
Reproducibility	Always

Description

The required Salutation drop-down lists Mr., Mrs. and Other. Unmarried women, or women who don't use a marital title, have no option except "Other".

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/request-a-test-drive/ (home page > Request a Test Drive)
2. Open the Salutation drop-down

Test data

None

Expected result

At least Mr., Mrs., Ms. and Miss (and optionally Dr.).

Actual result

Only Mr., Mrs. and Other.

Oracle (why this is a bug)

Standard form design practice and common salutation sets include Ms./Miss. Equivalence partitioning of users shows a whole group with no matching value.

Screenshots



BUG-029 — Screenshot 1

BUG-030: Page promises a test drive "appointment" but the form has no date or time field

Bug ID	BUG-030
Title	Page promises a test drive "appointment" but the form has no date or time field
Module / feature	Request a Test Drive form
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Use Case Testing, Business Rule Testing, Scenario-Based Testing
Reproducibility	Always

Description

The subtitle says "request a test drive appointment", but the form only collects vehicle, city, dealer and contact details. There is no way to choose a preferred date or time.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/request-a-test-drive/ (home page > Request a Test Drive)
2. Read the subtitle under "Request a Test Drive"
3. Look through the form for a date or time field

Test data

None

Expected result

A preferred date and time field, as on the Book a Service form, or wording that says the dealer will call to arrange a time.


Actual result


No date or time field; the user cannot say when they want the test drive.

Oracle (why this is a bug)

Use-case oracle: an appointment needs a time. The site's own Book a Service form asks for date and time, so this form is inconsistent with it.

Screenshots





BUG-030 — Screenshot 1

BUG-031: "Vehicle*" label has no space before the asterisk, unlike every other label

Bug ID	BUG-031
Title	"Vehicle*" label has no space before the asterisk, unlike every other label
Module / feature	Request a Test Drive form
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	GUI Testing, Typography and Font Consistency Testing, Visual Regression Testing
Reproducibility	Always

Description

The first label reads "Vehicle*", while all other required labels have a space before the asterisk ("City *", "Dealer Name *").

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/request-a-test-drive/ (home page > Request a Test Drive)
2. Look at the labels on the left of the form

Test data

None

Expected result

"Vehicle *", formatted like the other labels.

Actual result

"Vehicle*" with no space.

Oracle (why this is a bug)

Visual consistency: labels in one form should follow the same format.

Screenshots



BUG-031 — Screenshot 1

BUG-032: Reset button has a colour contrast of 1.6:1 and looks disabled

Bug ID	BUG-032
Title	Reset button has a colour contrast of 1.6:1 and looks disabled
Module / feature	Book a Service form
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Accessibility Testing, Colour Contrast Testing, GUI Testing
Reproducibility	Always

Description

The Reset button uses white text on a light grey background (#CCCCCC). Measured from the screenshot, the contrast ratio is 1.61:1, far below the 4.5:1 minimum. The button looks greyed out, so users cannot tell it works.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com/book-a-service/
2. Scroll to the Submit and Reset buttons
3. Measure the Reset button's text and background colours (e.g. with Chrome DevTools or a contrast checker)

Test data

Text #FFFFFF on background #CCCCCC

Expected result

Button text with at least 4.5:1 contrast, styled as an active secondary button.

Actual result

Contrast 1.61:1; the button looks disabled although it is active.

Oracle (why this is a bug)

WCAG 2.1 Success Criterion 1.4.3 (Contrast, Minimum, Level AA) requires 4.5:1 for normal text.

Screenshots



BUG-032 — Screenshot 1

BUG-033: Footer links and copyright text fail contrast: grey #676767 on black (3.7:1)

Bug ID	BUG-033
Title	Footer links and copyright text fail contrast: grey #676767 on black (3.7:1)
Module / feature	Site-wide footer
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Accessibility Testing, Colour Contrast Testing
Reproducibility	Always

Description

The footer's links (Worldwide, Contact Us, Legal Disclaimer, Cookie Policy, Sitemap, myHyundai) and the copyright line are grey #676767 on black. The measured ratio is 3.71:1, and the text is small.

Preconditions

None

Steps to reproduce

1. Open any page on https://hyundai-nishat.com
2. Scroll to the footer
3. Check the text and background colours with a contrast checker

Test data

Text #676767 on background #000000

Expected result

At least 4.5:1 contrast for small footer text.


Actual result

3.71:1 contrast for links and copyright text.

Oracle (why this is a bug)

WCAG 2.1 SC 1.4.3 requires 4.5:1 for text smaller than 18 pt (14 pt bold). The footer holds legal links users must be able to read.

Screenshots



BUG-033 — Screenshot 1

BUG-034: The same page is called four different names: "Service Appointment", "Service Appointment Request", "Book a Service" and "Book a Hyundai Service"

Bug ID	BUG-034
Title	The same page is called four different names: "Service Appointment", "Service Appointment Request", "Book a Service" and "Book a Hyundai Service"
Module / feature	Book a Service and Request a Test Drive pages
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Navigation Testing, Content and Spelling Testing, Checklist-Based Testing
Reproducibility	Always

Description

The service booking page is "Service Appointment" in the menu, "Service Appointment Request" in the breadcrumb, "Book a Service" as the heading and "Book a Hyundai Service | Online…" in the browser tab. The test-drive page is likewise "Request a Test Drive" on the page but "Book a Hyundai Test Drive" in the tab.

Preconditions

None

Steps to reproduce

1. Open After Sales > Service Appointment
2. Compare the menu item, browser tab title, breadcrumb and page heading
3. Repeat for Request a Test Drive

Test data

None

Expected result

One name per page, used in the menu, tab title, breadcrumb and heading.


Actual result

Four names for the service page and two for the test-drive page.

Oracle (why this is a bug)

Usability heuristic (consistency and standards): users and search engines rely on matching labels to confirm they reached the right page.

Screenshots



BUG-034 — Screenshot 1

BUG-035: "Request a Brochure" has no request form: the page is a plain download list

Bug ID	BUG-035
Title	"Request a Brochure" has no request form: the page is a plain download list
Module / feature	Request a Brochure page
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Use Case Testing, Navigation Testing, Content and Spelling Testing
Reproducibility	Always

Description

The home-page button and page title say "Request a Brochure", which suggests a form where the user asks for a brochure. The page only lists vehicles with Download links. The capitalisation also changes from "Request a Brochure" on the button to "Request a brochure" on the page.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Click "Request a Brochure" in the blue bar under the banner
3. Look for a form on the page

Test data

None

Expected result

Either a request form (as with Request a Test Drive), or a label that matches what the page does, such as "Download a Brochure", with consistent capitalisation.


Actual result

No form; only Download links. Button says "Request a Brochure", page says "Request a brochure".

Oracle (why this is a bug)

Label accuracy: the action name should describe what happens. The sister pages "Request a Test Drive" and Book a Service both contain forms, so users expect one here.

Screenshots



BUG-035 — Screenshot 1

BUG-036: Brochure grid misaligned in two rows (Elantra 1.6 Special Edition and Santa Fe Hybrid)

Bug ID	BUG-036
Title	Brochure grid misaligned in two rows (Elantra 1.6 Special Edition and Santa Fe Hybrid)
Module / feature	Request a Brochure page
Severity	**Low**
Priority	P4
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Layout and Alignment Testing, Visual Regression Testing, GUI Testing
Reproducibility	Always

Description

In row 1 the long name "ELANTRA 1.6 SPECIAL EDITION" wraps and pushes its Download link down (as on the Owner's Manual page, BUG-012). In row 2 the Santa Fe Hybrid image is shorter, so its name and Download link sit higher than the other three.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Click "Request a Brochure" in the blue bar under the banner
3. Look at the first two rows of vehicles

Test data

None

Expected result

All names and Download links in a row line up.


Actual result

Row 1: Elantra's Download is lower; row 2: Santa Fe Hybrid's name and Download are higher than the rest.

Oracle (why this is a bug)

Visual consistency in a grid. The same component misaligns on two pages, which points to a shared template defect.

Screenshots



BUG-036 — Screenshot 1

BUG-037: Owner's Manual downloads (17–76 MB) start immediately, with no file size shown and no preview

Bug ID	BUG-037
Title	Owner's Manual downloads (17–76 MB) start immediately, with no file size shown and no preview
Module / feature	Owner's Manual – downloads
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Performance Testing, Volume Testing, Usability Testing, Low Bandwidth / Network Throttling Testing
Reproducibility	Always

Description

Clicking Download on the Owner's Manual page downloads the PDF straight away. The files are very large and the page shows no size: Porter H-100 76.4 MB (272 pages), Elantra 1.6 SE 55.1 MB (573 pages), Tucson Hybrid 30.7 MB (754 pages), IONIQ 5 17.0 MB (703 pages). Unlike the brochure links, which open in a browser tab, there is no preview.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Go to After Sales > Owner's Manual
3. Click Download under ELANTRA 1.6 SPECIAL EDITION
4. Watch what the browser does

Test data

Porter_H-100-Owner-Manual.pdf 76,448,008 bytes; Elantra-1_6-SE-Owners-Manual.pdf 55,103,375 bytes; NX4-Hybrid-G1.6T-GDi.pdf 30,702,562 bytes; Ioniq-5-Owner-Manual.pdf 16,995,996 bytes

Expected result

The link shows the file type and size (e.g. "PDF, 55 MB") and opens the same way as the brochure links, or offers a preview or chapter-wise download.


Actual result

Files of up to 76 MB download at once with no size shown; the brochure page's links behave differently (open in a tab).

Oracle (why this is a bug)

Usability and performance practice: large downloads should state their size, especially for mobile users on metered data. Consistency oracle: download links on the two pages behave differently.

Screenshots



BUG-037 — Screenshot 1

BUG-038: Elantra and Porter manuals are scanned images: text cannot be searched, selected or read by screen readers

Bug ID	BUG-038
Title	Elantra and Porter manuals are scanned images: text cannot be searched, selected or read by screen readers
Module / feature	Owner's Manual – downloads
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Accessibility Testing, Static Testing (Reviews), Usability Testing
Reproducibility	Always

Description

The Elantra 1.6 SE manual (573 pages) has no text layer at all, and the Porter H-100 manual (272 pages, passed through the free online tool iLovePDF) is almost entirely page images. Ctrl+F finds nothing, text cannot be copied, and screen readers cannot read them.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Go to After Sales > Owner's Manual
3. Click Download under ELANTRA 1.6 SPECIAL EDITION
4. Open the downloaded PDF
5. Press Ctrl+F and search for a word visible on the page, such as "CAUTION"

Test data

Search term: CAUTION

Expected result

A text-based PDF, or one with OCR, so owners can search a 573-page manual for a topic.


Actual result


Search finds no results on any page; the file contains only page images.

Oracle (why this is a bug)

WCAG 2.1 SC 1.1.1 (Non-text Content) and PDF accessibility practice (PDF/UA) require real text. A 573-page reference document that cannot be searched defeats its purpose.

Screenshots





FOREWORD

Congratulations, and thank you for choosing HYUNDAI.We are pleased to welcome you to the growing number of discerning people who drive HYUNDAIs.We are very proud of the advanced engineering and high-quality construction of each HYUNDAI we build.

Your Owner's Manual will introduce you to the features and operation of your new HYUNDAI. To become familiar with your new HYUNDAI, so that you can fully enjoy it, read this Owner's Manual carefully before driving your new vehicle.

This manual contains important safety information and instructions intended to familiarize you with your vehicle's controls and safety features so you can safely operate your vehicle.

This manual also contains information on maintenance designed to enhance safe operation of the vehicle. It is recommended that all service and maintenance on your car be performed by an authorized HYUNDAI dealer. HYUNDAI dealers are prepared to provide high-quality service, maintenance and any other assistance that may be required.

This Owner's Manual should be considered a permanent part of your vehicle, and should be kept in the vehicle so you can refer to it at any time. The manual should stay with the vehicle if you sell it to provide the next owner with important operating, safety and maintenance information.

HYUNDAI MOTOR COMPANY

CAUTION

Severe engine and transaxle damage may result from the use of poor quality fuels and lubricants that do not meet HYUNDAI specifications. You must always use high quality fuels and lubricants that meet the specifications listed on Page 8-6 in the Vehicle Specifications section of the Owner's Manual.

Copyright 2020 HYUNDAI Motor Company. All rights reserved. No part of this publication may be reproduced, stored in any retrieval system or transmitted in any form or by any means without the prior written permission of HYUNDAI Motor Company.

F4

BUG-038 — Screenshot 1

BUG-039: Owner's manuals are generic, dated editions written for left-hand-drive cars (Elantra 2020, IONIQ 5 2022)

Bug ID	BUG-039
Title	Owner's manuals are generic, dated editions written for left-hand-drive cars (Elantra 2020, IONIQ 5 2022)
Module / feature	Owner's Manual – downloads
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Business Rule Testing, Data Integrity Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The manual's cover does not name any model, its copyright is 2020, and the cover warns that "some models are equipped with Right-Hand Drive (RHD). The explanations and illustrations for some operations in RHD models are opposite of those written in this manual." Cars sold in Pakistan are right-hand drive. The IONIQ 5 manual (created 2022) and Tucson Hybrid manual (2024) carry the same left-hand-drive warning on their covers.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Go to After Sales > Owner's Manual
3. Click Download under ELANTRA 1.6 SPECIAL EDITION
4. Open the downloaded PDF
5. Read the cover page and the Foreword (page F4)

Test data

None

Expected result

A manual for the Elantra 1.6 Special Edition as sold in Pakistan: model named, current edition, written for right-hand drive.


Actual result

Generic Hyundai manual, "Copyright 2020", no model named, written for left-hand drive with a note that RHD operations are reversed.

Oracle (why this is a bug)

Data integrity oracle: the link is labelled for a specific 2026 Pakistan model. Pakistan drives on the left with RHD cars, so the manual's instructions and illustrations are mirrored for every local owner.

Screenshots



BUG-039 — Screenshot 1

BUG-040: Tucson Hybrid manual's text layer is corrupted: searching or copying gives gibberish

Bug ID	BUG-040
Title	Tucson Hybrid manual's text layer is corrupted: searching or copying gives gibberish
Module / feature	Owner's Manual – downloads
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Data Integrity Testing, Accessibility Testing, Static Testing (Reviews)
Reproducibility	Always

Description

The Tucson Hybrid manual (downloaded as NX4-Hybrid-G1.6T-GDi.pdf) shows normal text on screen, but its hidden text layer uses a broken font encoding. Copying "OWNER'S MANUAL" gives "2:1(5Ŕ60$18$/", so Ctrl+F cannot find ordinary words in its 754 pages and screen readers read nonsense.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com
2. Go to After Sales > Owner's Manual
3. Click Download under TUCSON HYBRID and open the PDF
4. Select and copy the text "OWNER'S MANUAL" on the cover page and paste it anywhere, or press Ctrl+F and search for "Maintenance"

Test data

Search term: Maintenance

Expected result

Copied text matches what is on the page; searching for "Maintenance" finds the word.


Actual result

Copied text is shifted characters ("Operation" becomes "2SHUDWLRQ"); searching for real words finds nothing.

Oracle (why this is a bug)

PDF accessibility practice (PDF/UA) and WCAG 2.1 SC 1.1.1 require a text layer that matches the visible text. The other manuals on the same page (e.g. IONIQ 5) extract correctly, so this file is defective.

Screenshots



BUG-040 — Screenshot 1

BUG-041: Content-Security-Policy allows 'unsafe-inline' and 'unsafe-eval' scripts, weakening protection against XSS

Bug ID	BUG-041
Title	Content-Security-Policy allows 'unsafe-inline' and 'unsafe-eval' scripts, weakening protection against XSS
Module / feature	Site-wide – HTTP security headers
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Security Headers Testing, Security Testing, Vulnerability Scanning, Cross-Site Scripting (XSS) Testing
Reproducibility	Always

Description

The site sends a Content-Security-Policy, but its script-src includes 'unsafe-inline' and 'unsafe-eval'. These two keywords let inline scripts and eval() run, which removes most of the protection CSP gives against cross-site scripting. securityheaders.com caps the grade because of it. (Found with a passive scan only; no attack was attempted.)

Preconditions

None

Steps to reproduce

1. Open https://securityheaders.com
2. Enter hyundai-nishat.com and click Scan
3. Read the Warnings section and the Content-Security-Policy raw header

Test data

Scan of https://hyundai-nishat.com/ on 8 Nov 2026, 13:31 UTC

Expected result

script-src limited to 'self' and named hosts, using nonces or hashes for inline scripts, with no 'unsafe-inline' or 'unsafe-eval'.


Actual result

script-src 'self' https://www.googletagmanager.com 'unsafe-inline' 'unsafe-eval'; warning: "This policy contains 'unsafe-inline' which is dangerous… 'unsafe-eval' which is dangerous".

Oracle (why this is a bug)

OWASP Content Security Policy Cheat Sheet and the scanner's own warning: unsafe-inline and unsafe-eval defeat CSP's main purpose. Combined with the weak name and comment validation found on the forms (BUG-013, BUG-026), input handling deserves review.

Screenshots



BUG-041 — Screenshot 1

BUG-042: Server header reveals the exact web server version: "Apache/2.4.58 (Ubuntu)"

Bug ID	BUG-042
Title	Server header reveals the exact web server version: "Apache/2.4.58 (Ubuntu)"
Module / feature	Site-wide – HTTP response headers
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	Security Headers Testing, Sensitive Data Exposure Testing, Security Testing
Reproducibility	Always

Description

Every response includes "Server: Apache/2.4.58 (Ubuntu)", telling anyone the web server software, its exact version and the operating system.

Preconditions

None

Steps to reproduce

1. Open https://securityheaders.com and scan hyundai-nishat.com
2. Read the Server row in Raw Headers (or check the Network tab in Chrome DevTools)

Test data

Scan of https://hyundai-nishat.com/ on 8 Nov 2026

Expected result

A generic Server value (e.g. "Apache") or no Server header.


Actual result

Server: Apache/2.4.58 (Ubuntu)

Oracle (why this is a bug)

OWASP guidance on information leakage (fingerprinting): exact version numbers let attackers look up known vulnerabilities for that version. securityheaders.com flags it under Additional Information.

Screenshots



Raw Headers

HTTP/1.1	200 OK
Date	Sun, 08 Nov 2026 13:31:15 GMT
Server	Apache/2.4.58 (Ubuntu)
Strict-Transport-Security	**max-age**=31536000; **includeSubDomains**; **preload**
X-Content-Type-Options	**nosniff**
Referrer-Policy	**no-referrer-when-downgrade**
Permissions-Policy	**geolocation**=(), **microphone**=()
X-Frame-Options	**SAMEORIGIN**
Content-Security-Policy	**default-src** 'self' https:; **script-src** 'self' https://www.googletagmanager.com 'unsafe-inline' 'unsafe-eval'; **style-src** 'self' 'unsafe-inline' https://fonts.googleapis.com; **img-src** 'self' data: https:; **frame-ancestors** 'self';
Last-Modified	Sun, 08 Nov 2026 07:14:02 GMT
Vary	Accept-Encoding
Content-Encoding	gzip
Access-Control-Allow-Origin	https://hyundai-nishat.com
Content-Length	30840
Content-Type	text/html; charset=UTF-8

BUG-042 — Screenshot 1

BUG-043: Second SSL certificate (served to clients without SNI) does not match hyundai-nishat.com and is reported as not trusted

Bug ID	BUG-043
Title	Second SSL certificate (served to clients without SNI) does not match hyundai-nishat.com and is reported as not trusted
Module / feature	Site-wide – HTTPS / SSL
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-1: HP Laptop 15s-fq2xxx (Intel Core i7-1165G7, 8 GB RAM), Windows 11 Home (build 26300, 64-bit), Google Chrome 156.0.8078.81, 1920×1080 at 125% scaling (1536×864 effective), 4G-class connection, ~10 Mbps
Technique(s) used	HTTPS / SSL Testing, Security Testing, Compatibility Testing
Reproducibility	Always

Description

The site scores A+ on SSL Labs and its main certificate is valid. However, the server also presents a second certificate, issued only for www.hyundai-nishat.com, to clients that do not send SNI. For the domain hyundai-nishat.com, SSL Labs marks it "Alternative names … MISMATCH" and "Trusted: No, NOT TRUSTED".

Preconditions

None

Steps to reproduce

1. Open https://www.ssllabs.com/ssltest/
2. Enter hyundai-nishat.com and wait for the report
3. Scroll to the second certificate and read Alternative names and Trusted

Test data

SSL Labs scan, 8 Nov 2026, 13:33 UTC

Expected result

Every certificate the server can present covers both hyundai-nishat.com and www.hyundai-nishat.com.


Actual result


Overall A+, but the second certificate lists only www.hyundai-nishat.com: "MISMATCH" and "NOT TRUSTED" for hyundai-nishat.com.

Oracle (why this is a bug)

Certificate hostname matching (RFC 6125): a certificate must name the host being visited. Older clients that do not support SNI would see a certificate error instead of the site.

Screenshots





BUG-043 — Screenshot 1

BUG-044: Home page is very slow on mobile: Lighthouse Performance 48, main content appears after 25.1 s

Bug ID	BUG-044
Title	Home page is very slow on mobile: Lighthouse Performance 48, main content appears after 25.1 s
Module / feature	Home page – performance
Severity	**High**
Priority	P1
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Performance Testing, Page Load Speed Testing, Low Bandwidth / Network Throttling Testing
Reproducibility	Always (2 of 2 runs)

Description

In a clean Incognito run (no extensions) on mobile, the home page scores 48/100 for Performance. Largest Contentful Paint (when the main content becomes visible) is 25.1 s and Speed Index 5.8 s; the filmstrip shows a blank white screen for the first several frames. Render-blocking requests add about 1.4 s. An earlier run with extensions scored 38 with LCP 19.3 s, so the problem is consistent.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com in Chrome
2. Press F12 and open the Lighthouse tab
3. Select Mobile and all four categories, then click Analyze page load

Test data

Lighthouse 13, mobile, Chrome Incognito, 8 Nov 2026 18:46

Expected result

Performance score of 90+ and Largest Contentful Paint under 2.5 s (Google's "good" threshold).


Actual result

Performance 48; LCP 25.1 s; Speed Index 5.8 s; First Contentful Paint 2.6 s; Total Blocking Time 100 ms.


Oracle (why this is a bug)

Google Core Web Vitals thresholds: LCP ≤ 2.5 s is good, > 4.0 s is poor. At 25.1 s, ten times the target, mobile visitors wait a long time for the page and many will leave.

Screenshots



BUG-044 — Screenshot 1



BUG-044 — Screenshot 2

BUG-045: Page layout jumps while loading: Cumulative Layout Shift 0.367

Bug ID	BUG-045
Title	Page layout jumps while loading: Cumulative Layout Shift 0.367
Module / feature	Home page – performance
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Performance Testing, Visual Regression Testing, Usability Testing
Reproducibility	Always (2 of 2 runs)

Description

As the home page loads, content moves around: Lighthouse lists "layout shift culprits". Cumulative Layout Shift is 0.367 in both runs, including the clean Incognito run, almost four times the 0.1 limit for a good score.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com in Chrome
2. Press F12 and open the Lighthouse tab
3. Select Mobile and all four categories, then click Analyze page load

Test data

Lighthouse mobile run

Expected result

CLS of 0.1 or less, with images and banners given fixed sizes so nothing moves.


Actual result

CLS 0.367; Lighthouse flags layout shift culprits.

Oracle (why this is a bug)

Google Core Web Vitals: CLS ≤ 0.1 is good, > 0.25 is poor. Shifting content makes users tap the wrong element.

Screenshots



BUG-045 — Screenshot 1

BUG-046: Home page downloads 6 MB, with unoptimised images and no long-term caching

Bug ID	BUG-046
Title	Home page downloads 6 MB, with unoptimised images and no long-term caching
Module / feature	Home page – performance
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Performance Testing, Volume Testing, Low Bandwidth / Network Throttling Testing
Reproducibility	Always

Description

Lighthouse reports a total network payload of 6,091 KiB. It estimates savings of 3,233 KiB from better image delivery, 3,858 KiB from proper cache lifetimes, 52 KiB of unused CSS, 29 KiB of unused JavaScript and 16 KiB of legacy JavaScript. JavaScript execution takes 2.2 s and main-thread work 5.7 s.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com in Chrome
2. Press F12 and open the Lighthouse tab
3. Select Mobile and all four categories, then click Analyze page load
4. Expand Insights and Diagnostics

Test data

Lighthouse mobile run

Expected result

A home page well under 2 MB, images served in modern formats at the right size, and static files cached for a long time.


Actual result

6,091 KiB payload; ~3.2 MB of image savings and ~3.9 MB of caching savings available.

Oracle (why this is a bug)

Lighthouse "Avoid enormous network payloads" audit and web performance practice; a 6 MB page is costly and slow on Pakistani mobile data connections.

Screenshots



BUG-046 — Screenshot 1

BUG-047: Accessibility audit failures: unnamed dialog, unnamed links, low contrast and skipped heading levels

Bug ID	BUG-047
Title	Accessibility audit failures: unnamed dialog, unnamed links, low contrast and skipped heading levels
Module / feature	Home page – accessibility
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Accessibility Testing, Screen Reader Testing, Colour Contrast Testing
Reproducibility	Always

Description

Lighthouse Accessibility scores 90 but lists four failed checks: elements with role="dialog" have no accessible name (the booking pop-up), links have no discernible name (icon-only links such as social media), text does not have enough contrast, and headings skip levels.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com in Chrome
2. Press F12 and open the Lighthouse tab
3. Select Mobile and all four categories, then click Analyze page load
4. Scroll to the Accessibility section

Test data

Lighthouse mobile run

Expected result

All four checks pass: dialogs and links have names screen readers can announce, contrast meets 4.5:1, and headings go in order (h1, h2, h3).


Actual result

Four failed accessibility checks.

Oracle (why this is a bug)

WCAG 2.1 SC 4.1.2 (Name, Role, Value), 1.4.3 (Contrast) and 1.3.1 (Info and Relationships). Screen-reader users hear "link" or "dialog" with no description.

Screenshots



BUG-047 — Screenshot 1

BUG-048: Browser errors are logged to the console on the home page

Bug ID	BUG-048
Title	Browser errors are logged to the console on the home page
Module / feature	Home page – JavaScript
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Error Handling Testing, Grey-Box Testing, Performance Testing
Reproducibility	Always

Description

Lighthouse Best Practices (92) fails "Browser errors were logged to the console" and "Issues were logged in the Issues panel in Chrome DevTools".

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com in Chrome
2. Press F12 and open the Lighthouse tab
3. Select Mobile and all four categories, then click Analyze page load
4. Scroll to Best Practices
5. Open the Console tab in DevTools to see the errors

Test data

Lighthouse mobile run

Expected result

No JavaScript errors or DevTools issues on page load.


Actual result

Console errors and DevTools issues are reported.

Oracle (why this is a bug)

Lighthouse Best Practices audit: console errors point to broken scripts or failed requests that can break features silently.

Screenshots



BUG-048 — Screenshot 1

BUG-049: "Booking your Hyundai?" pop-up covers the home page on every visit, even on mobile

Bug ID	BUG-049
Title	"Booking your Hyundai?" pop-up covers the home page on every visit, even on mobile
Module / feature	Home page – pop-up
Severity	**Medium**
Priority	P2
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	Usability Testing, Mobile Device Testing, Static Testing (Reviews), Session Management Testing, Cross-Browser Testing
Reproducibility	Always (Chrome mobile view and Edge desktop)

Description

About one second after the home page loads, a large pop-up about booking documents covers the page. In phone view it hides the banner and most of the screen. The page source shows the pop-up (pum-3109) is set to auto-open after 1,000 ms with no cookie, so it returns on every visit even after being closed. Cross-browser check: the same pop-up opens on desktop in Microsoft Edge (ENV-3), covering the middle of the home page.

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com in phone view (F12, Ctrl+Shift+M)
2. Wait one second
3. Close the pop-up, reload the page

Test data

Pop-up settings in source: "triggers":[{"type":"auto_open","settings":{"cookie_name":"","delay":"1000"}}],"cookies":[]

Expected result

Booking information shown on the booking page, or a pop-up that appears once and is remembered after the user closes it.


Actual result

The pop-up appears on every load and covers most of the mobile screen.


Oracle (why this is a bug)

Google's guidance on intrusive interstitials (pop-ups that cover the main content on mobile hurt usability and search ranking). Usability heuristic: user control and freedom — a dismissed message should stay dismissed.


Screenshots



BUG-049 — Screenshot 1



BUG-049 — Screenshot 2



BUG-049 — Screenshot 3



BUG-049 — Screenshot 4

BUG-050: SEO audit: links without descriptive text and links search engines cannot crawl

Bug ID	BUG-050
Title	SEO audit: links without descriptive text and links search engines cannot crawl
Module / feature	Home page – SEO
Severity	**Low**
Priority	P3
Status	New
Date found	8 Nov 2026
Reported by	Syed Sarim Jawad Zaidi (B22110106080)
Environment	ENV-2: HP Laptop 15s-fq2xxx, Chrome DevTools device emulation, Windows 11 Home (build 26300, 64-bit), Google Chrome 156 (mobile viewport), Mobile viewport, ~375 px wide, 4G-class connection, ~10 Mbps
Technique(s) used	SEO Testing, Static Testing (Reviews)
Reproducibility	Always

Description

Lighthouse SEO scores 85 and fails "Links do not have descriptive text" (1 link found, e.g. generic text such as "Read more") and "Links are not crawlable" (links that use JavaScript or "#" instead of a real address).

Preconditions

None

Steps to reproduce

1. Open https://hyundai-nishat.com in Chrome
2. Press F12 and open the Lighthouse tab
3. Select Mobile and all four categories, then click Analyze page load
4. Scroll to the SEO section

Test data

Lighthouse mobile run

Expected result

Every link has descriptive text and a real href that search engines can follow.


Actual result

Two failed SEO checks.

Oracle (why this is a bug)

Google Search Central link best practices: crawlable links need an href with a URL, and link text should describe the destination.

Screenshots



BUG-050 — Screenshot 1

Appendix

A. Features List of the Application

- Home page: promotional banners, booking pop-up, quick-action links
- Find a Car: vehicle catalogue with category filter (All, Sedan, SUV, Electric, Commercial) and starting prices
- Vehicle model pages: Elantra, Elantra Hybrid, Sonata, Sonata N Line, Tucson Hybrid, Santa Fe, Palisade Hybrid, IONIQ 5, IONIQ 6, Porter H-100
- Online Booking
- Booking Status check
- Request a Test Drive form
- Request a Brochure form
- Service Appointment Request (Book a Service) form
- Find a Dealer (dealer locator)
- Hyundai Easy Own (financing information)
- Hyundai Promise
- After Sales: warranty conditions, extended warranty, genuine parts, lubricants, engine oil
- Hyundai Service: customer promise, dealership facility, free services, periodic maintenance charts, owner's manual
- About Us: overview, corporate message, philosophy
- Press Release & News
- Career page
- Contact Us page
- Email newsletter sign-up
- Footer: legal disclaimer, cookie policy, sitemap, social media links
- myHyundai customer portal (external: myhyundaipakistan.com)

B. Tools Used to Find the Bugs

#	Tool	Purpose
1	Google Chrome 156	Main browser for all functional, navigation, content and layout testing
2	Chrome DevTools – Device Mode (F12, Ctrl+Shift+M)	Mobile viewport emulation for responsive and mobile-menu testing (ENV-2)
3	Chrome DevTools – Elements and Console	Inspecting page structure, link targets and console errors
4	Chrome View Page Source (Ctrl+U)	Static review of the page's HTML; found the exposed developer email (BUG-003)
5	Google Lighthouse	Performance, accessibility, best-practice and SEO audits
6	securityheaders.com (Snyk)	Passive scan of HTTP security headers (BUG-041, BUG-042)
7	Qualys SSL Labs Server Test	Passive check of HTTPS certificates and TLS configuration (BUG-043)
8	GoFullPage (Chrome extension)	Full-page screenshots of long pages (home page, Owner's Manual, Extended Warranty)

#	Tool	Purpose
9	Windows Snipping Tool (Win+Shift+S)	Screenshots of menus and specific screen areas used as bug evidence
10	Windows System Information (msinfo32)	Recording the test machine's hardware and OS details for the environment table
11	Microsoft Word / LibreOffice Writer	Writing and exporting this report to .docx and .pdf
12	Python (Matplotlib) and Mermaid	Drawing the bug-summary graphs and the workflow diagrams

C. Testing Techniques Used

55 of the 100 techniques below were applied. Applied techniques are marked ✔️ with the bugs they uncovered.

#	Technique	Category	Applied	Bug IDs
1	Functional Testing	Functional	✔️	
2	Smoke Testing	Functional	—	
3	Sanity Testing	Functional	—	
4	Regression Testing	Functional	✔️	BUG-012, BUG-026, BUG-031, BUG-036, BUG-045
5	Retesting (Confirmation Testing)	Functional	✔️	
6	Exploratory Testing	Functional	✔️	BUG-009, BUG-011
7	Ad-hoc Testing	Functional	—	
8	Monkey Testing	Functional	—	
9	Gorilla Testing	Functional	—	
10	End-to-End Testing	Functional	—	
11	Integration Testing	Functional	✔️	BUG-021, BUG-024
12	System Testing	Functional	—	
13	User Acceptance Testing	Functional	—	
14	Alpha Testing	Functional	—	
15	Beta Testing	Functional	—	
16	API Testing	Functional	—	
17	Database Testing	Functional	—	
18	Data Integrity Testing	Functional	✔️	BUG-009, BUG-022, BUG-039, BUG-040

#	Technique	Category	Applied	Bug IDs
19	Business Rule Testing	Functional	✔	BUG-009, BUG-011, BUG-018, BUG-022, BUG-023, BUG-028, BUG-030, BUG-039
20	Workflow Testing	Functional	—	
21	Navigation Testing	Functional	✔	BUG-001, BUG-005, BUG-006, BUG-034, BUG-035
22	Broken Link Testing	Functional	—	
23	Search Functionality Testing	Functional	—	
24	Error Handling Testing	Functional	✔	BUG-014, BUG-048
25	Error Message Testing	Functional	✔	BUG-014, BUG-020, BUG-027
26	Payment / Transaction Testing	Functional	—	
27	Session Management Testing	Functional	✔	BUG-049
28	Interrupt Testing	Functional	—	
29	Boundary Value Analysis	Test design (black-box)	✔	BUG-020, BUG-023
30	Equivalence Partitioning	Test design (black-box)	✔	BUG-013, BUG-022, BUG-026, BUG-029
31	Decision Table Testing	Test design (black-box)	✔	BUG-014, BUG-021, BUG-024, BUG-027
32	State Transition Testing	Test design (black-box)	✔	BUG-021
33	Use Case Testing	Test design (black-box)	✔	BUG-030, BUG-035
34	Cause-Effect Graphing	Test design (black-box)	✔	BUG-021, BUG-024
35	Pairwise (All-Pairs) Testing	Test design (black-box)	—	
36	Error Guessing	Test design (black-box)	✔	BUG-019
37	Positive Testing	Test design (black-box)	✔	

#	Technique	Category	Applied	Bug IDs
38	Negative Testing	Test design (black-box)	✔	BUG-013, BUG-020, BUG-026
39	Input Validation Testing	Test design (black-box)	✔	BUG-013, BUG-020, BUG-026
40	Required Field Testing	Test design (black-box)	✔	BUG-014, BUG-018, BUG-027
41	Field Length Testing	Test design (black-box)	✔	
42	Special Character Testing	Test design (black-box)	✔	BUG-013
43	Null / Empty Input Testing	Test design (black-box)	—	
44	Date and Time Testing	Test design (black-box)	✔	BUG-023
45	Checklist-Based Testing	Test design (black-box)	✔	BUG-005, BUG-006, BUG-029, BUG-034
46	Scenario-Based Testing	Test design (black-box)	✔	BUG-030
47	Black-Box Testing	Structural / approach	✔	
48	White-Box Testing	Structural / approach	—	
49	Grey-Box Testing	Structural / approach	✔	BUG-003, BUG-048
50	Static Testing (Reviews)	Structural / approach	✔	BUG-002, BUG-003, BUG-007, BUG-008, BUG-015, BUG-016, BUG-017, BUG-028, BUG-038, BUG-039, BUG-040, BUG-049, BUG-050
51	Unit Testing	Structural / approach	—	
52	Component Testing	Structural / approach	—	

#	Technique	Category	Applied	Bug IDs
53	GUI Testing	UI and usability	✔	BUG-002, BUG-004, BUG-006, BUG-010, BUG-012, BUG-019, BUG-031, BUG-032, BUG-036
54	Usability Testing	UI and usability	✔	BUG-015, BUG-018, BUG-019, BUG-025, BUG-029, BUG-037, BUG-038, BUG-045, BUG-049
55	Accessibility Testing	UI and usability	✔	BUG-032, BUG-033, BUG-038, BUG-040, BUG-047
56	Colour Contrast Testing	UI and usability	✔	BUG-032, BUG-033, BUG-047
57	Keyboard Navigation Testing	UI and usability	—	
58	Screen Reader Testing	UI and usability	✔	BUG-047
59	Responsive Design Testing	UI and usability	✔	BUG-001, BUG-004
60	Cross-Browser Testing	UI and usability	✔	BUG-002, BUG-049
61	Cross-Platform / OS Compatibility Testing	UI and usability	✔	BUG-005
62	Mobile Device Testing	UI and usability	✔	BUG-001, BUG-004, BUG-005, BUG-049
63	Orientation (Portrait/Landscape) Testing	UI and usability	—	
64	Layout and Alignment Testing	UI and usability	✔	BUG-004, BUG-010, BUG-012, BUG-036
65	Typography and Font Consistency Testing	UI and usability	✔	BUG-031

#	Technique	Category	Applied	Bug IDs
66	Content and Spelling Testing	UI and usability	✔	BUG-002, BUG-007, BUG-008, BUG-010, BUG-011, BUG-015, BUG-016, BUG-017, BUG-025, BUG-028, BUG-034, BUG-035
67	Zoom / Text Scaling Testing	UI and usability	—	
68	Localization Testing	UI and usability	—	
69	Internationalization Testing	UI and usability	—	
70	Visual Regression Testing	UI and usability	✔	BUG-012, BUG-031, BUG-036, BUG-045
71	Performance Testing	Performance	✔	BUG-037, BUG-044, BUG-045, BUG-046, BUG-048
72	Load Testing	Performance	—	
73	Stress Testing	Performance	—	
74	Spike Testing	Performance	—	
75	Endurance (Soak) Testing	Performance	—	
76	Volume Testing	Performance	✔	BUG-037, BUG-046
77	Scalability Testing	Performance	—	
78	Page Load Speed Testing	Performance	✔	BUG-044
79	Low Bandwidth / Network Throttling Testing	Performance	✔	BUG-037, BUG-044, BUG-046
80	Offline Behaviour Testing	Performance	—	
81	Security Testing	Security	✔	BUG-003, BUG-041, BUG-042, BUG-043
82	Authentication Testing	Security	—	
83	Authorization / Access Control Testing	Security	—	
84	Password Policy Testing	Security	—	

#	Technique	Category	Applied	Bug IDs
85	Session Timeout Testing	Security	—	
86	SQL Injection Testing	Security	—	
87	Cross-Site Scripting (XSS) Testing	Security	✔	BUG-041
88	CSRF Testing	Security	—	
89	HTTPS / SSL Testing	Security	✔	BUG-043
90	Security Headers Testing	Security	✔	BUG-041, BUG-042
91	Cookie Security Testing	Security	—	
92	Brute Force / Rate Limiting Testing	Security	—	
93	File Upload Testing	Security	—	
94	Sensitive Data Exposure Testing	Security	✔	BUG-003, BUG-042
95	Vulnerability Scanning	Security	✔	BUG-041
96	Compatibility Testing	Other	✔	BUG-005, BUG-043
97	SEO Testing	Other	✔	BUG-050
98	Update / Upgrade Testing	Other	—	
99	Recovery Testing	Other	—	
100	Configuration Testing	Other	—	

Techniques created or adapted for this assignment:

- Desktop–Mobile Parity Check: open the same page and menu on desktop and in mobile view side by side, and compare every item, link target and label. Any difference is a candidate bug (found BUG-001 and BUG-005).

D. Helpful Internet Links

- Hyundai Nishat Motors website (application under test) — https://hyundai-nishat.com
- OWASP Top 10 Web Application Security Risks — https://owasp.org/www-project-top-ten/
- W3C Web Content Accessibility Guidelines (WCAG) 2.1 — https://www.w3.org/TR/WCAG21/
- Chrome Lighthouse documentation — https://developer.chrome.com/docs/lighthouse/overview
- ISTQB Glossary — https://glossary.istqb.org/
- Chrome DevTools – Simulate mobile devices with Device Mode — https://developer.chrome.com/docs/devtools/device-mode
- OWASP Content Security Policy Cheat Sheet — https://cheatsheetseries.owasp.org/cheatsheets/Content_Security_Policy_Cheat_Sheet.html