

DamageTriage - Disaster Response Report

Event: 2023 Turkiye-Syria Earthquake - SAR + Optical

Generated: 2026-09-24 17:24

Total buildings assessed: 806

Severity Breakdown

damaged 31 (3.8%)
intact 775

Needs Human Review (uncertain prediction)

7 of 806 predictions fell within +/-0.15 of the 0.5 decision boundary and are flagged for manual review before dispatch.

Full list in review_queue.json.

Top 15 Priority Buildings (highest damage probability)






Building ID (OSM)	P(damaged)	Confidence
intact/1139093089	1.00	1.00
intact/1139293924	1.00	1.00
damaged/1139266138	1.00	1.00
damaged/1139190969	1.00	1.00
damaged/1139190939	1.00	1.00
damaged/1139283021	1.00	1.00
damaged/1139290381	1.00	1.00
damaged/1139274282	1.00	1.00
damaged/1139119038	1.00	1.00
damaged/1139114880	1.00	1.00
damaged/1139274257	1.00	1.00
damaged/1139539884	1.00	1.00
damaged/1139248411	1.00	1.00
damaged/1139263478	1.00	1.00
intact/1139183211	0.99	0.99

DamageTriage - Disaster Response Report

Event: 2023 Turkiye-Syria Earthquake - SAR + Optical

Sample Damage Heatmaps (Grad-CAM, SAR + Optical)

Red = region the model's decision relied on most, per modality.



Source imagery: Capella Space (SAR) and Maxar Open Data (optical), CC BY 4.0. Building footprints/labels: OpenStreetMap + HOT, ODbL. Dataset: QuickQuakeBuildings (Sun et al., 2024), CC BY-NC-SA 4.0 - academic/non-commercial use only.