



Patriot Claims

Your Ladder Assist Partners

INSPECTION REPORT



CLAIM NUMBER: 260626590
INSURED: ANGELA MOBBS
LOSS ADDRESS: 418 CUMMINS ST
PINEVILLE LA 71360

PROFESSIONALLY PREPARED BY PATRIOT CLAIMS
June 30, 2026
Josh Cargile , INSPECTOR

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION SUMMARY

CLAIM NUMBER	INSPECTION DATE	INSPECTION TYPE	DATE OF LOSS
260626590	06/30/2026	Interior & Exterior Inspection	04/01/2026
INSURED	LOSS ADDRESS	STRUCTURE TYPE	STORIES
ANGELA MOBBS	418 CUMMINS ST, PINEVILLE, LA 71360	Single Family - 1 Story	STORIES
CARRIER	ADJUSTER	INSPECTOR	INSPECTOR CONTACT
National General		Josh Cargile	josh.cargile@field.patriotclaims.com (225) 337-5678
OTHER STRUCTURES			
N/A			

INSPECTOR SUMMARY:

Left slope has a spot where a limb fell all the way through the roof and the soffit, damaging a pipe boot as well. Insured reports pipe boot causing fuses to short so I was very careful not to mess with it but it will need to be replaced. The meter was knocked sideways off its mount on the left elevation as well but appears functional.

LOWER ELEVATIONS:

Left elevation soffit potential wind/ limb 1 24 x6 ft piece

ROOF:

Back slope potential wind x6, left slope potential wind x6, Right slope potential wind x3



Claim Number:	260626590
Insured Name:	ANGELA MOBBS
Loss Address:	418 CUMMINS ST, PINEVILLE, LA 71360

Inspector Name:	Josh Cargile
OA Name:	
Job Type:	Wind/Hail Inspection

CHECK ALL WHO WERE ON THE ROOF AT THE TIME OF THE INSPECTION	
Patriot Rep [✓]	Outside Adjuster []
Contractor []	Other []

ROOF TYPE	
20-year 3-Tab (flat, single-layer)	
[20 - Year Old]	
Predom Pitch:	4/12
Stories (#):	
Layers (#):	Single Layer w/Starter
Layer Type:	N/A

COLLATERAL: DAMAGE AND TOTAL COUNT

Box Vents	0 of 0
Turbines	0 of 1
HVAC Vents	0 of 1
Power Vents	0 of 0
Pipe Jacks	0 of 1
Chimney Cap	0 of 0
Skylights	0 of 0
Rain Diverters	0' 0" of 0' 0"
Ridge Vent	0 of 0
Satellite/Ant	0 of 0
Exhaust Vents	0 of 2
Ice/Water Shield	0 of 0
Drip Edge	Installed
Gutters	0 of 0

AERIAL MEASUREMENTS				FRONT OF HOUSE DIRECTION	
Yes:	✓	No:		North	

RIDGE:	Standard Asphalt	VALLEY:	Open metal valley
HIP:	Standard Asphalt		

TEST SQUARE COUNT				TARP R/R DONE: [Y/N]		
TOTAL SLOPE COUNT	TEST SQUARE SIZE	POTENTIAL HAIL	POTENTIAL WIND	D&R TARPS PER SLOPE	NEW TARPS PER SLOPE	DETACH TARPS PER SLOPE
F: 0	Size: 10X10	Count: 0	Count: 0	F: 0	0	0
L: 1	Size: 5X5	Count: 0	Count: 6	L: 0	1	0
B: 0	Size: 10X10	Count: 0	Count: 0	B: 0	0	0
R: 0	Size: 10X10	Count: 0	Count: 0	R: 0	0	0

ROOF CONDITIONS	F	L	B	R
Blisters				
Cup Curl				
Deck Rot				
Granule Loss	✓	✓	✓	✓
Manufacturer Defects				
Mechanical				
Nail Pops				
Prior Repairs				
Thermal Cracking				

CAD SKETCH KEY
TS = Test Square
SAT = Satellite
RV = Ridge Vent/Backing
ANT = Antenna
X = Potential Wind
EV = Exhaust Vent
PV = Power Vent
RD = Rain Diverter
ORV = Off-Ridge Vent
TV = Turbine Vent
BV = Box Vent
TD = Tree Damage
PJ = Pipe Jack
HVAC = Heating/AC Stack
CC = Chimney/Caps
SKY = Skylights
SP = Solar Panels



	GUTTER	SIZE	PAINT	MATERIAL		DOWNSPOUT	SIZE	PAINT	MATERIAL
F:	0 of 0				F:	0 of 0			
L:	0 of 0				L:	0 of 0			
B:	0 of 0				B:	0 of 0			
R:	0 of 0				R:	0 of 0			

ROOF COMPONENTS
Eave Depth - 24 Inches
Drip Edge - Drip Edge Materials: Aluminum Drip Edge - Drip Edge Type: Painted - Drip Edge Locations: Eave
Underlayment - Underlayment (Felt Type): 15 lb Felt - Layer Count (Layer): Single Layer w/Starter

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

ROOF COMPONENTS

Main Material/Shingle Gauge - Main Roof Material: Asphalt - Type: 3-Tab (flat, single-layer) - Size (Applicable on Asphalt & Metal Only): Asphalt: 20-year - Estimated Roof Age: 20 Years

Pitch - Roof Pitch 1st: 4 /12 - Predominate Pitch: Roof Pitch 1st - Rope & Harness Necessary: No

Ridge - Ridge: Standard Asphalt

Hips - Hips: Standard Asphalt

Valley - Valley: Open metal valley

Left Facet

Slope - Potential Wind Findings: 6 - Tarp Length: 2 - Tarp Width: 2 - Qty of Cap Nails: 6 - Qty Shingles Affected by Cap Nails: 4

Facet A - Potential Wind Findings: 6 Each - Other Findings: Granule Loss

Tarp 1 - Tarp: Yes - Tarp Length: 2 Ft - Tarp Width: 2 Ft - Service Provided: New Install Provided - Qty of Cap Nails: 6 Each - Qty Shingles Affected by Cap Nails: 4 Each

Front

Test Square Size: 10X10 - Potential Hail Count: 0 Each - Other Findings: Granule Loss

HVAC Vents - 0 of 1 - Total Unit: Each - Potentially Damaged Unit: Each - Sizes: Diameters: 5"

Left

Test Square Size: 5X5 - Other Findings: Granule Loss

Back

Test Square Size: 10X10 - Potential Hail Count: 0 Each - Other Findings: Granule Loss

Pipe Jacks - 0 of 1 - Total Unit: Each - Potentially Damaged Unit: Each

Exhaust Vents - 0 of 2 - Total Unit: Each - Potentially Damaged Unit: Each - Sizes: Collar/Opening: 5"

Turbines - 0 of 1 - Total Unit: Each - Potentially Damaged Unit: Each - Sizes: Diameters: 12" - Materials: Galvanized steel - Painted: No

Right

Test Square Size: 10X10 - Potential Hail Count: 0 Each - Other Findings: Granule Loss

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

General Inspection Questions

Was the named insured home?	Yes
Did you get on the roof?	Yes
Did the roof have potential hail or wind damage?	Yes
Is potential collateral damage consistent with report?	Yes

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

MAIN DWELLING INTERIOR FINDINGS SHEET

Room Name:	Dining Room	Perimeter Length:	0' 0"	Baseboards	No
Ttl Ceiling SqFt:		Ttl Wall SqFt:	80.00	Crown Molding	No
Ceiling Height:	0' 0"	Affected Ceiling SqFt:		Ceiling Fans	
Affected Wall1 SqFt:		3	Total Wall1 SqFt:		80
Vent Count:		Light Count:		Wall Texture:	Knockdown
Window Count:		Smoke Detector:		Ceiling Texture:	
Room Notes:					
Other:					

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Patriot Branding



Inspection Vehicle

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front of House



Risk Address

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Dining Room overview(8x12)
Room name: Dining Room



Dining Room potential leak (3x1) on wall
Room name: Dining Room

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Elevation Window Screen Clean



Front Elevation Window Screen Clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Elevation overview



Front Elevation Window Screen Clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Elevation door clean



Front Elevation Window Screen Clean

Inspection Report


Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Elevation Window Screen Clean



Front Elevation Window Screen Clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Elevation Window Screen Clean



Front Elevation Window Screen Clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Elevation overview



Left Elevation window clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Elevation window clean



Left Elevation fascia potential wind/ limb

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Elevation meter potential wind/ limb



Left Elevation eave potential wind/limb

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Elevation overview



Back Elevation Window Screen Clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Elevation Window Screen Clean



Back Elevation Window Screen Clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Elevation Window Screen Clean



Back Elevation door clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Elevation Window Screen Clean



Back Elevation window clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Right Elevation overview



Right Elevation ac overview

Inspection Report

Service Date: June 30, 2026

Claim Number: 260626590

Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,

Suite 700

Rockwall, TX 75032


214-717-3330

office@patriotclaims.com

INSPECTION PHOTO SHEET



Right Elevation ac clean



Right Elevation ac model

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Pitch

Eave Depth: 24 Inches



Eave Depth 24

Eave Depth: 24 Inches

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:


2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



1 layer

Eave Depth: 24 Inches



Valleys open

Valley: Open metal valley

Inspection Report


Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope Overview



Front Slope Test Square 10x10 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope Test Square q1 overview



Front Slope Test Square q1 potential granule loss

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope Test Square q2 overview



Front Slope Test Square q2 potential granule loss

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope Test Square q3 overview



Front Slope Test Square q3 potential granule loss

Inspection Report


Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope Test Square q4 overview



Front Slope Test Square q4 potential granule loss

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope Test Square q5 overview



Front Slope Test Square q5 potential granule loss

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope Test Square q6 overview



Front Slope Test Square q6 potential granule loss

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Front Slope HVAC Vent clean

Display Name: Furnace vent
Total Qty: 1 Each
Total Unit: Each
Potentially Damaged Qty: 0 Each
Potentially Damaged Unit: Each
Sizes: Diameters: 5"



Left Slope Overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Slope potential wind/limb x5



Left Slope potential wind/ limb x5

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Slope potential wind/ limb x5



Left Slope tarp install (Covered as much as I could without messing with knocked over pipe boot)

Inspection Report


Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Slope Test Square potential granule loss



Left Slope Test Square overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Slope Test Square potential granule loss



Left Slope Test Square potential granule loss

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Slope Test Square potential granule loss



Left Slope potential wind x6

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Slope potential wind x6



Left Slope Facet A Tarp 1 Tarp
Tarp: Yes

Inspection Report


Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Left Slope Facet A Tarp 1 Service Provided
Service Provided: New Install



Back Slope Overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope Test Square 10x10 overview



Back Slope Test Square q1 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope Test Square q1 potential granule loss



Back Slope Test Square q2 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope Test Square q2 potential granule loss



Back Slope Test Square q3 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope Test Square q3 potential granule loss



Back Slope Test Square q4 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope Test Square q4 potential granule loss



Back Slope Test Square q5 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope Test Square q5 potential granule loss



Back Slope Test Square q6 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope Test Square q6 potential granule loss



Back Slope potential wind x6

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope potential wind x6



Back Slope potential wind x6

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope potential wind x6



Back Slope potential wind x6

Inspection Report


Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope potential wind x6



Back Slope potential wind x6

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope potential wind x6



Back Slope potential limb

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope potential limb



Back Slope Exhaust vent clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope turbine clean



Back Slope Exhaust vent clean

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Back Slope pipe jack clean



Right Slope Overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Right Slope Test Square 10x5 overview



Right Slope Test Square q1 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Right Slope Test Square q1 potential granule loss



Right Slope Test Square q2 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Right Slope Test Square q2 potential granule loss



Right Slope Test Square q3 overview

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS




Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Right Slope Test Square q3 potential granule loss



Right Slope potential wind x2

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

INSPECTION PHOTO SHEET



Right Slope potential wind x2

Inspection Report

Service Date: June 30, 2026
Claim Number: 260626590
Insured: ANGELA MOBBS



Corporate Office:

2701 Sunset Ridge Drive,
Suite 700
Rockwall, TX 75032
214-717-3330
office@patriotclaims.com

Subrogation Opportunities

Improper nail/staple size	No
Nail/staple not on nail line	No
Improper fasteners installed	No
Improper shingle exposure	No
Manufacturer defects	No

This Inspection Report has been proudly prepared by **Patriot Claims**.

PATRIOT CLAIMS CORPORATE OFFICE

2701 Sunset Ridge Drive, suite 700
Rockwall, TX 75032

214-717-3330

office@patriotclaims.com

REQUEST AN INSPECTION ON OUR WEBSITE AT WWW.PATRIOTCLAIMS.COM

Request Inspection