


Sampling density, not grid resolution, drove the volume collapse

Neither curve reaches the true hull: column fill merges wheel wells and window openings into the solid, by design

Column-fill solid volume vs grid resolution



The 60k deficit grows with resolution

