# Inspection photos

PDF Created on October 13, 2020 at 11:30:43 AM

Claim Number: 3013539499-1



Risk



Front. Red= damaged sash






Hail Dent in 1 sash



No hail damage to frames or other sashes








Dent with scratch. Not hail



Glass marking. Unable to locate window brand





No hail dmg



Red chalk from contractor.



Mullion between windows is wavy from manufacturer.
Not hail related



No hail to sash cladding.







No storm damage



No storm damage



No storm damage



No storm damage



No storm damage



Right



No storm damage



No storm damage



No storm damage




Back







No storm damage



Million is wavy from manufacturer. No storm damage found




Note waviness of mullion.



No storm damage



Window under deck



Same waviness in mullion. Not hail



Left




Left




Dent in 1 sash






Front window




Left window