Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling - 1-Risk

Date Taken: 9/12/2025

Taken By: Gregory Tomes



Dwelling - 2-Shingle

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail spatter

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965




Dwelling - 3-Velley metal

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Small spatter observed



Dwelling - 4-Valley Metal

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute of damages

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling - 5-Valley metal

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute of damages



Dwelling/Front Elevation - 6-Gutter Guard

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail damage

Photo Sheet


Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Front Elevation - 7-Gutter Guard

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No hail damage to upper gutter guard



Dwelling/Front Elevation - 8-Gutter Guard

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Lower gutter guard. No dispute of damage

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Front Elevation - 9-IMG_0553

Date Taken: 9/12/2025

Taken By: Gregory Tomes



Dwelling/Front Elevation - 10-Upper Window over entry door

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No hail damage observed to the window

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Front Elevation - 11-Dining Room Windows

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Damage observed on left sash. 2008 MFG date stamp on windows



Dwelling/Front Elevation - 12-Bedroom 1

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute of damages

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Front Elevation - 13-Senco Windows

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Sashes with mfg dates in 1993, 1997, & 2008 observed during inspection



Dwelling/Front Elevation - 14-Dining Room

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Mechanical damage with marring present

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Front Elevation - 15-Dining Room

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Marring & scratches in the dent



Dwelling/Front Elevation - 16-Dining Room

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail damage

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Front Elevation - 17-Downspout

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damage



Dwelling/Front Elevation - 18-Downspout Extension

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damage

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Front Elevation - 19-Planter box

Date Taken: 9/12/2025

Taken By: Gregory Tomes

hail spatter



Dwelling/Right Elevation - 20-Right

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Arrow points to window with damage observed

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Right Elevation - 21-Ele Box Overview

Date Taken: 9/12/2025

Taken By: Gregory Tomes



Dwelling/Right Elevation - 22-ELE Box

Date Taken: 9/12/2025

Taken By: Gregory Tomes

spatter on the box

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Right Elevation - 23-Right

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail damage observed on sash



Dwelling/Right Elevation - 24-Right

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail damage to sash

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Rear Elevation - 25-Overview

Date Taken: 9/12/2025

Taken By: Gregory Tomes



Dwelling/Rear Elevation - 26-Rear

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damages

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Rear Elevation - 27-Siding

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damages



Dwelling/Rear Elevation - 28-Downspout

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No damage observed

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965




Dwelling/Rear Elevation - 29-Family Room

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Damage observed to right sash



Dwelling/Rear Elevation - 30-Family Room

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail damage on sash

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Rear Elevation - 31-Family Room

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail damage to sash



Dwelling/Rear Elevation - 32-Deck

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail spatter

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Rear Elevation - 33-Deck

Date Taken: 9/12/2025

Taken By: Gregory Tomes

Hail spatter



Dwelling/Left Elevation - 34-Overview

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damages

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Left Elevation - 35-Attached Garage

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damages



Dwelling/Left Elevation - 36-Downspout

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damages

Photo Sheet

Concise Resolution Services, LLC

2830 S Hulen St., PMB 353 | Fort Worth, TX 76109

Insured: Yibiao Lu

Claim #: 7007986837-1-1

Policy #: [redacted]4965



Dwelling/Left Elevation - 37-Window

Date Taken: 9/12/2025

Taken By: Gregory Tomes

No dispute on damages