
Job Run Certification Report

Job : 051509 No G72

Location :	Fujifilm Graphic Systems
Device :	09-04-08 Colorpath GE07
Run Date :	05/15/09 - 02:18 PM
Substrate :	Paper(1)
Ink 1 :	BLACK C(1.1)
Ink 2 :	CYAN C(1.2)
Ink 3 :	MAGENTA C(1.3)
Ink 4 :	YELLOW C(1.4)

Target Versus Actual AB Plot



Results Summary

Error Caution

Percent Of Patch Errors

	Actual	Threshold
Error %	0	NA

Δ E Values

Patch Type	Actual	Threshold
C	0.11	4.00
M	0.17	4.00
Y	0.17	4.00
K	0.77	4.00
M+Y	0.24	4.00
C+Y	0.17	4.00
C+M	0.63	4.00
PAPER	0.08	4.00
C_25%+M_19%+Y_19%	0.12	4.00
C_50%+M_40%+Y_40%	0.20	4.00
C_75%+M_66%+Y_66%	0.19	4.00

© Fujifilm 2011


Job : 051509 No G72

Device : 09-04-08 Colorpath GE07


Run Date : 05/15/09 - 02:18 PM

Substrate : Paper(1)


Gray Balance a* b* Charts



Gray Balance L* Chart



Neutral Print Density Charts



© Fujifilm 2011

Job : 051509 No G72

Device : 09-04-08 Colorpath GE07

Run Date : 05/15/09 - 02:18 PM


Substrate : Paper(1)

Job Δ E

Zone Δ E Summary



Densitometric Summary



© Fujifilm 2011


Job : 051509 No G72


Device : 09-04-08 Colorpath GE07


Run Date : 05/15/09 - 02:18 PM


Substrate : Paper(1)


Trends











© Fujifilm 2011