

DEANE AUTO REPAIRS

63 HAYR ROAD, THREE KINGS - 0800 625 9827

Vehicle Condition Report

A practical, visual pre-purchase inspection template
for clear workshop findings and customer decisions.

COMPLETED EXAMPLE

2008 Volkswagen Golf - using the vehicle data and findings
from the supplied inspection report.

REPORT NO.

PPI-2021-18670545

INSPECTION DATE

24 Feb 2021

1 CUSTOMER & VEHICLE

CUSTOMER NAME

MUHAMMAD BHATTI

PHONE / EMAIL

021 480 786

deaneautonz@gmail.com

MAKE / MODEL / YEAR

2008 Volkswagen Golf

REGISTRATION

X9485

VIN

WVWZZZ1KZ8U034604

ODOMETER (KM)

27,534 km

FUEL / TRANSMISSION

Petrol - Auto / Tiptronic

INSPECTION TYPE / TECHNICIAN

Pre-purchase inspection - road test 40-50 km/h

2 INSPECTION SNAPSHOT

Overall vehicle condition

Fair for age and mileage. May require unplanned maintenance or repair. Confirm transmission service history before purchase.

Next service due: 15 Mar 2021**Customer decision guide**

Good



Monitor

**Repair**

Recommended action / timing

Investigate oil leaks and 12V system.

3 KEY FINDINGS

ENGINE - FRONT ASSEMBLY

Oil leak; wet - investigate.

ENGINE - BOTTOM ASSEMBLY

Oil leak; drips forming - investigate.

12V ELECTRICAL SYSTEM

Battery and starter faults detected.

ELECTRICAL ACCESSORIES

Radio not working during road test.

Photo record

Photograph the condition that matters. Mark the image title with the relevant system, location or repair recommendation.





Photo notes: Current vehicle views retained from the source inspection. Add close-ups of the oil leak and battery/starter test results when available.


5 VEHICLE CONDITION MAPS

Exterior / body map



● Customer note ● Repair item ● Photo reference

Cabin / tyre reference



Tyre depths: LF ____ RF ____ LR ____ RR ____ mm

6 INSPECTION CHECKLIST

Engine & fluids ☐ OK ☐ MON ☐ REP

Steering & suspension ☐ OK ☐ MON ☐ REP

Body & interior ☐ OK ☐ MON ☐ REP

Brakes & tyres ☐ OK ☐ MON ☐ REP

Electrical & battery ☐ OK ☐ MON ☐ REP

Road test ☐ OK ☐ MON ☐ REP

7 TECHNICIAN NOTES & NEXT STEPS
