

OSHA Report Quality Nissan and Kia of Greenwood

Complete On: 9/04/2024

Report Created By:

Tom Dortch

815-404-8681

tomdortch@autorisknow.com

All vacant holes are not properly sealed off on electrical panel box.

Kia service - empty slot



All vacant holes are not properly sealed off on electrical panel box.


High Risk

Kia service - empty space on bottom with loose wiring



The fire extinguisher signs above the unit are not posted properly.

Kia parts - no sign upstairs



The eye wash equipment is not readily accessible.

Nissan service - unable to access first aid, eye wash, or fire extinguisher



All electrical cords are not in good working order (none frayed, cracked, taped, or spliced or ground missing on 3 prong plugs).

Nissan service - frayed wiring

