


PARTICLE SIZE DISTRIBUTION



Project Name:Mayfield RoadProject No.:101-17262-00Figure B6

Location ID.: BH8 Sample No./Depth: Granular Sub Base Remarks: Sandy gravel, trace silt