Imager Quality Analysis

Department: South Bay Radiation Oncology


Machine Name:SB-LA-1Data Acquired:1/19/2022Vendor:VarianData Analyzed:1/20/2022

Model: Truebeam Serial #: --

Quick Select: SBLA1_kV Dual Planar • Imager: Varian OBI • Energy: 100 Phantom: QCkV-1 • Phantom Template: QCkV-1 • Phantom Serial #:Y080667


Dual Image Planar QA

	Image 1				Image 2			
Noise (GSI)	F50 (lp/mm)	F40 (lp/mm)	F30 (lp/mm)	CNR	F50 (lp/mm)	F40 (lp/mm)	F30 (lp/mm)	CNR
152.697	1.449	1.681	1.942	94.137	1.450	1.684	1.947	94.109





20220119_180233_100 [kV] 1/19/2022 6:02:32 PM



20220119_180242_100 [kV] 1/19/2022 6:02:42 PM

