## **Imager Quality Analysis**

**Department:** South Bay Radiation Oncology


Machine Name:SB-LA-1Data Acquired:1/19/2022Vendor:VarianData Analyzed:1/20/2022

Model: Truebeam Serial #: --

Quick Select: SBLA1\_2.5MV\_Dual Planar • Imager: aSi 1000 • Energy: 2.5 Phantom: QC-3 • Phantom Template: QC-3 • Phantom Serial #:S072950

## Dual Image Planar QA

	Image 1				Image 2			
Noise (GSI)	F50 (lp/mm)	F40 (lp/mm)	F30 (lp/mm)	CNR	F50 (lp/mm)	F40 (lp/mm)	F30 (lp/mm)	CNR
7.274	0.390	0.474	0.579	793.817	0.389	0.472	0.577	793.737





20220119\_175938\_2.5x 1/19/2022 5:59:37 PM



20220119\_180023\_2.5x 1/19/2022 6:00:22 PM

