Inspection report

AV-26-004401 | Site visit 2026-10-05 | Report revision 1

INSURED	Meadow Lane Household Supply Ltd
SITE	Shop 12, Meadow Lane Arcade, Brookfield
REPORTED EVENT	Reported customer slip near a wet retail aisle
INSPECTING ADJUSTER	Elena Brooks

1. Reported circumstances

The store notified a reported slip near aisle two. Staff described water on the floor and a cleaning bucket nearby. A yellow warning sign appears in the later site photographs, but its position at the time of the reported event is disputed. No liability or medical causation conclusion is recorded.

2. Observations and limitations

The supplied later photographs show a shallow puddle, a gray bucket and a yellow folding sign in the retail aisle. They do not establish the warning arrangements at the incident time. The cleaning log has a gap between 10:30 and 11:30.

See the embedded annotated photo exhibit and case-specific location sketch. Both are original synthetic scenario exhibits; they do not establish cause, timing, liability or coverage.

Preliminary repair scope

AV-26-004401 | Revision 1 | 2026-10-05 | USD; tax excluded

Item / description	Qty	Unit	Rate	Amount
Floor inspection and moisture testing	1	LS	350.00	350.00
Temporary aisle protection	1	LS	200.00	200.00
Replace damaged shelf-end trim	2	each	125.00	250.00
Cleaning and disposal	1	LS	450.00	450.00
PRELIMINARY TOTAL				**1,250.00**

Scope qualifications

Quantities are provisional. Reserves, preliminary repair estimates, later proposals and any eventual payment are different measures. No completed work, cause or insurer approval is certified.

Request the original cleaning log, dated witness accounts and consented supporting correspondence. Preserve the earlier and later statements separately. Do not treat the later photograph as proof of the earlier sign position.

Annotated photo exhibit

AV-26-004401 | Synthetic scenario photos; original JPGs retained separately

PHOTO EXHIBIT | AV-26-004401





A - Sign shown in later photograph

B - Water visible; incident-time position disputed

Synthetic photos. Annotations describe appearances, not cause, timing, liability or coverage.


How to read this exhibit

Marks A and B refer to visible appearances only. Compare the embedded images with the inspection narrative and the separate original JPGs. Not every visually useful detail is transcribed into the report text.

These are generated scenario images, not independently dated field photographs. A later image cannot prove an earlier event sequence or reveal concealed conditions.

Location and evidence sketch

AV-26-004401 | Embedded case-specific diagram - not to scale



Interpretation and unresolved evidence

The aisle sketch locates features shown in the later photographs. It does not settle the disputed warning-sign position at the incident time or fill the gap in the cleaning record.

The initial supervisor account says the warning sign was already placed. A later witness note says it was brought to the aisle after staff attended. The file does not resolve that conflict.