Inspection report

AV-26-004459 | Site visit 2026-10-10 | Report revision 1

INSURED	Bluegate Storage Operations LLC
SITE	Unit B-14, Bluegate Storage Court, Southhaven
REPORTED EVENT	Damaged storage-unit latch and reported missing property
INSPECTING ADJUSTER	Priya Lane

1. Reported circumstances

The site contact discovered a damaged latch at unit B-14 during the morning check. A cut padlock was retained. The tenant subsequently reported missing boxed equipment, but the file contains neither purchase invoices nor a reconciled item inventory. The notification is not proof of the alleged contents loss.

2. Observations and limitations

The blue roll-up door has a deformed steel latch assembly and a detached padlock is visible near the threshold. Neither photograph identifies who caused the damage or establishes which items were inside. Keep access damage and reported missing property as separate facts.

See the embedded annotated photo exhibit and case-specific location sketch. Both are original synthetic scenario exhibits; they do not establish cause, timing, liability or coverage.

Preliminary repair scope

AV-26-004459 | Revision 1 | 2026-10-10 | USD; tax excluded

Item / description	Qty	Unit	Rate	Amount
Make-safe attendance	1	LS	450.00	450.00
Replace steel hasp and latch	1	each	650.00	650.00
Door guide and panel alignment	1	LS	950.00	950.00
Reported contents allowance - unverified	1	LS	6,700.00	6,700.00
PRELIMINARY TOTAL				**8,750.00**

Scope qualifications


Quantities are provisional. Reserves, preliminary repair estimates, later proposals and any eventual payment are different measures. No completed work, cause or insurer approval is certified.

Obtain the unit access log, tenant inventory and proof of ownership. The site contact did not witness entry. The photographs do not establish which items were inside or reconcile the reported contents count.

Annotated photo exhibit

AV-26-004459 | Synthetic scenario photos; original JPGs retained separately

PHOTO EXHIBIT | AV-26-004459



A - Deformed latch appearance

B - Detached padlock; contents not visible

Synthetic photos. Annotations describe appearances, not cause, timing, liability or coverage.


How to read this exhibit

Marks A and B refer to visible appearances only. Compare the embedded images with the inspection narrative and the separate original JPGs. Not every visually useful detail is transcribed into the report text.

These are generated scenario images, not independently dated field photographs. A later image cannot prove an earlier event sequence or reveal concealed conditions.

Location and evidence sketch

AV-26-004459 | Embedded case-specific diagram - not to scale



Interpretation and unresolved evidence

The entrance sketch identifies the latch and detached padlock. The interior and contents are not shown; the diagram cannot establish who entered or reconcile the reported missing-property count.

The early intake says three equipment cases may be missing; a later tenant note lists four. No reconciled schedule or invoices resolve the difference.