

Incident and Injury Investigation Report



											· · · · · · · · · · · · · · · · · · ·	and the state of the state of the state of	
Name of Employee	Mahfizur Rahman				Bad	ge No.	2428770172 Profes Design					_	
Safety Awareness Training Date	06 th July, 2022				1 '	of of ining	Site Safety Induction						
Name of Line Manager	Mr. Joey C. Taguba				Bad	ge No.	30040066						
Name of Supervisor	Mr. Muhammad Khan / Muhammad Zubair				Bad	ge No.	30037034/ 2447938164			44			
Division / Department	Maintenance / Construction (Civil)				n Proj Nan		Façade Repairing Building #61			Project Location		JHAH Dhahran	
Place of the Incident/Injury	Building # 61 , Smoking area				Date		28.07.2022		Time of Incident		05:15 PM		
Nature of the	Occupational Incident/Injury				No		Near	Other,	ther, Please specify :				
Incident/Injury	Road T Incide	raffic nt/Injury		Yes	No		Yes	No					
Brief Description of the Incident/ Injury	At about 1715 hours, A Scaffolding ledger (1.2 meter) fell down from the top (23 meter height) of the scaffolding edge towards the JHAH main visitors / Vehicles road side when Mr. Mahfizur Rahman, Scaffolding erector (rental), was erecting the railing there during erection. Luckily, Road was clear from any vehicle / visitors and there is no any harm or property damage occurred. Downside area was properly barricaded by site supervisor and the ledger fall inside the barricades.												
Details of the Injury (Specify affected body parts)	N/A												
First Aid Given?	Yes	No		1	Name of First Aider N/A								
Name of Hospital where patient was treated/ transferred	N/A						Address/Location N/A of the hospital						
Medical leave given by administering Hospital/Clinic or Doctor	Yes	No		. 1	imber of iys	N/A	Hospita	lization		Yes		No	
Property damage	Yes	No		pe	timated rcentage damage	N/A	Estimate damage	ed Cost o d (SAR)	f	N/A	.		
Property Details	Type / Function of the property N				/A		Location of affected property			N/A			
	Name of Manufacturer				N/A								
	Model of the Property				/A		Plate Number			N/A			
	Vehicle Registration Number				/A		Company Fleet Number			N/A			



Was Pre- Task / Toolbox meeting conducted

Specify the Personal Protective Equipment (PPE)

What was the injured person/employee doing at the time of the

Incident and Injury Investigation Report

No

N/A

Safety Harness.

Yes



No

Yes

Was the person using

required Personal

Protective Equipment (PPE) Safety glasses, helmet, glove, cover all, safety shoes, face mask,


incident?		N/A								
What was the machine/equi incident?	pment	doing at th	e of the	N/A	N/A					
What was the material/s / si incident	ubstand	ce/s doing		Scaffolding Ledger (Tube) was placed on bottom cup of cup lock						
Immediate Cause/s of the In	cident/	/injury:								
		Neglige	nce	of the Wor	ker (Erec	tor)				
Root Cause/s of the Incident	/injury	<i>7</i> :								
People: Poor Team W	ork by t	the worker	s, Wo	orker did not	get assista	nce				
Process / Ledger was le Procedure: erecting anoth				ock node (To	op Cup was	not locked o	on both end	ls of ledge	r) and	
Equipment:										
Workplace: Working on a	very hi	gh scaffold	ing p	latform in a	hot weathe	r conditions				
Corrective Action to prevent	reoccu	ırrence:								
Elimination:										
Substitution:										
Engineering Control: Safety	net to b	e installed	at an	appropriate	height to p	orevent falli	ng of object	:		
Administrative Control: Ref and erection of scaffolding, that workers are following a conditions during the hot w with the time interval, and	Adequathe erection to the erec	ate superv ction & dis conditions	ision mant s whe	have to be a tling procedu en assigning	vailable to ire. Also en for the job,	monitored to sure the wordstate the wordstat	he activity rker's phy	and to en sically & n	sure nental	
PPE:										
Were there any witnesses?	Yes	None	~	Type of witness/s	Employee	NA		Public		
Witness Details		N	/A		Badge Number	7.77	Mobile Number	N/A		
Witness Statement:										
					N	A				
Initial Investigation Conduc	ted by:	N 1		N	oted by:		Date	(52-52) 1,275/40.0-1		
Adeel Khan (Safety Officer 30040391) Noted by: JOAY TAGUBA JOAY TAGUBA							30.07.2022			
			0							
								P	age 2 of 3	




Incident and Injury Investigation Report



Additional Details:



Incident Picture



Safety Training Attendance







Spot Training Session conducted on site

Investigation Report Verified by:

MUHAMMAD AMJAD 30040896

Noted by:

JOAY TAGUBA

Date

30.07.2022