

Incident and Injury Investigation Report



Name of Employee	Surya Bahadur Thapa		Badge No.	30039751	0039751		1
Safety Awareness Training Date	5/21/2020		Proof of Training	Induction	nduction		3
Name of Line Manager	Engineer Amr		Badge No.	30104091	Profession/ Sr. Engineer Designation		- Civil
Name of Supervisor	Ragab Abdalla El Sayed Elktry		Badge No.	30036075			
Division / Department	Civil Department		Project Name	Catering Auditorium & Recreation Facilities	Project Location	JUC	
Place of the Incident/Injury	Auditorium		Date of Incident	2/15/2021	Time of Incident	2.30 PM	
Nature of the Incident/Injury	Occupational Incident/Injury N		ЙO	Near Miss	Other, Please specify :		
	Road Traffic Incident/Injury	No		Yes			
Brief Description of the Incident/Injury Property damage	While performing down from platform no injury or proper	n to bott	om. Lucki	ly area was b	g platform, tie arricaded and	rod plate for	elt as there
First Aid Given?	N/A	Name	f First Aide	pq			
Name of Hospital where patient was treated/transferred	No	Nume	I I I St Auc	Address/L of the hosp			
Medical leave given by administering Hospital/Clinic or Doctor	No	Numbe Days	r of	Hospitalization		No	
Property damage	No	Estimated percentage of damage		Estimated Cost of damaged (SAR)			
Property Details	Type / Function of the property			Location of affected property		•	
	Name of Manufacturer			•			
	Model of the Property		·	Plate Numb	per		
	Vehicle Registration Number			Company Fleet Number			



Incident and Injury Investigation Report



Was Pre- Task / Toolbox meeting conducted		Yes		Was the person using required Personal Protective Equipment (PPE)	ent	Ye	es
Specify the Personal Protective Equipment (PPE) Safety Sh			oes, Safety Goggles, Helmet, Vest, Gloves				
What was the injured person/employee doing at the time of the incident?			Worker was doing Housekeeping on the scaffolding platform				
What was the machine/incident?	equipment doing at	t the time of the	N/A				
What was the material/ the incident		ng at the time of	Loose	material lying on the	scaffoldi	ng platform	
Immediate Cause/s of the	ne Incident/injury:						
Loose materials and open	ı gaps in the platform	ŧ					
	Daonle: No proper	curowisian fra	Al-				
	People: No proper supervision from the supervisor and foreman.						
Root Cause/s of the	Process / Procedure- Procedure was not followed for the housekeeping after finishing the work.						
Incident/injury:	Equipment: N/A						
	Workplace: Loose material kept on platform by worker. Open gaps on the platform.						
	Elimination: N/A						
	Substitution: N/A						
Corrective Action to prevent reoccurrence:	Engineering Control: All gaps on the platforms must be closed						
	Administrative Control: Proper housekeeping after finishing the work. Area from downside must be barricaded with proper signage. While work at height, Depute one person downside to monitor the access.						
	PPE: Necessary PPEs at site must be worn.						
Were there any	NY.	Type of					<u> </u>
witnesses?	None	witness/s				Public	
Witness Details			Badg Num		lobile umber		
Witness Statement:							




Incident and Injury Investigation Report



Initial Investigation Conducted by: Krishna Pillai	Noted by: Mustafa Ali	Date	15-2-2021	
1. Ages				

Additional Details:



Investigation Report Verified by:	Noted by:		
		Date	