
## **Crackterized Result**





The image characterized as: Contains Crack

Length: 120.09 cm

Width: **114.35 mm** 

Positive Crack Probability: 73.11%

Negative Crack Probability: 26.89%

Location of Crack: Beam

Date Added: 2023-05-10 22:48:33

Remarks: