

# Algodon N Colors

**Encuentro**

**Style No:** 172706520

**Order No:** 17038

**Inspection  
Report**

# Algodon N Colors

## ORDER INFORMATION

### Order Information



Report No	A N C 01 / 017 / 00395	
Buyer	Encuentro	
Product Labeling		
Supplier	Delta Garments	
Location	Lahore – Pakistan	
Style No	172706520	
PO No	17038	
Color	Azul Claro and Azul Medio	
Fabric Description	80% Cotton 18% Poly 2% Elastan	
Item Description	Slim Denim 5 Pockets Pushup Pant	
Order Quantity	Azul Claro - 1000pcs Azul Medio -1000pcs	Total Qty 2000pcs
Shipment Date	30 <sup>th</sup> June, 017	



Inspection Information		
Auditor	Mr. Usman	
Type Of Inspection	Final Inspection	
Inspection Date	25 <sup>th</sup> June, 017	
Inspection offer Qty	Azul Claro - 1000pcs Azul Medio -1000pcs	Total Qty 2000pcs
Total Numbers of Cartons Packed	Assorted 26cartons Solid Claro 23cartons Solid Medio 23cartons	Ttl ctns 72ctns
A Q L and Sample size	2.5 A Q L Sample size 125pcs	
Major Defects accept	Major 07 / Miner 010	
Numbers of inspection cartons	Assorted 05cartons Solid Claro 07cartons Solid Medio 07cartons	Ttl ctns 19ctns

Overall Inspection Result

Pass ( As per AQL 2.5 )

# Algodon N Colors

## INSPECTION RESULT SUMMARY

S.No	Description	Result	Remarks									
01	Quantity	OK	Color	Order Quantity	Offer Quantity	Diff Quantity	Packed Percentage (%)					
			Azul Claro	1000	1000	0	100.00%					
			Azul Medio	1000	1000	0	100.00%					
			<b>Total</b>	<b>2000</b>	<b>2000</b>	<b>0</b>	<b>100.00%</b>					
Supplier offered full & final quantity and above mentioned details Solid color Assorted size and Solid color solid size packed Single piece polybag with silica jell One carton two white stickers pasted												
02	Fabric	OK	As per sample									
03	Trims	OK	As per sample									
	Labeling Barcode	OK	As per sample									
04	Wash / Color	OK	As per sample									
05	Product Measurements	within tolerance	<b>Measurement within tolerance</b>									
06	Packing and Packaging	OK	As per buyer requirement									
07	Shipping Mark	OK	As per buyer requirement									
08	Workmanship Defectives list	Quality OK as per AQL 2.5	Finding Quality									
			Description		Checked	Critical	Major	Minor				
			Defected Finding		125	000	007	007				
			Maximum Defects Allowed		125	000	007	010				
Broken stitch 03 / 0 Broken eyelet kaj 01 / 0 Open seam 01 / 0 Missing rivets 01 / 0 Damage grinding 01 / 0 Uncut thread 0 / 04 Not proper clean grinding 0 / 03												
09	Styling / Construction	OK	As per shipment sample									
<b>During Inspection Founding Remarks</b>												
During inspection selected cartons number are below mentioned												
Azul Claro with Azul Medio		03	11	15	18	24	-					
Azul Claro		28	32	35	40	43	45					
Azul Medio		51	55	59	63	66	68					
70												

# Algodon N Colors

## QUANTITY DETAILS:

Packing List Summary								
Color	Order Quantity	Offer Quantity	Diff Quantity	Packed Percentage	Remarks / Comments			
Azul Claro	1000	1000	0	100.00%	Full and final packed			
Azul Medio	1000	1000	0	100.00%	Full and final packed			
<b>Total</b>	<b>2000</b>	<b>2000</b>	<b>0</b>	<b>100.00%</b>	<b>Full and final packed</b>			

## PACKING LIST

<b>TO:</b> ENCUENTRO MODAS S.L.U. PLGN INDUSTRIAL DE GUIMAR MANZANA E, PARCELA-2, 38509, ARAFO, TENERIFE SPAIN	Total Quanty: 2000 PCS Total Cartons: 72 CTNS Total Gross Weight: 917 KGS Total Net Weight: 845 KGS Total Volume (CBM): 4.58 CBM Letter of Credit No. CI86023100168306
---	---

Destination:Tenerife, Spain (By Sea)

Style	172706520 (O/N 17038)	RT NO. RT162063-01	Composition of goods: 80% ALGODON 18% POLIESTER 2% ELASTANO
Description: SLIM DENIM 5 POCKETS PUSH UP ROTOS 80PCT COTTON 18 PCT POLYESTER 2PCT ELASTAN (LADIES SLIM 5 POCKET PUSH UP ROTOS)			
Carton start number	Carton end number	Total number of cartons	Colour
1	26	26	AZUL CLARO
			2 2 3 3 2 2
			14 364
			AZUL MEDIO
			2 2 3 3 2 2
			14 364
			Total 28 728
		Total Ctns 26	1.65 305.76 331.76

### SUMMARY

COLOUR	38	40	42	44	46	48			TOTAL
AZUL CLARO	52	52	78	78	52	52			364
AZUL MEDIO	52	52	78	78	52	52			364
Total	104	104	156	156	104	104			728

Style	172706520 (O/N 17038)	RT NO. RT162063-01	Composition of goods: 80% ALGODON 18% POLIESTER 2% ELASTANO
Description: SLIM DENIM 5 POCKETS PUSH UP ROTOS 80PCT COTTON 18 PCT POLYESTER 2PCT ELASTAN (LADIES SLIM 5 POCKET PUSH UP ROTOS)			
Carton start number	Carton end number	Total number of cartons	Colour
27	29	3	AZUL CLARO
			28
			28
			28
			28
			28
			28
			28
		Total Ctns 23	Total 636

### SUMMARY

COLOUR	38	40	42	44	46	48			TOTAL
AZUL CLARO	106	126	120	113	93	78			636
Total	106	126	120	113	93	78			636

Style	172706520 (O/N 17038)	RT NO. RT162063-01	Composition of goods: 80% ALGODON 18% POLIESTER 2% ELASTANO
Description: SLIM DENIM 5 POCKETS PUSH UP ROTOS 80PCT COTTON 18 PCT POLYESTER 2PCT ELASTAN (LADIES SLIM 5 POCKET PUSH UP ROTOS)			
Carton start number	Carton end number	Total number of cartons	Colour
50	52	3	AZUL MEDIO
			28
			28
			28
			28
			28
			28
		Total Ctns 23	Total 636

### SUMMARY

COLOUR	38	40	42	44	46	48			TOTAL
AZUL MEDIO	106	126	120	113	93	78			636
Total	106	126	120	113	93	78			636

# Algodon N Colors

## Color Wise Summary

### Azul Claro

Summary							
Sizes	38	40	42	44	46	48	Total
Order Quantity	158	178	198	191	145	130	1,000
Offer Quantity	158	178	198	191	145	130	1,000
Balance	0	0	0	0	0	0	0
Percentage	100.00	100.00	100.00	100.00	100.00	100.00	100.00

### Azul Medio

Summary							
Sizes	38	40	42	44	46	48	Total
Order Quantity	158	178	198	191	145	130	1,000
Offer Quantity	158	178	198	191	145	130	1,000
Balance	0	0	0	0	0	0	0
Percentage	100.00	100.00	100.00	100.00	100.00	100.00	100.00

### During inspection carton checking Pictures



## Algodon N Colors



# Algodon N Colors




## Algodon N Colors



### STYLING / CONSTRUCTION:

Azul Claro

#### Production With Sample Pictures



**Zipper**



**Waistband Button**

## Algodon N Colors




Rivets

Main Label



Care Label Upper

Care Label Inside



Care Label Barcode


PU Patch

## Algodon N Colors



**Hangtag**

**Hangtag with price**



**Hangtag with barcode**




**Waist tag**

### TESTS AND SPECIAL REQUIREMENTS:

During Inspection		
Test Description	Comment for Inspector	Result
Fatigue test for all adjustable parts found on each sample, cannot skip (i.e., all zippers, velcro and snaps, and normal force to pull all the buttons).  Do  this 20 times for each sample.--20 pieces (      Pieces)	Did not found unsecured button, rivet and zipper	<b>Pass</b>



## Algodon N Colors




Seaming strength test-Test the strength along & cross the seams by hand. Especially on side seams and pockets

Seams were perfect

Pass



## Algodon N Colors

<p>Rub test to check the color fastness of the fabric (including the lining) and all the accessories (Labels must be rubbed for this test). Use a white cotton cloth to rub the material. Rub the item 10 times over a 10 cm distance with a force of 9N (1kg). Test 1 piece per color with both a dry and a wet cloth. Expected result: There should be no color transfer greater than 4 on a grey scale (between the original white cloth and the colored one) after the dry test. There should be no color transfer greater than 3-4 on a grey scale (between the original white cloth and the colored one) after the wet test</p> <p>Enc</p>	<p>As per sample</p> 	<p>Pass</p>
--	--	-------------

# Algodon N Colors

## PRODUCT MEASUREMENTS:

### Measurement Information

<b>Product Size Range</b>	38, 40, 42, 44, 46, 48	<b>Provided Specs</b>	Buyer
<b>Type Of Sample</b>	PP sample	<b>Provided Sample</b>	Supplier

### Measurements Table

Point of Measurement	Style No: 172706520																colour Azul medio								
	38				40				42				44				46				48				
	Req	1	2	3	4	Req	1	2	3	4	Req	1	2	3	4	Req	1	2	3	4	Req	1	2	3	4
TOTAL LENGTH WITH WAIST BAND	90	-0.5	1.5	1	0.5	90.7	1	1	-0.5	1	91.4	-0.5	0	0.5	0.5	92.1	1	1	-0.5	1	92.8	-0.5	1	0.5	-0.5
WAIST	36.5	-0.5	-0.5	0.5	-1	38.5	-0.5	-1	0.5	1	40.5	-0.5	-0.5	1	0.5	42.5	-0.5	-1	0.5	0.5	44.5	-0.5	-0.5	1	0.5
HIPS (18 cm from waist)	42	-0.5	1	0.5	1	44	0	-1	-1	0.5	46	-1	1	1	0.5	48	1	-1	1	1.5	50	0.5	-1	1	0.5
Front rise (With waistband)	23	-0.5	0.5	0	1	23.8	-0.5	0.5	-0.5	0.7	24.6	0.5	0.5	0.5	0.5	25.4	-0.5	1	-0.5	0	26.2	0.5	0	0.5	-0.5
Back Rise with waist band	34.5	0.5	1	1	1	35.5	0.5	1	1	-0.5	36.5	1	1.5	1	1	37.5	1	0.5	1	0.5	38.5	0.5	1	0.5	1
Thigh 13cm from crotch	20.5	0.5	-0.5	0.5	0.5	21.5	-0.5	0.5	-0.5	-0.5	22.5	0.5	0.5	0.5	0.5	23.5	-0.5	0.5	-0.5	0	24.5	0.5	0.5	1	-0.5
Keen 32 cm from crotch	16.5	-0.5	0.5	1	-0.5	17.3	0.5	0.5	0.5	0.5	18.1	0.5	0.5	0	1	18.9	0.5	0.5	0.5	0.5	19.7	0.5	0.5	0	0.5
Hem	14	-0.5	0	0.5	0	14.6	0	-0.5	0	0	15.2	0.5	0	0.5	-0.5	15.8	0	0.5	0.5	0.5	16.4	-0.5	0.5	-0.5	0
Thigh 2.5 cm from crotch	23.3	0.5	0.5	1	1	24.4	0.5	0.5	0	0.5	25.5	1	0.5	1	0.5	26.6	0.5	0.5	1	1	27.7	-1	1	0.5	1

Point of Measurement	Style No: 172706520																colour Azul Claro								
	38				40				42				44				46				48				
	Req	1	2	3	4	Req	1	2	3	4	Req	1	2	3	4	Req	1	2	3	4	Req	1	2	3	4
TOTAL LENGTH WITH WAIST BAND	90	1	0	1.5	1	90.7	1	1.5	1	1	91.4	1	1	-0.5	-1	92.1	1.5	1	-1	0.5	92.8	0	-1	-0.5	-0.5
WAIST	36.5	-0.5	-1	0.5	1	38.5	-0.5	-1	0.5	1	40.5	-0.5	-1	0.5	0.5	42.5	1	-0.5	-1	0.5	44.5	-0.5	0.1	0.5	0.5
HIPS (18 cm from waist)	42	0	-1	-0.5	0.5	44	-0.5	1	-1	1	46	1	0	1	0.5	48	1	0.5	1	0.5	50	1.5	0.5	0.5	1
Front rise (With waistband)	23	-0.5	0	-0.5	0	23.8	-0.5	0	-0.5	0	24.6	-0.5	0	-0.5	0	25.4	0.5	1	0.5	0	26.2	-0.5	-0.5	1	-0.5
Back Rise with waist band	34.5	0.5	0.5	1	-0.5	35.5	0.5	0.5	1	0.5	36.5	0.5	0.5	0	-0.5	37.5	1	-0.5	1	-0.5	38.5	-0.5	0.5	-0.5	1
Thigh 13cm from crotch	20.5	-0.5	0	-0.5	-0.5	21.5	-0.5	0	-0.5	-0.5	22.5	-0.5	1	1.5	-0.5	23.5	0.5	0.5	0.5	0.5	24.5	-0.5	-0.5	0.5	1
Keen 32 cm from crotch	16.5	0	0.5	0.5	0.5	17.3	0	0.5	0.5	0.5	18.1	0	0.5	0.5	0.5	18.9	0.5	0.5	0.5	0.5	19.7	0.5	0.5	0.5	0.5
Hem	14	0.5	-0.5	0	0.5	14.6	0.5	-0.5	0.5	0.5	15.2	0	-0.5	0	-0.5	15.8	-0.5	0	-0.5	-0.5	16.4	-0.5	-0.5	0.5	-0.5
Thigh 2.5 cm from crotch	23.3	1	0.5	1	0.5	24.4	0.5	0.5	1	1	25.5	1	0.5	1	0.5	26.6	1	1	0.5	0.5	27.7	1	0.5	1	0.5

## Algodon N Colors

### How To Measure Pictures



## Algodon N Colors



## Algodon N Colors

### QUALITY DEFECTIVES LIST:

DEFECTIVES LIST					Picture
	Description	CRI	MAJ	MIN	
01	Broken stitch		01		
02	Missing rivets		01		
03	Open seam		01		

### Algodon N Colors

04	Broken eyelet kaj	01		
05	Broken stitch	01		
06	Broken stitch	01		
07	Damage grinding	01		

### Algodon N Colors

08 Uncut thread

04



Encuestas

## Algodon N Colors

09	Not proper clean grinding			03	
					
					

### DEFECTIVES LIST SUMMARY

Description	Cri	Maj	Min	AQL result
Number of Detectives found	000	007	007	
Maximum Allowed	000	007	010	<b>AQL 2.5 Pass</b>
No. of Inspected Samples	125	125	125	