Harbour Air & Electrical

14 Harbour St, Balmain NSW 2041

(512) 555-0125

EIN: 51 824 753 556

Insurance: Synthetic Insurer · synthetic-glove-190 · expires Dec 31, 2031

Service report

J-1001 · Completed heating inspection

Harbourview Dental
14 Harbour St, Balmain NSW 2041

Feb 28, 2030 · Technician: Priya

Completed Feb 28, 2030, 10:00 AM (America/Chicago)

Work summary

Completed inspection with airflow test.

Findings


Pressure above the recorded range.

Inspection results


Heating readings

Supply pressure
95 psi
Out of range · expected 40–80 psi

Reading original



Photos



Heat exchanger original

Materials used

- Copper fitting × 2 each

Customer sign-off

Signed by Synthetic Customer



Recommendations

Pressure regulator

Discuss regulator work with the office.

Document terms

report document terms retained.

report final customer footer.

Contact Harbour Air & Electrical: (512) 555-0125