Synthetic Glove LLC

DBA Synthetic Trade

125 Test Street, Austin TX 78701

(512) 555-0125 office@harbourair.example

EIN: 12-3456789

Plumbing · TX license synthetic-glove-12

HVAC · TX license synthetic-glove-13

Insurance: Synthetic Insurer · synthetic-glove-14 · expires Dec 31, 2028

Service report

J-1001 · Water heater service

Harbourview Dental
14 Harbour St, Balmain NSW 2041

Nov 3, 2026 · Technician: Priya

Completed Nov 3, 2026, 10:00 AM (Australia/Sydney)

Work summary

Completed the heater inspection

Findings

High water pressure

Inspection results


Water heater inspection

Unit running?
Yes

Water pressure
95 psi
Out of range · expected 40–80 psi

Inspection notes
Expansion tank needs attention

Photos



Water heater installation

Materials used

- Copper fitting × 2 each

Customer sign-off

Signed by Dr Mei Lin



Recommendations

Pressure regulator

Fit a regulator before the next service

Contact Harbour Air & Electrical: (512) 555-0125 · office@harbourair.example